

Name of Driver

NRIC/Passport Number

Contact Number

97910528

Address

Postcode

Insurance Company Name


Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan




Driver's Nric (Front)



Driver's Nric (Back)



Driver's Driving License (Front)



Driver's Driving License (Back)

**CLASSIFIED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)**

**1 → 4 F → EFFECTIVE DATE**

**Class 3A** Motor cars without clutch pedals (Auto) =< 3000kg  
< 7 passengers, exclusive of the driver; and  
other motor vehicles without clutch pedals =< 2500kg

**27 Aug 2015**




License No SS9635850Z

Accident Photo



Accident Photo



# Revol Carz Garage Pte Ltd

PHOTOCOPIED

Blk 10 Ang Mo Kio Industrial Park 2a, Ang Mo Kio Autopoint #02-18

Singapore 568047

Tel: 65551171 Fax: 62679317

## Part By Part repair of SMA 8993 Y

Name : Lim Beng Kwee  
Address : c/o Blk 10 Ang Mo Kio Industrial Park 2A  
#02-18 Ang Mo Kio Autopoint  
Singapore 568047  
Model : Mercedes Benz GLA180

Date : 6-May-19

QTY	ITEM	AMT (\$)
	<b>List Items</b>	
1 pc	Rear bumper top	\$ 1,170.00
1 pc	Rear bumper centre	\$ 560.00
1 pc	Rear bumper lower	\$ 390.00
1 pc	Rear bumper top chrome	\$ 195.00
1 pc	Rear bumper sensor	\$ 180.00
		<u>\$ 2,495.00</u>
	<b>Special Nett Items</b>	
1 pc	Paint protection (Ze Tough Foundation)	\$ 1,438.00
		<u>\$ 1,438.00</u>
<b>S/N</b>	<b>Labour Charge</b>	
1	To remove and refit reverse sensor.	\$ 80.00
2	Panel beating	\$ 500.00
3	Spray painting	\$ 500.00
		<u>\$ 1,080.00</u>
	<b>Total</b>	<u>\$ 5,013.00</u>

Dollars : Five Thousand And Thirteen Only

PHOTOCOPY

# PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Billing Name & Address

Lim Beng Kwee  
c/o Blk 10 Ang Mo Kio Industrial Park 2A  
#02-18 Ang Mo Kio Autopoint  
Singapore 568047

Invoice No 04-19004/AY

Date 6 May 2019

Vehicle No : SMA 8993 Y

Model : Mercedes Benz GLA180

Item	Descriptions	Amount S\$
1	Date of inspection : <u>2 Apr 2019</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>65</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 605.00</u>
	SDLS : SIX HUNDRED AND FIVE ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

# PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 04-19004/AY / 2019

Date of Report : 6 May 2019

Lim Beng Kwee  
c/o Blk 10 Ang Mo Kio Industrial Park 2A  
#02-18 Ang Mo Kio Autopoint  
Singapore 568047

## THIRD PARTY SURVEY

ACCIDENT HAPPENED ON 19 Jan 2019

As per your instruction dated 2 Apr 2019 with regard to the above matter. We have carried out a physical inspection on the said vehicle SMA 8993 Y. We enclosed herewith our report and findings as follows:

### 1. VEHICLE PARTICULARS

Registration No : SMA 8993 Y  
Model : Mercedes Benz GLA180  
Year / Capacity : 2018/1595  
Chassis No : WDC1569422J418415  
Engine No : 27091031403874  
Mileage : 13215  
Colour : White

### 2. TYRES CONDITION

		<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	215/60 R17	Continental	6.00	mm	Sport
REAR	O/S	215/60 R17	Continental	6.00	mm	Sport
FRONT	N/S	215/60 R17	Continental	6.00	mm	Sport
REAR	N/S	215/60 R17	Continental	6.00	mm	Sport

# PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883  
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Revol Carz Garage Pte Ltd  
Blk 10 Ang Mo Kio Industrial Park 2A  
#02-18 Ang Mo Kio Autopoint  
Singapore 568047

5. Estimated normal period of repair : 4 working days to complete.

6. Enclosed number of photograph : 65 copies.

7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

#### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SMA 8993 Y  
 Report No: TP/ 04-19004/AY / 2019

**SPARE PARTS**

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>Nett Items</u>				
1	Rear bumper top	Damage	\$ 1170.00	\$ 1170.00
1	Rear bumper centre	Damage	\$ 560.00	\$ 560.00
1	Rear bumper lower	Damage	\$ 390.00	\$ 390.00
1	Rear bumper reinforcement	Repair	\$ 797.00	\$
1	Rear bumper top chrome	Damage	\$ 195.00	\$ 195.00
1	Rear bumper sensor	Damage	\$ 180.00	\$ <del>X 180.00</del>
			\$ 3292.00	\$ 2495.00
<u>Special Nett Items</u>				
1	Paint protection (Ze Tough Foundation)	Necessary	\$ 1438.00	\$ <del>1438.00</del>
			\$ 1438.00	\$ 1438.00

2315  
 (10/01/2018) 2083.5

**Spare Parts Total**    \$ 4730.00    \$ 3933.00

Vehicle No: SMA 8993 Y  
 Report No: TP/ 04-19004/AY / 2019

**LABOUR COST**

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 4730.00	\$ 3933.00
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	Not Required
2	To remove and refit rear bumper sensor.	\$ 100.00	<del>80.00</del> 40
3	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 700.00	<del>500.00</del> 200
4	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 700.00	<del>500.00</del> 400
			640
	<b>Total</b>	<u>\$ 6280.00</u>	<u>\$ 5013.00</u>

Recommended PART BY PART Repair Amount of: \$ 5013.00

SDLS: FIVE THOUSAND THIRTEEN ONLY

2923.5

  
 Qualified Appraiser



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG19014812/Gsd3s2

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120  
ATTN: MING YAO LEE

Date : 28-08-2019



Code : AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SDJ 81R	Veh. Inspected	SMA 8993Y
Policy No.	2100256400-07	Coverage (\$)	0.00
Claim No.	4932921674SG-003	Excess (\$)	0.00
Assign From	MING YAO LEE	Assign Date	21/08/2019

### 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ GLA180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WDC1569422J418415	Colour	WHITE
Odometer	19914	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	CONTINENTAL	6 mm
L/H Front Tyre	215/60 R17	CONTINENTAL	6 mm
R/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm
L/H Rear Tyre	215/60 R17	CONTINENTAL	6 mm

### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.  
REPAIR CONDITION SEE DETAILS.

### 5. General Information

Accident Date	19/01/2019	Inspection Date	23/08/2019
Survey held at	CARPARK OF BLOCK 14 TOH YI DRIVE		
Repairer	REVOL CARZ GARAGE PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 8993Y

Page No.: 1 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER TOP (N)	REPLACED	1,170.00	1,170.00
1	REAR BUMPER CENTRE (N)	REPLACED	560.00	560.00
1	REAR BUMPER LOWER (N)	REPLACED	390.00	390.00
1	REAR BUMPER REINFORCEMENT (N)	REPAIRED SEE LABOUR	797.00	-
1	REAR BUMPER TOP CHROME (N)	REPLACED	195.00	195.00
1	REAR BUMPER SENSOR (N)	NOT NECESSARY	180.00	-
	LESS 10% DISCOUNT		-	-231.50
			3,292.00	2,083.50
<b>SPECIAL NETT ITEMS</b>				
1	PAINT PROTECTION (ZE TOUGH FAUDATION) (SN)	REPLACED	1,438.00	200.00
			1,438.00	200.00
<b>LABOUR</b>				
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.	NOT NECESSARY	50.00	-
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		100.00	40.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		700.00	200.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		700.00	400.00
			-	-
			-	-
			-	-
			1,550.00	640.00
<b>GRAND TOTAL</b>			<b>6,280.00</b>	<b>2,923.50</b>

Report Ref No. CS/AIG19014812/Gsd3s2



RECOMMENDED COST OF REPAIRS

2,923.50

Report Ref No. CS/AIG19014812/Gsd3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.