

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

15/05/2018  
17:15:11

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:


Wong Fung  
67200147X



### SKETCH PLAN

A-5KG7173X

R = 56088990



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- The above accident happened at the corner of Bitten Street 13 while I was trying to exit from my carpark lot.
- While exiting from the carpark lot, I did not realize that my car hit onto the vehicle in front of me.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_

Date &amp; Time:

15/05/2016  
17 15 hrs

Driver's Signature \_\_\_\_\_

(If driver is not the policyholder)

**Date & Time:**

Reporting Centre Personnel's Signature

Name: Tom Ford

NRIC/FIN No.: 62040617x



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



# PAR Automotive Consultancy

Regn. No: S2986974L

Thomson Rd Post Office PO Box 029 Singapore 915701 Tel : 645 31173, Fax : 645 36131

PHOTO COPY

Report No: 0310-19-TCA

24 June 2019

Ng Kwang Seng  
Blk 166 Bishan St 13 #07-248  
Singapore 570166

**INVOICE No. 0310-19-TCA**

Vehicle No. SKD8899U

<u>S/NO</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$685.00
<b>Total amount payable</b>		<b><u>\$685.00</u></b>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

**PAR Automotive Consultancy**



# PAR Automotive Consultancy

Regn. No: 12086974E

Thomson Rd Post Office PO Box 029 Singapore 915701 Tel: 645 31173, Fax: 645 36131

Report No: 0310-19-TCA

24 June 2019

## ACCIDENT VEHICLE SURVEY REPORT

Ng Kwang Seng  
Blk 166 Bishan St 13 #07-248  
Singapore 570166

### VEHICLE INFORMATION:

Vehicle Reg No.:	SKD8899U	Odometer:	93329km
Make & Model:	Mercedes Benz SLK250 A	Colour:	Silver
Chassis number:	WDD1724472F016271	Date of accident:	14/05/2018
Year of Regn.:	18/10/2011	Date inspected:	04/06/2018
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921		

### RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

### REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

# PAR Automotive Consultancy

Regn. No. 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

---

Report No: 0310-19-TCA

24 June 2019

## ACCIDENT VEHICLE SURVEY REPORT

Ng Kwang Seng  
Blk 166 Bishan St 13 #07-248  
Singapore 570166

### VEHICLE INFORMATION:

Vehicle Reg No.:	SKD8899U	Odometer:	93329km
Make & Model:	Mercedes Benz SLK250 A	Colour:	Silver
Chassis number:	WDD1724472F016271	Date of accident:	14/05/2018
Year of Regn.:	18/10/2011	Date inspected:	04/06/2018
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921		

### STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

### TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Dunlop	6mm/Dunlop	245/35ZR19
Rear:	6mm/Dunlop	6mm/Dunlop	275/30ZR19

### POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear LH portion.  
Please see details as described in the Annex for parts and labour.

### REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

## Parts and Labour Assessment

### PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment	
REAR BUMPER	1	squashed	1,688.00	✓ 1,688.00	1519.2
REAR BUMPER BRACKET L/R	2	repair	148.00	✗ 0.00	
REAR BUMPER INNER SPONGE	1	deformed	165.00	✗ 165.00	
REAR BUMPER SIDE ARCH MOULDING L/R	2	L-deformed	336.00	✗ 168.00	SVC
REAR BUMPER SIDE RETAINER L/R	2	necessary	76.00	✗ 76.00	
REAR LH DRIVE SHAFT	1	bent	2,250.00	✗ 2,250.00	
REAR LH KNUCKLE ARM	1	distorted	1,410.00	✗ 1,410.00	
REAR LH KNUCKLE ARM BEARING	1	dislodged	362.00	✗ 362.00	
REAR LH LEVELING SENSOR	1	shorted	389.00	✗ 389.00	
REAR LH LINKAGE	1	bent	170.00	✗ 170.00	
REAR LH LOWER ARM	1	bent	448.00	✗ 448.00	
REAR LH SPORT RIM	1	abraded	3,375.00	✓ 3,375.00	1800(SV)
REAR LH STAY ARM	1	bent	280.00	✗ 280.00	
REAR LH STAY ROD	1	bent	260.00	✗ 260.00	
REAR LH TORSION ARM	1	bent	320.00	✗ 320.00	SVC
REAR LH WHEEL HUB	1	dislodged	470.00	✗ 470.00	
Subtotal before discount			S\$ 12,147.00	S\$ 11,831.00	1367.28
Percentage discount 10% and 10%			S\$ 1,214.70	S\$ 1,183.10	
Sub-total 1			S\$ 10,932.30	S\$ 10,647.90	
REAR BUMPER CLIPS - SET	1	necessary	50.00	✓ 50.00	
REAR LH 275/30/19 TYRE	1	abraded	850.00	✗ 850.00	SVC
Subtotal before discount			S\$ 900.00	S\$ 900.00	
Sub-total 2			S\$ 900.00	S\$ 900.00	
Parts-total			S\$ 11,832.30	S\$ 11,547.90	

### LABOUR

To reset system after repair works	500.00	400.00	X
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	100.00	50.00	40
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.	500.00	400.00	X
To road test driving, check and resetting wheel alignments system.	180.00	180.00	60
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	150.00	0.00	
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	700.00	500.00	400
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	600.00	500.00	300
To apply anti-rust chemical on repaired and replaced panel.	80.00	30.00	X
Labour Total	SS 2,810.00	SS 2,060.00	800
Parts & Labour Total	SS 14,642.30	SS 13,607.90	

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

**Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 11,600.00  
and the recommended number of working days for the repairs is within 9 day(s).**



**B J Loi** (I Eng., MIML, AIRTE)  
Automotive Appraiser

4017.28

20% : 3200



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18010044/Gvd3s2-1

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120  
ATTN: SALIHA

Date : 07-10-2019



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKG 7173X	Veh. Inspected	SKD 8899U
Policy No.	2100473514	Coverage (\$)	0.00
Claim No.	6097407800SG	Excess (\$)	0.00
Assign From	SALIHA	Assign Date	20/08/2019

## 2. Vehicle Particulars & Condition

Make & Model	MERCEDES-BENZ SLK250	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDD1724472F016271	Colour	SILVER
Odometer	93329	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/30 ZR19	DUNLOP	6 mm
L/H Front Tyre	225/30 ZR19	DUNLOP	6 mm
R/H Rear Tyre	225/30 ZR19	DUNLOP	6 mm
L/H Rear Tyre	225/30 ZR19	DUNLOP	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	14/05/2018	Inspection Date	04/06/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 8899U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BUMPER	SQUASHED	1,688.00	1,519.20
2	REAR BUMPER BRACKET L/R	SERVICEABLE	148.00	-
1	REAR BUMPER INNER SPONGE	SERVICEABLE	165.00	-
2	REAR BUMPER SIDE ARCH MOULDING L/R	SERVICEABLE	336.00	-
2	REAR BUMPER SIDE RETAINER L/R	SERVICEABLE	76.00	-
1	REAR LH DRIVE SHAFT	SERVICEABLE	2,250.00	-
1	REAR LH KNUCKLE ARM	SERVICEABLE	1,410.00	-
1	REAR LH KNUCKLE ARM BEARING	SERVICEABLE	362.00	-
1	REAR LH LEVELING SENSOR	SERVICEABLE	389.00	-
1	REAR LH LINKAGE	SERVICEABLE	170.00	-
1	REAR LH LOWER ARM	SERVICEABLE	448.00	-
1	REAR LH STAY ARM	SERVICEABLE	280.00	-
1	REAR LH STAY ROD	SERVICEABLE	260.00	-
1	REAR LH TORSION ARM	SERVICEABLE	320.00	-
1	REAR LH WHEEL HUB	SERVICEABLE	470.00	-
	LESS 10% DISCOUNT		-877.20	-151.92
			7,894.80	1,367.28
1	REAR LH SPORT RIM (SN)	ABRADED	3,375.00	1,800.00
	LESS 10% DISCOUNT		-337.50	-
			3,037.50	1,800.00
<b>SPECIAL NETT ITEMS</b>				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR LH 275/30/19 TYRE (SN)	SERVICEABLE	850.00	-
			900.00	50.00
<b>LABOUR</b>				
	TO RESET SYSTEM AFTER REPAIR WORKS.	NOT NECESSARY	500.00	-
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		100.00	40.00

Report Ref No. CS3/AIG18010044/Gvd3s2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, CHANGE REAR SUSPEJNSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC.	NOT NECESSARY	500.00	-
	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENT SYSTEM.		180.00	60.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	NOT NECESSARY	150.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		700.00	400.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		600.00	300.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	80.00	-
			2,810.00	800.00
<b>GRAND TOTAL</b>			<b>14,642.30</b>	<b>4,017.28</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,200.00</b>

Report Ref No. CS3/AIG18010044/Gvd3s2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.