*100m	03/212	1003497/Btd3	-1
unimen	Ng Jeffrey	A1C)	21/08/2019
to began V	3 7 1 3 1 1		Kta Smorth 2.2 SLG 4725
of Toley to Tour beaut	BIK 9002, fempires of 2100 482856	93 # 01-72 16:	7 96333593 7 Junpins Ind. Park 17 0457679986
Edds of Veh O Bent's Donal CA / REV /	INCEL REVEATING CUPS	Ewez	1111/2 21/02/19
Date/True	1.41pmg 28/2/19 Person Continued	Jeruny	Vehicle (Cr.) stri
l une/Lune	Dismonte: 27 2/2019	12/4	
	lump Sum \$ 7150f 3018 File pass to type	cred 3650; st	38°(.) 29/8/2019

Nivitha (LKK Auto)

From: Ng, Jeffreysaykiat <Jeffreysaykiat.Ng@aig.com>

Sent: Wednesday, 21 August 2019 9:52 AM

To: Admin-D (LKKAuto)

Cc: Hsiao Tong (LKKAuto); SUR; assignments

Subject: RE: FW: ***URGENT-RI APPOINTMENT****RE: AIG ref: 7624576799SG003 & 004 //

Vision Law LLC ref: DA1-ylv-Ins-D11-109687-19-er (claimant: UE-TAY SZE YIN)

Attachments: 20190819120225.pdf

Dear G.Nivitha,

Attached documents.

Please proceed to do a paper re-survey of TP vehicle SFV1541L, thank you.

Jeffrey Ng

AIG

Senior Complex Claims Examiner Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1916 | Fax +(65) 6835 7416

Jeffreysaykiat.Ng@aig.com | www.aig.com.sg



AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards. Click here to find out more.

Follow us:



IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Wednesday, August 21, 2019 9:45 AM To: Ng, Jeffreysaykiat; SUR; assignments

Cc: Hsiao Tong (LKKAuto)

Subject: [EXTERNAL] RE: FW: ***URGENT-RI APPOINTMENT****RE: AIG ref: 7624576799SG003 & 004 // Vision

Law LLC ref: DA1-ylv-Ins-D11-109687-19-er (claimant: UE-TAY SZE YIN)

This message is from an external sender; be cautious with links and attachments.

Dear Jeffrey,

PAL'S

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Invoice No 02-19022/AY

Billing Name & Address Ue-Tay Sze Yin 15 Riviera Drive #07-17 Singapore 467205

Date

21 Mar 2019

Vehicle No : SFV 1541 L

Model: Toyota Wish

tem	Descriptions	Amount S\$
1	Date of inspection: 22 Feb 2019 A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs 304 copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection Total	\$ 1079.00
	SDLS : ONE THOUSAND AND SEVENTY-NINE ONLY	

Notes:

- 1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
- 2. All cheque should have our "invoice No." written on the reverse side of the cheque
- 3. For further enquiries on this invoice, please feel free to contact us

Official Stamp



No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 02-19022/AY / 2019

Date of Report

: 21 Mar 2019

Ue-Tay Sze Yin 15 Riviera Drive

#07-17

Singapore 467205

THIRD PARTY SURVEY ACCIDENT HAPPENED ON

21 Feb 2019

As per your instruction dated 22 Feb 2019 carried out a physical inspection on the said vehicle our report and findings as follows:

with regard to the above matter. We have SFV 1541 L . We enclosed herewith

1. VEHICLE PARTICULARS

Registration No : SFV 1541 L

Model : Toyota Wish Year / Capacity : 2015/1798

Chassis No : JTDGG20WX0J002312

Engine No : 2ZR1526444

Mileage : 92012 Colour : Black

2. TYRES CONDITION

	OFFICE OF THE		Size	Made	Balance		Rim
FRONT	O/S		195/65 R15	Yokohama	5.00	mm	Sport
REAR	O/S	*	195/65 R15	Yokohama	5.00	mm	Sport
FRONT	N/S	83	195/65 R15	Yokohama	5.00	mm	Sport
REAR	N/S	11	195/65 R15	Yokohama	5.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883 Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear and front portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Derrick Motor Works

Blk 9002 Tampines Street 93 #01-72 Tampines Ind Park A

Singapore 528836

Estimated normal period of repair : 13 working days to complete.

6. Enclosed number of photograph : 304 copies.

- 7. In accordance to your instruction, we have <u>Not Authorised</u> repair to the vehicle and the survey was done on a <u>"Without Prejudice"</u> basis. We hope that this report will be of assistance to you in dealing with the matter.
- Should you discover any discrepancy in the report, please kindly notify us <u>within 2 weeks</u>, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

REPAIR DETAILS

Reco	mmer	habr	Parts
T-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C-C	1111111	IU etu	F dillo

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1	*FRT NUMBER PLATE BASE	Dented	0.00 F	*. F
3	1	*FRT BUMPER	Broken	0.00 F	*- F
4	1	*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1	*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
6	1	*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
7	1	*FRT BUMPER SPONGE	Broken	0.00 F	*- F
8	1	*FRT BUMPER GRILLE	Dislodged	0.00 F	*- F
9	1	*FRT LH BUMPER FOG LAMP COVER	Broken	0.00 F	*- F
10	1	*FRT RH BUMPER FOG LAMP COVER	Broken	0.00 F	*- F
11	3	*FRT LH BUMPER FOG LAMP	Broken	0.00 F	*- F
12	1	*FRT RH BUMPER FOG LAMP	Broken	0.00 F	*. F
13	1	*FRT GRILLE	Cut	0.00 F	*. #
14	1	*FRT SUPPORT PANEL	Repair	0.00 F	• #
15	1	*FRT LH HEADLAMP ASSY	Broken	0.00 F	* F
16	1	*FRT RH HEADLAMP ASSY	Broken	0.00 F	• •
17	1	*BONNET	Bent	0.00 F	*. F
18	1	*BONNET EMBLEM	Necessary	0.00 F	*. F
19	1	*REAR NUMBER PLATE	Bent	0.00 F	*- F
20	1	*REAR NUMBER PLATE GARNISH	Dented	0.00 F	*- F
21	1	*REAR BUMPER	Dented	0.00 F	*. F
22	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*. F
23	1	*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	* F
24	2	*REAR BUMPER REFLECTOR	Cracked	0.00 F	
25	1	*REVERSE SENSOR	Dislodged	0.00 F	*- F
26	1	*TAILGATE	Dented	0.00 F	*- F
27	3	*TAILGATE EMBLEM	Necessary	0.00 F	*. F
28	1	*TAILGATE MOULDING	Dislodged	0.00 F	
29	1	*TAILGATE GARNISH	Broken	0.00 F	*. F
30	1	*TAILGATE LAMP	Broken	0.00 F	*. F
31	1	*TAILGATE GLASS RUBBER	Necessary	0.00 F	*.F
32	1	*TAILGATE GLASS SEALANT	Necessary	0.00 F	*. F
33		*TAILGATE LOCK	Bent	0.00 F	
34	1	*TAILGATE RUBBER	Cut	0.00 F	• •
35	1	*CENTRE EXHAUST PIPE ASSY	Bent	0.00F	• F
36	1	*CENTRE EXHAUST MOUNTING (RUBBER)	Distorted	0.00 F	*. F
37	1	*REAR EXHAUST MOUNTING	Distorted	0.00F	*- F
38	1	REAR RH FENDER INNER GARNISH	Distorted	0.00 F	* F
	inchise part	NEAR AIT FERDER IRRER GARRIST	Distoried -	0.001	
FREE					

Report was unsubmitted during this print-out.

Vehicle No: Report No:

SFV 1541 L TP/ 02-19022/AY / 2019

		TS

aty	Parts Description	Condition		orkshop's stimation	Our Revised Estimation
	List Items				
1	Rear windscreen moulding	Necessary	\$	132.40	\$ / 132.40 (
1	Rear tailgate	Damage	\$	1209.65	\$ 1209.65
1	Rear tailgate chrome handle	Damage	\$	268.10	\$ 200.00 268.10
1	Rear tailgate Inner trim board	Damage	\$	325,40	\$ 325.40 B
2	Rear tailgate lamps	Damage	s	465.80	\$ /465.800
1	Rear tailgate lock	Damage	\$	409.00	\$ 409.00
1	Rear tailgate logo	Necessary	\$	68.50	\$ 68.50 %
1	Rear tailgate rubber	Necessary	s	220.60	\$ 220.60 5
1	Rear tailgate 'VALVE' emblem	Necessary	\$	46.00	\$46.00 N
1	Rear tailgate handle switch	Damage	\$	145.00	\$ \145.00 B
2	Rear taillamps	Damage	Š	643.00	\$ \(\begin{array}{c} 643.00 \(\beta \)
1	Rear end panel	Damage	\$	477.20	\$ 477.20 \$
1	Rear end panel top garnish	Damage	\$	202.50	\$ \square 202.50 B
1	Rear end panel sensor	Damage	Š	151.80	\$ 151.80 %
1	Rear bumper	Damage	\$	499.50	\$ / 499.50 B
2	Rear bumper brackets	Damage	Š	137.00	\$ \square 137.00 \beta
2	Rear bumper reflectors	Damage	Š	139.20	\$ 139.20 8
2	Rear bumper side retainers	Necessary	Š	103.00	\$ /103.00 N
1	Rear floor panel	Repair	\$	580.30	\$
1	Rear floor panel board	Damage	Š	310.50	\$ 310.50 S
	Rear floor panel board inner garnish	Damage	S	157.20	\$ 157.20 <i>5</i>
	Rear exhaust silencer	Damage	\$	780.15	\$ 780.15
2	Rear exhaust silencer mountings	Necessary	ě	77.80	
1	Rear o/s fender	Damage	ě	775.90	\$77.90 R \$ 775.90 R
1	Rear o/s fender inner lower garnish	Damage	***********	629.95	\$ 629.95
1	Bonnet	Repair	Š	722.80	\$ 029.95
	Bonnet logo	Necessary	ě	58.65	\$ 58.65 N
2	Front headlamps	Damage	9	1802.40	
ï	Front grille	Damage	\$	107.32	
	Front bumper	Damage	\$	465.57	\$ /107.32 8
	Front bumper fog lamps				\$301.90465.57
	Front bumper fog lamp covers	Damage	\$	339.80	\$ \sqrt{339.80 &}
	Front bumper inner sponge	Damage	\$	101.60	\$ 69,30 101.60 B
	Front bumper reinforcement	Damage	\$	97.65	\$ / 97.65 B
2	Front bumper side grilles	Damage		275.24	\$ 275.24 R
2	Front bumper side retainers	Damage	\$	97.90	\$82.60 97.90 5
i	Front support panel	Necessary	\$	78.20	\$ 78.20 No
	Tont support parier	Repair	\$	1329.00	\$

8370.57

List Items Sub Total \$ 14431.58 \$ 11799.48 Vehicle No: Report No:

SFV 1541 L TP/ 02-19022/AY / 2019

IΔ	RO	UR	CC	ST
_		un	-	

S/No	Job Descriptions	orkshop's stimation		r Revised stimation
	Spare Parts Total c/f	\$ 11404.93	\$	9365.86
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ 2	o-ro 40.00
2	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 2	0 m 40.00
3	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 150.00	\$ 5	6-60100:00
4	To remove and replace air-con system, refill gas and test for leakages.	\$ 200.00	Not	Required
5	To remove and refit rear windscreen glass.	\$ 200.00	\$	120.00
6	To remove and refit quarter glass to facilitate the repairs.	\$ 100.00	\$	60.00
7	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 150.00	\$ 5	80.00
8	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and wield body panels. To re-adjust to the original position using power tools.	\$ 2000.00	\$	1,600.00 1760.00
9	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 2000.00	\$	1760.00
0	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 250.00	\$	150.00
	Total	\$ 16554.93	\$	13475.86

Vehicle No:

Report No:

SFV 1541 L TP/ 02-19022/AY / 2019

SPARE	PARTS
-------	--------------

Qty	Parts Description		Condition		orkshop's stimation		ır Revised stimation
	List Items		List Items Total c/f	\$	14431.58	\$	11799.48 837057
1	Front support top garnish		Damage	\$	115.00	\$	√115.00
		Discoun	t 25.0%	\$	14546.58 3636.65 10909.93	\$	11914.48 246 2978.62 212 8935.86 63
1	Special Nett Items Rear windscreen sealant		Necessary	\$	80.00	•	
1	Rear bumper clip (1 set)		Necessary	\$	80.00 35.00	\$ 3. \$	
1	Rear reverse sensor (1 set)		Damage	s	280.00	\$20	35.00
1	Rear o/s fender quarter glass :	sealant	Necessary	s	40.00	s	20.00
1	Front number plate		Damage	\$	60.00	\$ 20	45.00
			100000000000000000000000000000000000000	\$	495.00	\$	430.00 3/8/00

9365.86

Vehicle No:

SFV 1541 L

Report No:

TP/ 02-19022/AY / 2019

LABOUR COST

S/No Job Descriptions Workshop's Estimation Estimation

Total c/f \$ 16554.93 \$ 13475.86

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 10800.00

SDLS: TEN THOUSAND EIGHT HUNDRED ONLY

Qualified Appraiser

Parts 6364.18

3 N 310.00

Labour 2320.60

8994.18

1798.84

7195.34

LIS 7,150/2

Repaindays 8

TOTIM LIM

Page 6

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the clams process.
- This Form must be completed by the Policyholper and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wiful representation or witholding of material facts may allow was represented to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- Filly the fodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available atoresaid

ACCIDENT	STAT	EMENT
ACCIDEN'		EMEN

Date Of Report 22/02/2019 12:59 Date Of Accident 21/02/2019 17:10

Exact Location Of Accident UPPER CHANGI ROAD EAST TWDS BEDOK

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SFV1541L

Insured/Policyholder

Name Of Registered Owner UE-TAY SZE YIN NRIC No S7522140A Email Address NOEMAIL

Mobile Phone No (LOCAL) +65-96199806 Alternative Phone No. OTHERS-96199806

Vehicle Particulars

Manufacturer TOYOTA

Model WISH-1.8 CVT (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company AVIVA LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO Policy Number 10818411

Cover Note Number

Driver

Name of Driver UE-TAY SZE YIN NRIC No S7522140A Date Of Birth 09/08/1975 Occupation INDOOR Date Of Driving Pass 30/03/1999

Driving Experience 19 YEARS AND 10 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-96199806

Fax Number

Contact Number OTHERS-96199806

EMail Address NOEMAIL Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHD1462C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

GBD7806B

Vehicle Make/Model/Colour

Details Of Properties

and the second second

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

B. SLG 1123.
C. SHO 1462C
D GEO 1806B.
Upper Chang Raffee twends Bridge

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LIGHT OF THE ACCIDENT

LIGHT OF THE ACCIDENT

There of the standard training was moving along schooly. All A souther

There is moved the standard training and the standard training of the standard training to compase there is a should be the standard training to compase there is the standard training of t

DECLARATION

I/We declare the foregoing porticulars are this in every respect.

Paticyholder's Signatury Date & Timis: Enver's Signature (If driver is not the quity holder) Late & Time

Name: sale;/Y/N No.

Reporting Centre Perso

MNA119024840 / National Assessment Centre Services - Ubi ENTRY DATE & TIME 22/02/2019 14:33 SUBMITTED BY: Jackson Ho Zhao Tian

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Occupation

Date Of Driving Pass

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

	ACCIDENT STATEMENT
Date Of Report	22/02/2019 14:33
Date Of Accident	21/02/2019 17:00
Exact Location Of Accident	UPP CHANGI RD EAST BEFORE BUS STOP: 96019
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLG472S
insured/Policyholder	
Name Of Registered Owner	QUEK LEE CHENG, NANTHANI (GUO LIQING, NANTHANI)
NRIC No	S8224971J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91806001
Alternative Phone No	Office-91806001
Vehicle Particulars	
Manufacturer	KIA
Model	SORENTO 2.2(A) CRDI 2WD
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
f No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100482856-02
Cover Note Number	
Driver	
Name of Driver	QUEK LEE CHENG, NANTHANI (GUO LIQING, NANTHANI)
NRIC No	S8224971J
Date Of Birth	01/09/1982

INDOOR

30/07/2003

Gender

Mobile Number

FEMALE

(LOCAL) +65-91806001

Fax Number

Contact Number

OFFICE-91806001

EMail Address

NOEMAIL

Address

26 FERNWOOD TERRACE

#20-01

Postcode

458555

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

4

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBD7806B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

Contact Number Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHD1462C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAX

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SFV1541L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Terriore outegory

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- the compact correctly the cetars of the accident to speed up the clams process
 - to completed by the Policyholder and/or the Authorised Dever
 - colors are received must be at trathful and accurate as possible. Any wiful representation or withholding of more or last this area decreases comparises to expudite policy liability.
- 1 the power and supplied of this form by insurance companies is not an admission of policy liability on the part of the insurance completes.

thre little expecting may be referred to the Police for investigation.

- The British will be forwarded by the insurers of the GA Records Management Centre established by the General Insurance insulative of Singulary (GAS) for archiving and that copies of this report will for a fee be made available upon application by
- to the indigeness of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies or the tripoint being made available aforesaid.
- Consent under the Personal Data Protection Act (PDFA)
 - It interceived, at knowledge, agree and convent than
 - We seemed my workships and the General Insurance Association of Singapore ("GIA") may/are permeted to collect, we there entally process try personal deta/personal information set out in this [form) and disclose and transfer augmented by my insurer (spliestively the "Personal Information") and disclose and transfer augmented information to all insurer(s) who have insured vehicle(s) envolved in this equipment (all insurer(s) who have insured vehicle(s) envolved in this equipment (all insurer(s) who have insured in the collectively referred to as the "Insurers"), the insurers lawyers/ass from the Vincetary Authority of Singapore and any relevant government agency/authority (such as the prince), for the purposes; if
 - 11 processing, hundling ant/or dealing with my claims including the settlement of the claims and any necessary inventigations reviewing to the claims.
 - bit immiligating the adulated and/or my claims.
 - Exilinating out unition dealing with my instructions or responding to any enquiries by me.
 - 6 vi administrang my claims (including the maring of correspondence, statements, invoices, reports or motices to me, which could invoice disclosure of certain personal data about me to bring about delivery of the same as well as on the extremal cover of envelopes/mail packages), and/or
 - (ii) comprising with applicable law in administrating processing, handling and/or dealing with my claims (collectivate the "Purposes")
- to extend other have maked whice(a) method in this accident and the travers' travers/faw firms, may are permitted to extent, use, should and/or process my Personal information for one or more of the above Purposes, and
- you for some information may/can be disclosed by any of the insurers and/or GIA to their third party service provides. In approximation, and the service provides an approximation of singapore, for one or more of the above Purposes.
- (iii) one Personal information will also be suited and used to compile claims testory for the purpose of travel detection, morninger on and management in present and all future claims.
- any from terrotom to collected under (it) above may be shared / discipsed.
 - 1) "multi-repress and/or any other third parties that assist in evaluating investigating, controlling or managing fraud, required to: Live enforcement and government agencies as reasonably required for the purposes stated, or
 - (1) for complying with requirements under any regulations, lews or court seders.

Contraction to the service

Driver's Signature \"
If driver is not the policyhelder!
Date & Time:

Reporting Contine For Name NRC/FIN No.

	包	
	大区台	
ı	*	,

A: 3164715

8. 650 78063

C: 540 14626

0. SEV 1541 L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

	1	3696	New	φ.	590	gie	alway	Vepri	Charge	1,2	Eugt.	ويواري	7
ů.	10	440	State	Cer		- 0	4, 6	. مداد	I.,	543	When	I o	ume
		wy	T	in	oi.	Video	e legg	ep ==	- (4	nied.	My	yet.	le.
	hy	yr i	-rward	£	kie	the	Vénuse	0	. 4	m/4	ut .	ne	
										-			
	-				_					_			
	-				_								

of driver a not the a Date & Time

Name NRC/FIN No.

Reporting Controlling




































51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Intern	ationale Des Experts En Autor	mobile
AIG ASIA PACIFIC IN	SURANCE PTE LTD	Ref : CS3/AIG19003	3497/Btd3e2-1
78 SHENTON WAY # CHARTIS BUILDING SINGAPORE 079120		Date: 30-08-2019	
ATTN : NG JEFFREY		Code: AIG	
1.		ars :- THIRD PARTY CLA	
Insured Veh.	SLG 472S	Veh. Inspected	SFV 1541L
Policy No.	2100482856-02	Coverage (\$)	0.00
Claim No.	7624576799SG003	Excess (\$)	0.00
Assign From	NG JEFFREY	Assign Date	21/08/2019
2.	Vehicle Pa	articulars & Condition	
Make & Model	TOYOTA WISH	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTDGG20WX0J002312	Colour	BLACK
Odometer	92019	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3.	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
4.	Descri	ption of Damages	
	USTAINED DAMAGES AT THE	FRONT AND REAR PORTIO	ON.
DAMAGES SEE I		eral Information	AT THE RESERVE
Accident Date	21/02/2019	Inspection Date	25/02/2019
Survey held at			EGIVE EQ 1Q
ourvey neid at	BLK 9002 #01-72 TAMPINES ST 93 SINGAPORE 528836		
5a.		Remarks	
	ON WAS CONDUCTED ON A"		
5b.	Estim	ate Days of Repair	
ESTIMATED NO	RMAL PERIOD FOR REPAIR:	8 Working Day	ys



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFV 1541L

ty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN MOULDING	NECESSARY	132.40	132.40
1	REAR TAILGATE	DENTED	1,209.65	1,209.65
1	REAR TAILGATE CHROME HANDLE	CRACKED	268.10	200.00
1	REAR TAILGATE INNER TRIM BOARD	BROKEN	325.40	325.40
2	REAR TAILGATE LAMPS	BROKEN	465.80	465.80
1	REAR TAILGATE LOCK	DENTED	409.00	409.00
1	REAR TAILGATE LOGO	NECESSARY	68.50	68.50
1	REAR TAILGATE RUBBER	SERVICEABLE	220.60	9
1	REAR TAILGATE 'VALVE' EMBLEM	NECESSARY	46.00	46.0
1	REAR TAILGATE HANDLE SWITCH	BROKEN	145.00	145.0
2	REAR TAILLAMPS	BROKEN	643.00	643.0
1	REAR END PANEL	DENTED	477.20	477.2
1	REAR END PANEL TOP GARNISH	BENT	202.50	202.5
1	REAR END PANEL SENSOR	BROKEN	151.80	151.8
1	REAR BUMPER	BROKEN	499.50	499.5
2	REAR BUMPER BRACKETS	BROKEN	137.00	137.0
2	REAR BUMPER REFLECTORS	BROKEN	139.20	139.2
2	REAR BUMPER SIDE RETAINERS	NECESSARY	103.00	103.0
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	580.30	1
1	REAR FLOOR PANEL BOARD	SERVICEABLE	310.50	
1	REAR FLOOR PANEL BOARD INNER GARNISH	SERVICEABLE	157.20	
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	780.15	3
2	REAR EXHAUST SILENCER MOUNTINGS	CUT	77.80	77.8
1	REAR O/S FENDER	TO REPAIR SEE LABOUR	775.90	2
1	REAR O/S FENDER INNER LOWER GARNISH	TO REPAIR SEE LABOUR	629.95	à
1	BONNET	TO REPAIR SEE LABOUR	722.80	
1	BONNET LOGO	NECESSARY	58.65	58.68

Report Ref No. CS3/AIG19003497/Btd3e2-1



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
2	FRONT HEADLAMPS	BROKEN	1,802.40	1,802.40
1	FRONT GRILLE	BROKEN	107.32	107.32
1	FRONT BUMPER	CRACKED	465.57	301.90
2	FRONT BUMPER FOG LAMPS	BROKEN	339.80	339.80
2	FRONT BUMPER FOG LAMP COVERS	BROKEN	101.60	69.30
1	FRONT BUMPER INNER SPONGE	BROKEN	97.65	97.65
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	275.24	
2	FRONT BUMPER SIDE GRILLES	BROKEN	97.90	82.60
2	FRONT BUMPER SIDE RETAINERS	NECESSARY	78.20	78.20
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	1,329.00	
1	FRONT SUPPORT TOP GARNISH	DAMAGED	115.00	115.00
	LESS 25% DISCOUNT		-3,636.65	-2,121.39
			10,909.93	6,364.18
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	30.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	35.00	35.00
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR O/S FENDER QUARTER GLASS SEALANT (SN)	NECESSARY	40.00	20.00
1	FRONT NUMBER PLATE (SN)	DAMAGED	60.00	25.00
	W 440		495.00	310.00
	LABOUR			
	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		50.00	20.00
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING, REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		50.00	20.00
	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS.		150.00	50.00
	TO REMOVE AND REPLACE AIR-CON SYSTEM, REFILL GAS AND TEST FOR LEAKAGES.	NOT NECESSARY	200.00	
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.		200.00	120.00
	TO REMOVE AND REFIT QUARTER GLASS TO FACILITATE THE REPAIRS.	NOT NECESSARY	100.00	

Report Ref No. CS3/AIG19003497/Btd3e2-1



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTINGS.		150.00	50.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS: INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL, REAR EXHAUST SILENCER, REAR O/S FENDER, REAR O/S FENDER INNER LOWER GARNISH, BONNET, FRONT BUMPER REINFORCEMENT AND FRONT SUPPORT PANEL.		2,000.00	1,000.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		2,000.00	1,000.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		250.00	60.00
			5,150.00	2,320.00
	GRAND TOTAL		16,554.93	8,994.18
	RECOMMENDED COST OF LUMP SUM REPAIRS	I CIEPT		7,150.00

Report Ref No. CS3/AIG19003497/Btd3e2-1



LIM TEOW GUAN

Automotive Assessor

(TO ITS PRE-ACCIDENT CONDITION)

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatspever, in contact or tork is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.