


Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-19-077113

Date of Request: 15/05/2019

Your Ref No: SB/PO/ACC/2019-8983

ORACLE LAW CORPORATION
237 Alexandra Road #04-11
The Alexcier
Singapore 159929

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 09/05/2019

Place of Accident: ROAD BETW CARPENTER & HONGKONG

Client Vehicle No: SJV1910H

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
GZ2026T	No match found.	

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-077113

Date of Request: 15/05/2019

Your Ref No: SB/PO/ACC/2019-8983

ORACLE LAW CORPORATION

237 Alexandra Road #04-11

The Alexcier

Singapore 159929

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 09/05/2019

Place of Accident: ROAD BETW CARPENTER & HONGKONG

Client Vehicle No: SJV1910H

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

SEARCH RESULTS

Our Ref No: GR-19-100168
Date of Request: 24/06/2019

Your Ref No: SB/PO/ACC/2019-8983

ORACLE LAW CORPORATION
237 Alexandra Road #04-11
The Alexcier
Singapore 159929

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 09/05/2019
Place of Accident: BETW CARPENTER/HONGKONG ST
Client Vehicle No: SJV1910H

With reference to your search criteria for the accident report, the following documents were found to closely match your search criteria:

REQ. VEHICLE	ACCIDENT LOCATION	ACCIDENT DATE
GZ2026T	ALONG CARPENTER STREET & HONG KONG STREET	09/05/2019 15:15

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-100168

Date of Request: 24/06/2019

Your Ref No: SB/PO/ACC/2019-8983

ORACLE LAW CORPORATION
237 Alexandra Road #04-11
The Alexcier
Singapore 159929

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 09/05/2019

Place of Accident: BETW CARPENTER/HONGKONG ST

Client Vehicle No: SJV1910H

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-100174
Date of Request: 24/06/2019

Your Ref No: SB/PO/ACC/2019-8983

ORACLE LAW CORPORATION
237 Alexandra Road #04-11
The Alexcier
Singapore 159929

Dear Sir/Madam,

Date of Accident: 09/05/2019
Vehicle No: SJV1910H
Place of Accident: RD BETWEEN CARPENTER ST TWDS HONG KONG ST
Involving Vehicle No: GZ2026T

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
GZ2026T	RD BETWEEN CARPENTER ST TWDS HONG KONG ST	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

Our ref. : UAM19-05.12-AK-STP-HLA-SJV1919H

Date : 31 May 2019

Motormaxx Pte Ltd

WITHOUT PREJUDICE

Dear Sir,

Re : Third Party Claim For Vehicle Registration No. SJV1910H

We refer to your instruction to appraise the above-mentioned vehicle on 10 May 2019

A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. Hiap Lek Automobile Trading for SGD 8,108.84 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.

Our revised quotation for the repair is SGD 5,545.21. In our opinion, it to be excessive. Therefore, we recommend a contract lump-sum repair cost. This is more economical than to have the above-mentioned vehicle repaired on parts by/for parts basis. Invariably, the repairer has the prerogative/option for the recommended replacement parts to either be repaired or be replaced.

We have negotiated with the repairer and they have agreed to repair the above-mentioned vehicle for SGD 4,400.00 NETT. Which, in our opinion is fair and reasonable.

The repairer has agreed to undertake the repairs to your requirement at the recommended contract lump-sum. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs.

Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of 4 (Four) days.

We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisal schedule and invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Yours faithfully,

United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc
Motor Vehicle Appraiser

Encls. :

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

VEHICLE INSPECTION REPORT

To : Motormaxx Pte Ltd

Our ref. : UAM19-05.12-AK-STP-HLA-SJV1919H

Date : 31 May 2019

REFERENCE

Assign by	: Motormaxx Pte Ltd	Insured	: To be advice
Assign on	: 10 May 2019	Policy no.	: To be advice
Inspection on	: 10 May 2019	Claim no.	: To be advice
Accident on	: 09 May 2019	Sum insured	: To be advice
Workshop name	: Hiap Lek Automobile Trading	Excess	: Not applicable
Inspection at	: 160 Sin Ming Drive	3rd party Veh.	: To be advice
	#05-17 Sin Ming Autocity	3rd party ins.	: To be advice
	Singapore 575722		

PARTICULARS OF DAMAGED VEHICLE

Registration no.	: SJV1910H	Odometer	: 0 km
Make / Model	: Toyota Corolla Altis 1.6 Auto	Chassis no.	: MR053ZEE106164567
Regn. date	: 14 Jan 2010	Engine no.	: 3ZZ4962527
Body colour	: Black	Engine cap.	: 1598 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	: In order	Paintwork	: Good
Footbrake	: In order	Undercarriage	: Serviceable
Handbrake	: In order	Gen. condition	: Good

TYRE CONDITION ON VEHICLE


	Make	Size	Tread depth	Type of road wheel
Front N/S	: Firenza	195/65R15	70%	Alloy
Front O/S	: Firenza	195/65R15	70%	Alloy
Rear N/S	: Firenza	195/65R15	70%	Alloy
Rear O/S	: Firenza	195/65R15	70%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

* Denotes damaged component/s

POINT OF IMPACT

On the near side in the direction from left to right.

**SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT**

The impact of the collision has damaged / affected the n/s front fender, wing mirror, front door, rear door and etc...

Please refer to Annex A (Appraisalment Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on 11 May 2019 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs Hiap Lek Automobile Trading as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 4,400.00 to carry out the repairs. Please refer to Annex A (Appraisalment Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would takes approximately 4 (Four) working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully,

United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc
Motor Vehicle Appraiser

UAM

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SJV1910H

Our reference : UAM19-05.12-AK-STP-HLA-SJV1919H

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
-----	-----	-------------	---------------------	-----------------------	------------------

LIST ITEMS

1	1	Front fender n/s	Dented	635.50	✓635.50 DDV
2	1	Front fender inner shield n/s	Re-Used	145.30	—0.00
3	1	Wing mirror n/s	Damaged	523.40 422.10	523.40 BR ✓
4	1	Front door n/s	Dented	927.70 881.90	927.70 DDV ✓
5	1	Front door inner lock n/s	Distorted	221.25	-221.25 SVCX
6	1	Front door outer handle n/s	Distorted	185.00	-185.00 RX
7	1	Front door handle key sleeve n/s	Distorted	120.30	120.30 CUT ✓
8	1	Front door black tape n/s	Necessary	145.00	145.00 NECV
9	1	Front door protector n/s	Distorted	178.00	178.00 SVCX
10	1	Front door protector chrome n/s	Grazed	123.00	123.00 SVCX
11	1	Front door weatherstrip n/s	Necessary	148.00	148.00 CUT ✓
12	1	Front door regulator gear n/s	Jammed	277.00	277.00 SVCX
13	1	Front door regulator motor n/s	Shorted	326.80	-326.80 SVCX
14	1	Front door window run channel n/s	Necessary	220.00	220.00 NECV ✓
15	1	Front door trim board n/s	Deformed	316.00	✓316.00 CRP ✓
16	1	Rear door n/s	Serviceable	711.59	0.00
				5203.84	4346.95 2988.80
Less 0% / 25%				0.00	1086.74 722.20
				5203.84	3260.21 2166.60

SPECIAL NETT ITEMS

1	1	Sundries	Necessary	50.00	30.00 REUSE
2	1set	Front fender inner shield clip n/s	Necessary	25.00	25.00 NECV
3	1	Front door sealant n/s	Necessary	100.00 30.00	80.00 NECV
4	1set	Front door trimboard clips n/s	Necessary	50.00 30.00	50.00 ✓
				225.00	185.00
TOTAL				5428.84	3445.21 85.00

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SJV1910H

Our reference : UAM19-05.12-AK-STP-HLA-SJV1919H

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
			Part Balance C/F	5428.84	3445.21
<u>LABOUR & MISC CHARGES</u>					
1		To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.		800.00	^{500.00} 600.00 ✓
2		To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.		80.00	^{40.00} 60.00
3		To remove and refit interior upholstery to facilitate the repair.		200.00	^{50.00} 180.00 ✓
4		To remove and refit n/s front door component to replace n/s front door, check and alignment.		100.00	^{50.00} 80.00
5		To remove and refit n/s rear door component to replace n/s rear door, check and alignment.	Not Applicable	100.00	0.00
6		To apply undercoating on the accident repair and replaced panel for rust protection.		200.00	^{80.00} 180.00
7		Supply spray paint material and necessary items to respray n/s front fender, wing mirror, front door, door centre pillar, rear door and other affected area / panel.		1200.00	^{600.00} 1000.00
TOTAL				2680.00	2100.00
Total Parts and Labour Cost of Repair				8108.84	5545.21
Less (Lumpsum repair adjustment)					1145.21
Adjustment Parts and Labour Cost of Repair					4400.00

L/S 3,550/-

Parts 2166.60
 SN 85.00
 Labour 1320.00
 3571.60

TGim
 23/8/19




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS3/LPC19008318/Btd3s2-1		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 26-08-2019		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 2026T	Veh. Inspected	SVJ 1910H	
Policy No.	Z18VC05000241	Coverage (\$)	0.00	
Claim No.	18/19/19/VC05/021780	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	05/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MR053ZEE106164567	Colour	BLACK	
Odometer	147900	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65R15	FIRENZA	6 mm	
L/H Front Tyre	195/65R15	FIRENZA	6 mm	
R/H Rear Tyre	195/65R15	FIRENZA	6 mm	
L/H Rear Tyre	195/65R15	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/05/2019	Inspection Date	10/05/2019	
Survey held at	160 SIN MING DRIVE #05-17			
Repairer	HIAP LEK AUTOMOBILE TRADING			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 1910H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER N/S	DENTED	635.50	635.50
1	FRONT FENDER INNER SHIELD N/S	REUSE	145.30	-
1	WING MIRROR N/S	BROKEN	523.40	422.10
1	FRONT DOOR N/S	DENTED	927.70	881.90
1	FRONT DOOR INNER LOCK N/S	SERVICEABLE	221.25	-
1	FRONT DOOR OUTER HANDLE N/S	TO REPAIR SEE LABOUR	185.00	-
1	FRONT DOOR HANDLE KEY SLEEVE N/S	CUT	120.30	120.30
1	FRONT DOOR BLACK TAPE N/S	NECESSARY	145.00	145.00
1	FRONT DOOR PROTECTOR N/S	SERVICEABLE	178.00	-
1	FRONT DOOR PROTECTOR CHROME N/S	SERVICEABLE	123.00	-
1	FRONT DOOR WEATHERSTRIP N/S	CUT	148.00	148.00
1	FRONT DOOR REGULATOR GEAR N/S	SERVICEABLE	277.00	-
1	FRONT DOOR REGULATOR MOTOR N/S	SERVICEABLE	326.80	-
1	FRONT DOOR WINDOW RUN CHANNEL N/S	NECESSARY	220.00	220.00
1	FRONT DOOR TRIM BOARD N/S	CRACKED	316.00	316.00
1	REAR DOOR N/S	SERVICEABLE	711.59	-
	LESS 25% DISCOUNT		-	-722.20
			5,203.84	2,166.60
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	REUSE	50.00	-
1	SET FRONT FENDER INNER SHIELD CLIP N/S (SN)	NECESSARY	25.00	25.00
1	FRONT DOOR SEALANT N/S (SN)	NECESSARY	100.00	30.00
1	SET FRONT DOOR TRMBOARD CLIPS N/S (SN)	NECESSARY	50.00	30.00
			225.00	85.00
<u>LABOUR</u>				
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR OUTER HANDLE N/S.		800.00	500.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS.		80.00	40.00
	TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR.		200.00	50.00

Report Ref No. CS3/LPC19008318/Btd3s2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT N/S FRONT DOOR COMPONENT TO REPLACE N/S FRONT DOOR, CHECK AND ALIGNMENT.	NOT NECESSARY	100.00	50.00
	TO REMOVE AND REFIT N/S REAR DOOR COMPONENT TO REPLACE N/S REAR DOOR, CHECK AND ALIGNMENT.		100.00	-
	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION.		200.00	80.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY N/S FRONT FENDER, WING MIRROR, FRONT DOOR, DOOR CENTRE PILLAR, REAR DOOR AND OTHER AFFECTED AREA / PANEL.		1,200.00	600.00
			2,680.00	1,320.00
GRAND TOTAL			8,108.84	3,571.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,850.00

Report Ref No. CS3/LPC19008318/Btd3s2-1

LIM TEOW GUAN

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.