Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19014831/T1GA3Q2

Date: 07/07/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00004211

Claimant Insured Vehicle No: SJP301D SLN2132Z

Vehicle No:

ΤP Date of Loss: 16/08/2019 Nature of Claim: Claim No: 1201900024392

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLN2132Z Reg No:

Make & Model: MAZDA 3, 1.5 SEDAN EU6 (A) Engine No: P520442327

Reg. Date: 26/04/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0151064

Colour: Odometer: 152437 km Grey

Engine Capacity: 1496 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm Front Right Side: Rear Right Side: West Lake 6 mm West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,015.20	1,600.00	2,415.20	60.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,220.00	530.00	1,690.00	76.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,235.20	2,130.00	4,105.20	65.84
+ GST 7.00/7.00% (S\$)	436.46	149.10	287.36	65.84
Nett Amount (S\$)	6,671.66	2,279.10	4,392.56	65.84
+ Loss of Use (3.0 x	S\$70.00/day) (S\$)	210.00		
+ Car Rental (3.0 x S\$66.95/day) (S\$)		200.85		
+ Do	c/Search Fee (S\$)	7.45		
	Nett Liability (S\$)	2,697.40		
Global Sur	m Settlement (S\$)	2,600.00		

INSPECTION

Date of Assignment: 21/08/2019

Date Inspected: 09/09/2019 Inspected At: Pegasus Engineering & Trading Pte

Ltd (Kian Teck) 74 Kian Teck Road Singapore 628800

Estimated Period of Repair: 2.0 days Adjuster Report Page 2 of 4

Adjuster: Chong Pui Lin Manager: MOHD TAUFIKH BIN HAMID

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Mar 2020)

Parts: 143 MAZDA 3 1.5 SEDAN EU6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLN2132Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,075.00 FL	*1,075.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Not Necessary	150.00 FL	*-FL
3	10		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
4	4		*REAR BUMPER RIVET	Necessary	20.00 FL	*20.00 FL
5	1		*REAR BUMPER INNER CENTER BRACKET	Not Necessary	35.00 FL	*- FL
6	2		*REAR BUMPER TOW COVER	Missing	70.00 FL	*70.00 FL
7	2		*REAR BUMPER REFLECTOR	Not Necessary	230.00 FL	*- FL
8	1		*REAR REINFORCEMENT	Dented	545.00 FL	*545.00 FL
9	1		*REAR END PANEL	Not Necessary	715.00 FL	*-FL
10	1		*REAR END PANEL TOP GARNISH	Not Necessary	125.00 FL	*- FL
11	6		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	24.00 FL	*- FL
12	1		*REAR WEATHERSTRIP	Not Necessary	155.00 FL	*- FL
13	1		*REAR BOOTLID COVER	Not Necessary	1,185.00 FL	*-FL
14	1		*REAR BOOTLID MAZDA EMBLEM	Not Necessary	75.00 FL	*- FL
15	1		*REAR BOOTLID MAZDA 3 BADGE	Not Necessary	65.00 FL	*- FL
16	1		*REAR BOOTLID SKYACTIV BADGE	Not Necessary	85.00 FL	*- FL
17	1		*REAR REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
18	1		*REAR NO PLATE & CASING	Not Necessary	60.00 FS	*-FS
F=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.			
				Sub Total (S\$)	•	1,950.00
			- List Item Discount on L Items 2	20.00/20.00% (S\$)	918.80	350.00
				Total Parts (S\$)	4,015.20	1,600.00

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
TO REMOVE & REPLACED REAR REVERSE SENSOR	New	100.00	30.00
TO APPLY RUSTPROOFING & TUFFCOATING TREATMENT	New	120.00	0.00
TO KNOCKING & PANEL BEAT	New	1,000.00	200.00
TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	300.00
Gross Labour Cost (S\$)		2,220.00	530.00
	OUR Items TO REMOVE & REPLACED REAR REVERSE SENSOR TO APPLY RUSTPROOFING & TUFFCOATING TREATMENT TO KNOCKING & PANEL BEAT TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS	OUR Items TO REMOVE & REPLACED REAR REVERSE SENSOR New TO APPLY RUSTPROOFING & TUFFCOATING New TREATMENT TO KNOCKING & PANEL BEAT New TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS New	OUR Items TO REMOVE & REPLACED REAR REVERSE SENSOR New 100.00 TO APPLY RUSTPROOFING & TUFFCOATING New 120.00 TREATMENT TO KNOCKING & PANEL BEAT New 1,000.00 TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS New 1,000.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.