Surveyor Taufit	0	ASSIGNMEN				
From (Person): kwot	woon choo	of MS19			Onte/Time: 20. 8.19	16.27 p. A
Estimated Cost:			Bill to:		_	
ON THE WSETT RE	S/OD RES/EVA	/INV/MV/CS				
To Inspect Vehicle No:	4P 4891	'R		Insured:		
at Workshop m/s Q				Tel	62686183	
of BIL 3 Pionu	OF DESCRIPTION PRODUCTS	h #01-18				
Policy No. 290309	63		Claim No:	602846		
Sum Insured:				700		
Make of Veh:				- 1	D.O.A. 9.6.2017	
CA (REV) REP. / Date/Time: 23.4.19	REV 24 HRS 10-1000-n Per	mon Contacted.	Jage		11 (1) (1) (1)	
Date/Time Action	Instruction ( V	) Estimato.				
YF L	X - X 0P3+					
26/8- Reve	ext via v	lenimen-				
26/2-2:55	mandate o	DOVIVAL	tan Keni	л она		
A		7 1.000	10	) 0		

winn

REF:

· Merimen e-Claims

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Authled	Status	
Main	20 Aug 2019 16:17 Sendback Est	20 Aug 2019 16:30 \$\$7,415.00	22 Aug 2019 16:27 Assign				New Assi Cancel C	Service of the servic
	Main	Refere	nce	Claim De	etails	Documents		Show All
CLAIM SU	BFOLDER DETAIL	LS						
Insured:		JNR MARI	NE ENGINEERING	G PTE. LTD.,	Co. Reg. No.: 201412	THE RESERVE OF THE PARTY OF THE		
Vehicle Re	g. No.:	YP4890F	t	Date of	Loss:	09/08/2019 11:00 - :59 [43 Months and 8 Days From Reg Date (Man Yr)]		
Claim Type	E	OD / 602846 Policy/Cover Note No.:		Coverag	29030963 (Comprehensive) Coverage: 16/11/2018 - 15/11/2019			
				Excess:				
Repairer:			e Motor & Panel :	Service Pte Lt	d (Pioneer) Blk 3 Pi	oneer Road Norti	h, #01-18, 62	8457
Handling Ir	nsurer:	MSIG Insu 6643 13301		apore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 [Handled by Kwok Woon Ch			oon Choo -	
Adjuster: Driver/Cus	to History				6256-3561 [ <b>Imr</b>			
Adj Asg. Ri	Section 1		3/08/2019 1PM to	ARAN (42 / Male) , NRIC: G7326040Q, Tel: +6590514028 Email: NOEMAIL M to 4PM, please survey and revert. Please contact us ASAP if you cannot atten				
ASSOCIATED MAIL RECEIVED					View All	Compose	Case Mail	
There are r	no mail for this case							
E								
	CIATED TASKS			Vic	ew All   Search Tas	ks   Create	New Task	Complete
Due Dat	e Priority Ty	pe Task Grou	p Subject	Handler A	ssigned By Co	mpleted On	Created 0	

# Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Monday, 26 August 2019 2:55 PM

To:

'ADMIN SNGAHTEE'

Cc:

SAMANTHA TAN; Janice Chang; Sharon Sng

Subject:

YP 4890R / OD / MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle YP 4890R (Excess \$700/-). Part by Part repair

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# Claim Audit

	UDIT TRAIL		Remarks	By
io.	On	Audit	Remarks	[1]
	16 Aug 2019 11:31	Clm Veh Model Changed	(203313) MITSUBISHI CANTER 3.0 D FEB21 (M),	Sam
	10-22 - 700000		Reg No: YP4890R, Policy No: 29030963. Acct Date: 2019/08/09. Claim Type: SC. Insur	[1]
	16 Aug 2019 11:31	Cim Created	er: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Ins.Status => Notification. Created from SAS:MSAT19104926	Sam Tan
				Janice
3	20 Aug 2019	Clm Registration Modified	Seti.Type:3->0, Claim Type:SC->OD,	Chang
	16:17	Modified		Siew
				[R]
				Janice
	20 Aug 2019 16:18	Clm Submitted	7249.50.	Chang
				Yin
				[1]
	20 Aug 2019	Ins Sent Back Est	as per janice instruction to send back estimate	Jowyr Tay Me
	16:28	200 200 200 200	THE PLANT CONTINUES OF MICE AND LISTED SOND AND LISTED SOND	Ling
				[R]
	20 Aug 2019	201 2012 2012	E522104	Chang
6	16:30	Clm Submitted	7415.00.	Siew
				Yin
				[I] Keny
7	21 Aug 2019	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):a if c	Ong
1	15:15	Adj Co Assigned	1916 triadiance (Singapore) Free East (Internal Society)	Thlan
				Beng
				[I] Keny
	21 Aug 2019	Adj Next Rpt Changed	Next Rpt:lm. Advice.Due Date:2019/08/22	Ong
	15:15		TO TO THE TOTAL OF THE TOTAL OF THE PROPERTY O	Thian
				Beng [I]
				Keny
9	21 Aug 2019 15:15	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	Ong
	13.13			Thiam Beng
		/		[A]
10	21 Aug 2019 15:21	Assignment 1st Accessed		Ong Z
		1000		Hul [I] On
11	22 Aug 2019 16:26	Adj Assignment Cancelled	Car in on 23/08/2019 1PM to 4PM - outsource as per Jason's instruction	Zi Hu
12	22 Aug 2019	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] On Zi Hu
	16:26 22 Aug 2019 16:27		LKK Auto Consultants Pte Ltd (HQ):Car in on 23/08/2019 1PM to 4PM, please survey an	
		Adj Co Assigned	d revert. Please contact us ASAP if you cannot attend this assignment.	Zi Hu
14	22 Aug 2019	Adj Next Rpt Changed	Next Rpt:lm. Advice.Due Date:2019/08/23	[I] On Zi Hu
	10:27	Pinces Sales-per	et 1 Carrie a company y a comp	[1] On
15	22 Aug 2019 16:27	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	Zi Hu
		Assignment 1st		[A] LE
1.6	22 Aug 2019 16:34	Accessed		THING
	22.4			[A] LE
17	23 Aug 2019 14:03	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	SU
	-17C			THING [A]
	***			DENIS
18	26 Aug 2019 09:06	Adj Rpt Initiated		TAY
	03.00			CHEN
				[A]
	26 Aug 2019			DENIS
19	09:06	Cim Dtl Modified	Vehicle Class; -> -1.	KWEE
				CHEN
				[A]
20	26 Aug 2019	Adj Im. Advice	Next Rpt:Final Rpt.Due Date:2019/09/21	DENIS
20	09:15	Submitted	trems offert time offerman minutes, etc., p.s.	KWEE
				CHEN
				[A] DENIS
21	26 Aug 2019	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/21	TAY
	09:15	1347	5 A	KWEE
				CHE

AL É	UDIT TRAIL	(		
No.	On	Audit	Remarks	By
33 <sup>2</sup>	6 Aug 2019 19:16	Adj Mandate Request	Cur.Req:6672.50:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
	26 Aug 2019 10:17	Clm Registration Modified	Excess: -> 700.00.	[I] Kwok Woon Choo
	26 Aug 2019 14:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/21, Mandate Remarks: a if c	[I] Keny Ong Thiam Beng
25	26 Aug 2019 14:46	Adj Mandate Set	Approved:6672.50:a if c	[I] Keny Ong Thiam Beng

Audit Type None

▼ Go

#### ACTIVITY

Date From

[22/08/2019 16:23] Ong Zi Hui:
Car in on 23/08/2019 1PM to 4PM - outsource as per Jason's instruction
[22/08/2019 15:55] Ong Zi Hui:
Joy confirm car in on 23/08/2019 1PM to 4PM.
[21/08/2019 15:22] Ong Zi Hui:
Janice confirm car not in, will arrange and revert with IHS.

■ Date To

arimen Billin	g for this case -	Transaction H	istory				
Bill Ref No.	Bill Date	Acc Type	Acc Name	(Branch)	Ref. 1	Set 2	Amount
2251375	20/08/2019 16:17	Motor	Sng Ah Tee Motor & Panel Service Pte Ltd	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	YP4890R		xx,xx
2256734	26/08/2019 09:06	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	YP4890R		11.77

#### Note: This document has not been finalised.

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Kwok Woon Choo

26 Aug 2019

#### Preliminary Advice

Vehicle No

: YP4890R

Accident Date

: 09/08/2019

Make

Policy No.

: MITSUBISHI CANTER

: 29030963

Assignment Date

: 22/08/2019

Excess

: \$\$0.00

Date of Inspection

: 23/08/2019

Est, Duration of Repair

: 7.00

Inspection At

: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

BLK 3 PIONEER ROAD NORTH, #01-18

SINGAPORE 628457

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...... portion and parts claimed are consistent to the accident,

Repairer's Estimate (Gross)	:S\$	7,415.00
Revised Amount	:S\$	6,463.50
Check Items (Estimated)	:S\$	209.00
Total	:S\$	6,672.50
Lump Sum Repair	:S\$	

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	54,000.00
COE / PARF Rebate	:S\$	15,222.00
Salvage Value	:S\$	
Margin for Repair	:S\$	38,778.00

#### Remarks

( X	The vehicle is economical	for repair
-----	---------------------------	------------

The above survey was conducted on a 'without prejudice' basis.

# > Back to OneMotoring

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	427H
Vehicle Details	
Vehicle No.:	YP4890R
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Aug 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	4P10C34220
Chassis No.:	FEB21EA20954
Maximum Power Output:	*
Open Market Value:	\$34,954.00
Original Registration Date:	16 Nov 2016
First Registration Date:	16 Nov 2016
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$1,748.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	15 Nov 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$21,118.00
COE Rebate Amount:	\$15,222.00
Total Rebate Amount:	\$15,222.00

The information contained herein is correct as at 13 Aug 2019

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- f. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCI			

Date Of Report 13/08/2019 10:13
Date Of Accident 09/08/2019 11:30

Exact Location Of Accident JUNCTION OF KIAN TECK AVE & INTERNATIONAL RD

Country/State of Loss SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number YP4890R

Insured/Policyholder

Name Of Registered Owner JNR MARINE ENGINEERING PTE. LTD.

Co Reg No 201412427H

Email Address JNRMARINE@YAHOO.COM

Mobile Phone No

Alternative Phone No OFFICE-86871010

Vehicle Particulars

Manufacturer MITSUBISHI

Model CANTER-3.0 D FEB21 (M)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No. Please state action to be taken

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number A29030963MKC

Cover Note Number

Driver

Name of Driver ULAGANATHAN DHAMODARAN

 NRIC No
 G7326040Q

 Date Of Birth
 10/03/1977

 Occupation
 OUTDOOR

 Date Of Driving Pass
 12/03/2010

Driving Experience 9 YEARS AND 4 MONTHS

Gender MALI

Mobile Number (LOCAL) +65-90514028

Fax Number Contact Number

EMail Address NOEMAIL

Page 1 of 19

Address

N/A

Postcode

Was driver an employee of the Insured's Company YES

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

8

General Information of the Accident

Type Of Accident

COLLISION - CROSS JUNCTION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

.

Was any other material or property damaged?

I have been approached by unknown person(s)

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver)

4

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

JURONG WEST NPC

Police Station Address

ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT T/20190809/2109

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJF1220A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

TAY HUEY GUANG

NRIC/Passport Number

\$72147211

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 19

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report sorrectly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
  the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my dalms;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

SAR Maring

Pelicyholder's Signature Date & Time: 1001.4

Driver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

I AM AWARED THAT MY ILISURER MAY HAVE A 14 DAYS TRIEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

#### Sketch Plan Pg. 2

	0.00	to attachi	and
	in 64 EA	NO WHITEM	rent.
CONTROL CINCUINACTAN	OF THE ACCIDEN		
SCRIBE CIRCUMSTAN			
Refer to P	olice Report	7/20190809	2109
			Claim own policy
			☐ Claim third party
			Claim OD / TP at other works hop      For record purpose
			Policy No. A 29630963MEC
C ADATION	cartlandair nea torre le po-	an recourt	Insurer TM SI Gy Ven No. Y PSR 90k
CLARATION	articulars are true in ev	ery respect	1100
CLARATION AND THE STREET OF STREET			
Ve declare the foregoing of		3	
(# Engine	0	3.4	3
* Engine		B.y.	Benefine Centre Restandi's Senature
(# Engine	Driver's Sign		Reporting Centre Personnel's Signature

Cerra	7 1 7	+ 1+ 1	9 B
====	1		177
NO SJE 1220A	1		25
220A	i i		International Rd
	1 -	P	2
FITST LOK Yange Ed			EIRZH FOR YOU
Long		Tours De	
		, ,	4
VIAN TREK BYE.	1		3
		1	terr
			international Rd
		1	705
		1	E
		100	

#### POLICE REPORT Pg. 1





Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999 1 of 3 Report No. T/20190809/2109

#### REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/08/2019 18:22		Made:	Vide Report No.:	Station Diary No.: 85	
Informa	nt's Partic	ulars			
Name of Informant: ULAGANATHAN DHAMODARAN			Address: C/O JNR MARINE ENGINEERING PTE LTD SINGAPORE		
ID Type / ID No.: FIN NO / G7326040Q			Contact No.: Home/Office:	Mobile: 90514028	
Nationality: INDIAN			Email:		
Sex: Male	Age: 42	Date of Birth: 10/03/1977	Type of Informant: Driver		
Race: Indian			Language Institution / School Na English		
Occupation: DRIVER			Driving Licence Information: Class: 3 Date of Expiry: 11/03/20		

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 09/08/2019 11:30	Type of Location X-Junction	
Location: Junction of R INTERNATIO KIAN TECK A Weather:		Road Surface:		Road Speed Limit:	
Clear		Dry		7,000	
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: No Traffic	
Type of Collis	fam.			Anyone conveyed by	

Details of V	ehicle Invo	lved		No. of Contract of		
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenge
SJF1220A	Car	TOYOTA		Black	Slightly Damaged	1
YP4890R	Lorry	MITSUBISHI		White	Slightly Damaged	0

Details of Person Involved					
Any Pedestrian Involved: No					
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA				

#### POLICE REPORT Pg. 2





Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999 2 of 3 Report No. T/20190609/2109

CONTINUATION OF REPORT

Driver	WHERE SHEET STATE OF			SAU.		SHEET PROPERTY.
Name	TAY HUEY GUANG			ID No		S7214721I
Related Vehicle	SJF1220A (Car)		Conta	ct No.	90689100	
Hospital/Clinic	NIL			Class Drivin Licens Expiry	g ce &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL			
No. of Days granted Medical Leave NIL		NIL	Degree of Injury   NIL			
Driver			TR. 3005(1)		510	THE REAL PROPERTY.
Name	ULAGANATHAN DH	AMODARAN	4	ID No		G7326040Q
Related Vehicle	YP4890R (Lorry)			Conta	ct No.	90514028
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g ce &	Class: 3 Date of Expiry: 11/03/2020
Date Treatment	NIL		Date Disch	narge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of			

#### Brief Details.

On 9/8/2019 at about 1130hrs, I was driving my company lorry (YP4890R) along the left lane of the 20 lane road of Kian Teck Avenue towards International Road. As I was approaching the X-junction of Kian Teck Avenue and International Road, I stopped my lorry at the stop line and observed the oncoming traffic. I then observed that there were no vehicles. As such, I proceeded straight to First Lok Yang Road. Suddenly there was a black Toyota car (SJF1220A) coming from the left (International Road towards Corporation Road). I then applied the brakes but could not stop in time. As such, the front left side of the lorry had collided with the left portion of the car. We then alighted from our vehicles and subsequently, ambulance and traffic police arrived. Nobody was conveyed to hospital. No visible injuries. The front left portion of my lorry was damaged. The front and rear right passenger doors were dented due to the collision. No in-vehicle cameras inside my company lorry and the other car.

#### POLICE REPORT Pg. 3





Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SIN 3 of 3 Report No. T/20190809/2109

700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999

CONTINUATION OF REPORT

#### Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report  J / Sgt 3 MUHAMMAD FADHIL KAMRODEN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 09/08/2019 18:22
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NG BEIFENG Contact No.: 65476415	Classification Of Case:
uthentication Stamp	

Claim Reference:

Assessment number: YP4890R-OD MSIG

Version: 1810

Date calculated: 20/08/2019 4:21 PM

Full Report

Registration: YP4890R

Printed: 20/08/2019 4:21 PM

#### **Summary Information**

Claim

Location:

Singapore (SG)

Work Provider:

MSIG Insurance

(Singapore) Pte Ltd

Printed by:

SNG AH TEE Claim Reference:

Estimated Repair Time: Actual Repair Days:

Currency:

Date of Incident:

SGD 09/08/19

Hire Car Start:

Hire Car End:

Vehicle

Manufacturer:

Model:

Sub Model:

Model Sheet Number:

Vehicle Details

Registration:

VIN number:

Odometer: Model Specs

FROM 09/2016 SINGLE CAB

**FUSO** 

CANTER (FB/FE/FG)

BASE MODEL 32 87 01

YP4890R

FEB21EA20954

AIR CONDITIONING LOADING PLATFORM

3.0 LTR 96 KW PREPARE OFF VEHICLE **GWR 3.5T** 

BASECOAT CLEAR

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey beforefatter spray painting
- To display damaged part(x) during resurvey.
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis. . No illegal modification(s) is allowed
- \* Supplementary Item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Taylor 97495749

Claim Reference:

**Full Report** 

Assessment number: YP4890R-OD MSIG

Registration: YP4890R

Version: 1810

Printed: 20/08/2019 4:21 PM

Date calculated: 20/08/2019 4:21 PM


#### **Vehicle Condition**

#### Vehicle Status

Pre-Accident Damage: Date of Inspection:

#### Damage Areas

All Underbody



#### Labour

	Time Base 10 WU/h	Price = 50.	00 SGD/h
Code	Description	wu	Price SGD
NO NUMBER	RENEW FRONT BUMPER INCLUDES: R + R NECESSARY ATTACHED PARTS	11.0	55.00
NO NUMBER	R + R RADIATOR GRILLE	12.0	60.00
NO NUMBER	R + R L/F REPEATER LAMP	4.0	20.00
NO NUMBER	R + R L/F CORNER PANEL	4.0	20.00
NO NUMBER	RENEW FRONT MANUFACTURER BADGE	3.0	15.00
NO NUMBER	R + R L/F STEP	6.0	30.00
NO NUMBER	RENEW L/F DOOR INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	69.0	345.00
NO NUMBER	R + R FAN BLADE	1.0	5.00
NO NUMBER	R + R FAN COWL	3.0	15.00
NO NUMBER	DETACH + REFIT RADIATOR	4.0	20.00
NO NUMBER	R + R CONDENSER	8.0	40.00
NO NUMBER	DRAIN + REFILL AIR CONDITIONING	5.0	25.00

Claim Reference:

Full Report

Assessment number: YP4890R-OD MSIG

Registration: YP4890R Printed: 20/08/2019 4:21 PM

Version: 1810

Date calculated: 20/08/2019 4:21 PM

Code	Description	v	/U	Price SGD
NO NUMBER	ADJUST HEADLAMPS	2	.0	10.00
2227	LEFT A-PILLAR REPAIR	30.0	*	150.00
5095	L/F S-ABS BRKT REPAIR	5.0	*	25.00
5096	R/F S-ABS BRKT REPAIR	5.0	*	25.00
6005	L/BRACKET REPAIR	10.0	)*	50.00
6006	R/BRACKET REPAIR	10.0	)*	50.00
1004	L/F HEADLAMP PANEL	15.0	)*	75.00
	Labour Cost	Hrs W	/U	
	Panel / Mechanical Labour	20.70 207	.0	1,035.00
	Total of Labour			1,035.00

_				4.
D	-	٠	-	۰

Paint Work	CYCTEM ATT	Time Beels 10WII/h
Paint Work	SYSTEM AZT	Time Basis 10WU/h
Code	Description - BASECOAT CLEAR	WU Price SGD
	FRONT BUMPER NEW PART PAINTING	11.0
	L/F CORNER PANEL NEW PART PAINTING	8.0
	LEFT FRONT DOOR NEW PART PAINTING	15.0
	L/F BUMPER CORNER NEW PART PAINT K1R	4.0
	R/F BUMPER CORNER NEW PART PAINT K1R	4.0
	FRONT GRILLE NEW PART PAINT K1R	8.0
	L/F STEP NEW PART PAINT K1R	4.0
	LEFT A-PILLAR REPAIR PAINTING >50%	9.0
	L/F S-ABS BRKT SURFACE PAINT	4.0
	R/F S-ABS BRKT SURFACE PAINT	4.0
	L/BRACKET SURFACE PAINT	4.0
	R/BRACKET SURFACE PAINT	4.0
	L/F HEADLAMP PANEL	15.0*

#### Paint Material Per Part

Code	Description	Price SGD
0281	FRONT BUMPER NEW PART PAINTING	24.77
0887	L/F CORNER PANEL NEW PART PAINTING	9.29
1481	LEFT FRONT DOOR NEW PART PAINTING	39.22
0289	L/F BUMPER CORNER NEW PART PAINT K1R	5.90
0290	R/F BUMPER CORNER NEW PART PAINT K1R	5.90
0410	FRONT GRILLE NEW PART PAINT K1R	33.46
2205	L/F STEP NEW PART PAINT K1R	5.90
2227	LEFT A-PILLAR REPAIR PAINTING >50%	1.58

Claim Reference:

Full Report

Assessment number: YP4890R-OD MSIG

Registration: YP4890R Printed: 20/08/2019 4:21 PM

Version: 1810

Date calculated: 20/08/2019 4:21 PM

#### Paint Material Per Part

Code	Description	Price SGD
5095	L/F S-ABS BRKT SURFACE PAINT	1.99
5096	R/F S-ABS BRKT SURFACE PAINT	1.99
6005	L/BRACKET SURFACE PAINT	0.75
6006	R/BRACKET SURFACE PAINT	0.75

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h			
Time Paint	-		94.0	
Preparation Main Work Metal		2.50	25.0	125.00
Preparation Comp. Work Plastic		0.50	5.0	25.00
Total	10 WU/h	12.40	124.0	620.00

Material Cost - Paint	Price SGD
New Part Painting	73.28
New Part Painting - Plastic K1R	51.16
Repair Painting	1.58
Surface-/Blend Paint	5.48
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	169.10

#### **Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
	1		CONTINUES CONTIN	
0257	FRONT NUMBER PLATE	NO NUMBER		64/ 0.00
0281	FRONT BUMPER	MC978515		6/ 550.00
0289	L/F BUMPER CORNER	MK617983		M/5 200.00
0290	R/F BUMPER CORNER	MK617989		× 5/1 200.00
0410	FRONT GRILLE	MC975208		cut 600.00
0435	L/BADGE	MK676977		N4 0.00
0561	LEFT HEADLAMP ASSY	MK580525		Cre 300.00
0677	L/F INDICATOR	MX915952		Cm 160.00
0717	L/POSITION LAMP	MK580529		0 100.00
0887	L/F CORNER PANEL	MC976410		di 260.00
1481	LEFT FRONT DOOR	MK702223		let 1,050.00
1577	L/INN DOOR LOCK	MK434983		Q 100 00 V
2205	L/F STEP	MK677506		300.00
4466	CONDENSER CPL	ML272230		bt 500.00

Claim Reference:

Full Report

Assessment number: YP4890R-OD MSIG

Registration: YP4890R Printed: 20/08/2019 4:21 PM

Version: 1810

Date calculated: 20/08/2019 4:21 PM

Code	Description	Part Number	Supplier	Price SGD
7767	RADIATOR SHROUD	ML241486	Chooping troops	n/1 × 240.00
7793	COOLING FAN	ML242320		nn × 120.00
1001	FRT GRILLE CLIP	GRILLE CLIP		28 14- 60.00
1002	L/F BUMPER	BRACKET		ht 115.00
1003	R/F BUMPER	BRACKET		ии. У 115.00
1006	L/F HEADLAMP LOWER	SEAL		22 19 9.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			5,069.00
u: Used parts	Addition(+10.00%)	)		506.90
	Total			5,575.90

EXLIAS		
Code	Description	Price SGD
1000	FRT NUMBER PLATE NUMBER PLATE	H_15.00*

	SGD	SGD
Parts	5,069.00	
Addition(+10.00%)	506.90	
Total Parts		5,575.90
Labour Time Base 10 WU/h		
Total 207.0 WU X 50.00 SGD/h	1015 1,035.00	
Total of Labour	19:2	1,035.00
Total Of Extras		15.00
Paint Work Time Base 10 WU/h		
Labour Cost 124.0 WU X 50.00 SGD/h	620.00	
Material Cost	169.10	
Total Paint Including Material		789.10
Repair Cost Excludes GST		7,415.00
GST (+7.0%)		519.05
Repair Cost Included GST		7,934.05

7930-90

Claim Reference:

Assessment number: YP4890R-OD MSIG

Version: 1810

Date calculated: 20/08/2019 4:21 PM

Full Report Registration: YP4890R

Printed: 20/08/2019 4:21 PM

#### Comments

\* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS ) - WU PARTIAL INCL IN OTHER POSITIONS

# REPAIR DETAILS Reference Part Source: (Last Synchronised: 26 Dec 2019) Parts: N/A MITSUBISHI CANTER 3.0 D FEB21 (M) (Model not available in database) Labour: Repairer's (Price-denominated Standard List) Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/YP4890R/26/12/2019 16:13 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF

ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

No.	Qty Par	rt No.	Particulars		%Disc	%Depr		Amount
1	1		*SCUFF PLATE LH		0.00	0.00	de	*60.00F ~
2	1		*FRT DOOR AIR VENT LH		0.00	0.00	qe	*25.00F
3	1		*CORNER PANEL TOP COVER LH		0.00	0.00	MIS	*20.00F ~
F=Fn	nchise part.							
				Sub Total (S\$)				105.00
				+ Margin on L,N Items 10.00% (S\$)				10,50
				Total Parts (S\$)				115,50

Sng Ah Tee Motor & Panel Service Pte Ltd/YP4890R/26/12/2019 16:13. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

# **LKK Auto Consultants** #01-25 Paya Ubi Industrial Park, 51 **Ubi Avenue 1** 408933

**Insurer Reference:** 

**Full Report** Registration: YP4890R

Repairer Reference: YP4890R-OD MSIG Date calculated: 16/01/2020 11:13 AM

Printed: 16/01/2020 11:13 AM

**Summary Information** 

Claim

Location:

Singapore (SG)

Work Provider:

MSIG Insurance

(Singapore) Pte Ltd

Printed by:

KK LAU

Currency: Date of Incident: SGD 09/08/19

Claim Reference:

Estimated Repair Time: Actual Repair Days:

Hire Car Start:

Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

**FUSO** 

Model:

CANTER (FB/FE/FG)

Sub Model:

BASE MODEL 32 87 01

Model Sheet Number: Registration:

YP4890R

VIN number:

FEB21EA20954

Odometer:

**Model Specs** 

FROM 09/2016

AIR CONDITIONING

3.0 LTR 96 KW

**GWR 3.5T** 

SINGLE CAB

LOADING PLATFORM

PREPARE OFF VEHICLE

BASECOAT CLEAR

**Vehicle Condition** 

**Vehicle Status** 

Pre-Accident Damage: Date of Inspection:

**Damage Areas** 

All

Underbody



Labour	Time Base 10 WU/h	Pri	ce = 50.	00 SGD/h
Code	Description		wu	Price SGD
NO NUMBER	RENEW FRONT BUMPER		11.0	55.00
	INCLUDES: R + R NECESSARY ATTACHED PARTS			
NO NUMBER	R + R RADIATOR GRILLE		12.0	60.00
NO NUMBER	R + R L/F REPEATER LAMP		4.0	20.00
NO NUMBER	R + R L/F CORNER PANEL		4.0	20.00
NO NUMBER	RENEW FRONT MANUFACTURER BADGE		3.0	15.00
NO NUMBER	R + R L/F STEP		6.0	30.00
NO NUMBER	RENEW L/F DOOR		69.0	345.00
VIEW CERTIFICATION	INCLUDES: R + R DOOR,			
	CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
NO NUMBER	DETACH + REFIT RADIATOR		4.0	20.00
NO NUMBER	R + R CONDENSER		8.0	40.00
NO NUMBER	DRAIN + REFILL AIR CONDITIONING		5.0	25.00
NO NUMBER	ADJUST HEADLAMPS		2.0	10.00
2227	LEFT A-PILLAR REPAIR		30.0*	150.00
5095	L/F S-ABS BRKT REPAIR		5.0*	25.00
5096	R/F S-ABS BRKT REPAIR		5.0*	25.00
6005	L/BRACKET REPAIR		10.0*	50.00
6006	R/BRACKET REPAIR		10.0*	50.00
1004	L/F HEADLAMP PANEL		15.0*	75.00
कार्यक्षण (१)	TAN TOTAL MANUTURE SEE	95	2000	
	Labour Cost	Hrs	WU	
	Panel / Mechanical Labour	20.30	203.0	1,015.00
	Total of Labour			1,015.00
Paint				
Paint Work	SYSTEM AZT	Tir	ne Basis	10 WU/h
Code	Description - BASECOAT CLEAR		wu	Price SGD
	FRONT BUMPER NEW PART PAINTING		11.0	
	L/F CORNER PANEL NEW PART PAINTING		8.0	
	LEFT FRONT DOOR NEW PART PAINTING		15.0	
	L/F BUMPER CORNER NEW PART PAINT K1R		4.0	
	R/F BUMPER CORNER NEW PART PAINT K1R		4.0	
	FRONT GRILLE NEW PART PAINT K1R		8.0	
	L/F STEP NEW PART PAINT K1R		4.0	
			4.0	
	LEFT A-PILLAR REPAIR PAINTING >50%		9.0	
	LEFT A-PILLAR REPAIR PAINTING >50% L/F S-ABS BRKT SURFACE PAINT			
	L/F S-ABS BRKT SURFACE PAINT		9.0	
	L/F S-ABS BRKT SURFACE PAINT R/F S-ABS BRKT SURFACE PAINT		9.0 4.0	
	L/F S-ABS BRKT SURFACE PAINT R/F S-ABS BRKT SURFACE PAINT L/BRACKET SURFACE PAINT		9.0 4.0 4.0	1107 (* 10
	L/F S-ABS BRKT SURFACE PAINT R/F S-ABS BRKT SURFACE PAINT		9.0 4.0 4.0 4.0	Late of
Paint Mater	L/F S-ABS BRKT SURFACE PAINT R/F S-ABS BRKT SURFACE PAINT L/BRACKET SURFACE PAINT R/BRACKET SURFACE PAINT L/F HEADLAMP PANEL		9.0 4.0 4.0 4.0 4.0	100 S 100
Paint Mater Code	L/F S-ABS BRKT SURFACE PAINT R/F S-ABS BRKT SURFACE PAINT L/BRACKET SURFACE PAINT R/BRACKET SURFACE PAINT L/F HEADLAMP PANEL		9.0 4.0 4.0 4.0 4.0	Price SGD
Code	L/F S-ABS BRKT SURFACE PAINT R/F S-ABS BRKT SURFACE PAINT L/BRACKET SURFACE PAINT R/BRACKET SURFACE PAINT L/F HEADLAMP PANEL  ial Per Part		9.0 4.0 4.0 4.0 4.0	Price SGD
	L/F S-ABS BRKT SURFACE PAINT R/F S-ABS BRKT SURFACE PAINT L/BRACKET SURFACE PAINT R/BRACKET SURFACE PAINT L/F HEADLAMP PANEL  ial Per Part  Description		9.0 4.0 4.0 4.0 4.0	

#### Paint Material Per Part

Code	Description	Price SGD
0289	L/F BUMPER CORNER NEW PART PAINT K1R	5.90
0290	R/F BUMPER CORNER NEW PART PAINT K1R	5.90
0410	FRONT GRILLE NEW PART PAINT K1R	33.46
2205	L/F STEP NEW PART PAINT K1R	5.90
2227	LEFT A-PILLAR REPAIR PAINTING >50%	1.58
5095	L/F S-ABS BRKT SURFACE PAINT	1.99
5096	R/F S-ABS BRKT SURFACE PAINT	1.99
6005	L/BRACKET SURFACE PAINT	0.75
6006	R/BRACKET SURFACE PAINT	0.75

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h			
Time Paint			94.0	
Preparation Main Work Metal		2.50	25.0	125.00
Preparation Comp. Work Plastic		0.50	5.0	25.00
Total	10 WU/h	12.40	124.0	620.00

Material Cost - Paint	Price SGD
New Part Painting	73.28
New Part Painting - Plastic K1R	51.16
Repair Painting	1.58
Surface-/Blend Paint	5.48
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	169.10

#### **Spare Parts**

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
4466	CONDENSER CPL	ML272230		500.00
1009	CRN PNL TOP CVR (LH)	LH		20.00
0281	FRONT BUMPER	MC978515		550.00
0410	FRONT GRILLE	MC975208		600.00
0257	FRONT NUMBER PLATE	NO NUMBER		0.00
1008	FRT DOOR AIR VENT	(LH)		25.00
1001	FRT GRILLE CLIP	GRILLE CLIP		28.00
0435	L/BADGE	MK676977		0.00
1002	L/F BUMPER BRKT	brkt		115.00
0289	L/F BUMPER CORNER	MK617983		200.00
0887	L/F CORNER PANEL	MC976410		260.00
1006	L/F HEADLAMP LOWER	SEAL		22.00
0677	L/F INDICATOR	MX915952		160.00
2205	L/F STEP	MK677506		220.00
0717	L/POSITION LAMP	MK580529		100.00
1481	LEFT FRONT DOOR	MK702223		1,050.00
0561	LEFT HEADLAMP ASSY	MK580525		280.00
1007	SCUFF PLATE	(LH)		60.00
f: OEM Parts	Savings			0.00

f: OEM Parts n: Non-OEM Parts u: Used parts

Audatex System Using Manufacturer Times

Page 3 of 4

PRINT DATE 16/01/2020

	Subtotal Addition(+15.00%)		4,190.00 628.50
	Total		4,818.50
Extras			
Code	Description		Price SGD
1010	TO REFILL AIRCON GAS		60.00*
1011	FRT NUMBER PLATE NUMBER PLATE Total Extras		15.00* 75.00
Final Cal	culation		
		SGD	SGD
Parts		4,190.00	
Addition( Total Parts	(+15.00%) s	628.50	4,818.50
	ime Base 10 WU/h 03.0 WU X 50.00 SGD/h	1,015.00	
Total of La		1,013.00	1,015.00
Total Of Ex	xtras		75.00
	k Time Base 10 WU/h Cost 124.0 WU X 50.00 SGD/h	620.00 169.10	
	t Including Material	103:10	789.10
_	st Excludes GST		6,697.60
GST (+7 Repair Cos	st Included GST		468.83 7,166.43
	s (Excludes GST)	1 220 52	
Total Of De	ost Discount (+20.00%) eductions (Excludes GST)	-1,339.52	-1,339.52
Grand Tota	al Excludes GST		5,358.08
GST (+7	(.0%)		375.07
	al Included GST		5,733.15

#### Comments

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

#### **Assessment Note**

No assessment notes entered.

Insurer Reference:

Repairer Reference: YP4890R-OD MSIG Date calculated: 26/12/2019 3:41 PM

**Full Report** Registration: YP4890R Printed: 26/12/2019 3:41 PM

#### Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

MSIG Insurance

(Singapore) Pte Ltd

Printed by:

Claim Reference:

SNG AH TEE

Currency: Date of Incident: SGD 09/08/19

Estimated Repair Time:

Actual Repair Days:

Hire Car Start:

Hire Car End:

#### Vehicle Details

Vehicle

Manufacturer:

**FUSO** 

Model:

CANTER (FB/FE/FG)

Sub Model:

BASE MODEL 32 87 01

Model Sheet Number: Registration:

YP4890R

VIN number:

FEB21EA20954

Odometer:

**Model Specs** 

FROM 09/2016

AIR CONDITIONING

3.0 LTR 96 KW

**GWR 3.5T** 

SINGLE CAB

LOADING PLATFORM

PREPARE OFF VEHICLE

BASECOAT CLEAR

#### **Vehicle Condition**


#### **Vehicle Status**

Pre-Accident Damage: Date of Inspection:

#### **Damage Areas**

All

Underbody



#### Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

Paint Paint Work	SYSTEM AZT	Ti	me Basis	10 WU/h
Paint				
	Total of Labour			1,015.00
			inamo mo	
	Labour Cost Panel / Mechanical Labour	Hrs 20.30	WU 203.0	1,015.00
1004	L/F HEADLAMP PANEL		15.0*	75.00
6006	R/BRACKET REPAIR		10.0*	50.00
6005	L/BRACKET REPAIR		10.0*	50.00
5096	R/F S-ABS BRKT REPAIR		5.0*	25.00
5095	L/F S-ABS BRKT REPAIR		5.0*	25.00
2227	LEFT A-PILLAR REPAIR		30.0*	150.00
NO NUMBER	ADJUST HEADLAMPS		2.0	10.00
NO NUMBER	DRAIN + REFILL AIR CONDITIONING		5.0	25.00
NO NUMBER	R + R CONDENSER		8.0	40.00
NO NUMBER	NECESSARY DETACH + REFIT RADIATOR		4.0	20.00
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF			
NO NUMBER	RENEW L/F DOOR		69.0	345.00
NO NUMBER	R + R L/F STEP		6.0	30.00
NO NUMBER	RENEW FRONT MANUFACTURER BADGE		3.0	15.00
NO NUMBER	R + R L/F CORNER PANEL		4.0	20.00
NO NUMBER	R + R L/F REPEATER LAMP		4.0	20.00
NO NUMBER	INCLUDES: R + R NECESSARY ATTACHED PARTS R + R RADIATOR GRILLE		12.0	60.00
NO NUMBER	RENEW FRONT BUMPER		11.0	55.00
Code	Description		wu	Price SGD

Paint			
Paint Work	SYSTEM AZT	Time Basis 10	WU/h
Code	Description - BASECOAT CLEAR	WU Pri	ce SGD
	FRONT BUMPER NEW PART PAINTING	11.0	
	L/F CORNER PANEL NEW PART PAINTING	8.0	
	LEFT FRONT DOOR NEW PART PAINTING	15.0	
	L/F BUMPER CORNER NEW PART PAINT K1R	4.0	
	R/F BUMPER CORNER NEW PART PAINT K1R	4.0	
	FRONT GRILLE NEW PART PAINT K1R	8.0	
	L/F STEP NEW PART PAINT K1R	4.0	
	LEFT A-PILLAR REPAIR PAINTING >50%	9.0	
	L/F S-ABS BRKT SURFACE PAINT	4.0	
	R/F S-ABS BRKT SURFACE PAINT	4.0	
	L/BRACKET SURFACE PAINT	4.0	
	R/BRACKET SURFACE PAINT	4.0	
	L/E HEADLAMP PANEL	15.0*	

# Paint Material Per Part

Code	Description	Price SGD
0281	FRONT BUMPER NEW PART PAINTING	24.77
0887	L/F CORNER PANEL NEW PART PAINTING	9.29
1481	LEFT FRONT DOOR NEW PART PAINTING	39.22
0289	L/F BUMPER CORNER NEW PART PAINT K1R	5.90
0290	R/F BUMPER CORNER NEW PART PAINT K1R	5.90
0410	FRONT GRILLE NEW PART PAINT K1R	33.46

#### **Paint Material Per Part**

Code	Description	Price SGD
2205	L/F STEP NEW PART PAINT K1R	5.90
2227	LEFT A-PILLAR REPAIR PAINTING >50%	1.58
5095	L/F S-ABS BRKT SURFACE PAINT	1.99
5096	R/F S-ABS BRKT SURFACE PAINT	1.99
6005	L/BRACKET SURFACE PAINT	0.75
6006	R/BRACKET SURFACE PAINT	0.75

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h			
Time Paint	10		94.0	
Preparation Main Work Metal		2.50	25.0	125.00
Preparation Comp. Work Plastic		0.50	5.0	25.00
Total	10 WU/h	12.40	124.0	620.00

Material Cost - Paint	Price SGD
New Part Painting	73.28
New Part Painting - Plastic K1R	51.16
Repair Painting	1.58
Surface-/Blend Paint	5.48
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	169.10

#### Spare Parts

opure r ures				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0257	FRONT NUMBER PLATE	NO NUMBER		0.00
0281	FRONT BUMPER	MC978515		550.00
0289	L/F BUMPER CORNER	MK617983		200.00
0410	FRONT GRILLE	MC975208		600.00
0435	L/BADGE	MK676977		0.00
0561	LEFT HEADLAMP ASSY	MK580525		280.00
0677	L/F INDICATOR	MX915952		160.00
0717	L/POSITION LAMP	MK580529		100.00
0887	L/F CORNER PANEL	MC976410		260.00
1481	LEFT FRONT DOOR	MK702223		1,050.00
2205	L/F STEP	MK677506		220.00
4466	CONDENSER CPL	ML272230		500.00
1001	FRT GRILLE CLIP	GRILLE CLIP		28.00
1002	L/F BUMPER BRKT	brkt		115.00
1006	L/F HEADLAMP LOWER	SEAL		22.00
1007	SCUFF PLATE	(LH)		de/ 60.00
1008	FRT DOOR AIR VENT	(LH)		de 25.00
1009	CRN PNL TOP CVR (LH)	LH		Mis 20.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			4,190.00
u: Used parts	Addition(+15.00%)	)		628.50

Extras		D.1 CCD
Code	Description	Price SGD
1000	FRT NUMBER PLATE NUMBER PLATE	15.00*
1010	TO REFILL AIRCON GAS	60.00* AL. 75.00
	Total Extras	75.00

	SGD	SGD
Parts	4,190.00	
Addition(+15.00%)	628.50	
Total Parts		4,818.50
Labour Time Base 10 WU/h		
Total 203.0 WU X 50.00 SGD/h	1,015.00	
Total of Labour		1,015.00
Total Of Extras		75.00
Paint Work Time Base 10 WU/h		
Labour Cost 124.0 WU X 50.00 SGD/h	620.00	
Material Cost	169.10	100000000
Total Paint Including Material		789.10
Repair Cost Excludes GST		6,697.60
GST (+7.0%)		468.83
Repair Cost Included GST		7,166.43
Deductions (Excludes GST)		
Repair Cost Discount (+20.00%)	-1,339.52	
Total Of Deductions (Excludes GST)		-1,339.52
Grand Total Excludes GST		5,358.08
GST (+7.0%)		375.07
Grand Total Included GST		5,733.15

1/595350.

#### Comments

\* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

#### **Assessment Note**

No assessment notes entered.

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Ad	§ Submitted	Ins Auth'ed	Status	
Main	20 Aug 2019 16:17 Sendback Est	20 Aug 2019 16:30 5\$7,415.00	22 Aug 2019 16:27 Edit Adj Rpt	S\$5,350.00 Edit Estimates	10.0	5,350.00 View Rpt		Pending for Report Cancel Ca	
Supp #1	26 Dec 2019 16:11	26 Dec 2019 16:13 \$\$115.50	26 Dec 2019 16:13				(Combined)	Uncombin	with Main e Suppl.
	Main	Refer	ence	Claim De	tails		Documents	٦.	Show All
CLAIM SU	BFOLDER DETA								
Insured:	**************************************	ENGINEERING F	TE. LTD., Co. R	eg. No.: 2014124	27H				
Vehicle Reg No.:	YP4890R			Date of		A STATE OF THE PARTY OF THE PAR	and 24 Days From LT	A Reg Date	(Man Yr)]
Claim Type	OD / 60284	OD / 602846 Policy/Cover 29030963 (Comprehensive) Coverage: 16/11/2018 - 15/11/2019							
	F 45 F 1			Excess:		5\$700.00	10 630453 Dinner	Tal: 6360	6103
Repairer: Handling			SE PO MEN				1-18, 628457 Pioneer		6103
Insurer	MSIG Insura	nce (Singapore)	Pte. Ltd. (HQ) -	Tel: +65 6827 78	88	[Handled by K	wok Woon Choo -	5643 1330]	
Adjuster:	21/09/2019		(HQ) - Tel: 6256	-3561 [Handle	d by M	OHD TAUFIN	(H BIN HAMID) [	Final Rpt	due
Driver/Cust dian:	ULAGANATHA	N DHAMODARAN (	42 / Male) , NRI	C: G7326040Q,	Tel: +	6590514028	Email: NOEMAIL		
Adj Asg. Remarks:	Car in on 23/0	08/2019 1PM to 4P	M, please survey a	and revert. Please	contac	ct us ASAP if y	ou cannot attend the	s assignmen	t.
ASSOCIAT	TED MAIL RECE	IVED					View All	Compos	e Case Mail
<ul> <li>M5IG_5</li> </ul>	G (21/01/2020): A	Alert - Adj Manda	ste Approved (St	6697.60) - YP4	890R	- Claim Hand	ller: Kwok Woon Ch ller: Kwok Woon Ch ller: Kwok Woon Ch	1	
ALL ASSO	CIATED TASKS	3				/iew All Se	arch Tasks Create	New Task	Complete
Due Dat	e Priority	Type Task Gr	oup Subject	Handler	Assign	ned By	Completed On	Created Or	1 Done

#### Claim Documents

# YP4890R (602846) OD Aug 9 2019 11:00AM [JNR MARINE ENGINEERING PTE. LTD.] Sng Ah Tee Motor & Panel Service Pte Ltd

Ass	essment Reports		1 per	page 🔻	8
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
i	20/08/19 16:30	Repairer Estimates	0	Load HTM	
2	26/12/19 16:13	Repairer Estimates Suppl. #1	0	Load HTM	Land I
No.	Finalized On 26/08/19 09:15	LKK Auto Consultants Pte Ltd (HQ)	0	Thumbnall Load HTM	Print
2	16/01/20 11:35	Adjuster Immediate Advice Adjuster Immediate Advice	ő	Load HTM	
3	26/02/20 10:48	Adjuster Immediate Advice	ō	Load HTM	
Pho	otos/Images		3 per	page V	<b>V</b>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	10/01/20 11:19	Odometer Reading	0	Load JPG	$\overline{\mathbf{A}}$
2	10/01/20 11:19	General View	0	Load JPG	1
3	10/01/20 11:19	General View	0	Load 3PG	[2]
4	10/01/20 11:19	General View	0	Load JPG	<b>V</b>
5	10/01/20 11:19	General View	0	Load JPG	100
6	10/01/20 11:19	General View	0	Load JPG	V
7	10/01/20 11:19	General View	0	Load JPG	Z
8	10/01/20 11:19	General View	0	Load JPG	V
9	10/01/20 11:19	General View	0	Load JPG	1
10	10/01/20 11:19	General View	0	Load JPG	Z
11	10/01/20 11:19	General View	0	Load JPG	V
12	10/01/20 11:19	General View	0	Load JPG	M
13	10/01/20 11:19	General View	0	Load JPG	V
14	10/01/20 11:19	General View	0	Load JPG	1
15	10/01/20 11:19	General View	0	Load JPG	V
16	10/01/20 11:19	General View	0	Load JPG	V
17	10/01/20 11:20	General View	0	Load JPG	V
18	10/01/20 11:20	General View	0	Load JPG	V
19	10/01/20 11:20	General View	0	Load JPG	1
20	10/01/20 11:20	General View	0	Load JPG	1
21	10/01/20 11:20	General View	0	Load JPG	12
22	10/01/20 11:20	General View	0	Load JPG	V
23	10/01/20 11:20	General View	0	Load JPG	V
24	10/01/20 11:20	General View	0	Load JPG	V
25	10/01/20 11:20	General View	0	Load JPG	V
26	10/01/20 11:20	General View	0	Load 3PG	V
27	10/01/20 11:20	General View	0	Load 3PG	V
28	10/01/20 11:20	General View	0	Load JPG	V
29	10/01/20 11:20	General View	0	Load JPG	120
30	10/01/20 11:20	General View	0	Load JPG	V
31	10/01/20 11:20	General View	0	Load JPG	V

Page 2 of 3

Asse	ssment Reports		1 per pag	ye v	8
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	1	humbnail	Print
32	10/01/20 11:20	General View	0	Load 3PG	V
33	10/01/20 11:20	General View	0	Load JPG	V
34	10/01/20 11:20	General View	0	Load JPG	V
35	10/01/20 11:20	General View	0	Load JPG	V
36	10/01/20 11:20	General View	0	Load JPG	3
37	10/01/20 11:20	General View	0	Load JPG	V
38	10/01/20 11:20	General View	0	Load 3PG	V
39	10/01/20 11:20	General View	0	Load JPG	V
40	10/01/20 11:20	General View	0	Load JPG	V
41	10/01/20 11:20	General View	0	Load JPG	V
42	10/01/20 11:20	General View	0	Load JPG	V
43	10/01/20 11:20	General View	0	Load JPG	8
	The state of the s	Nepries (Comp.	0	Load JPG	3
44	10/01/20 11:20	General View		A-3/14/	₩.
45	10/01/20 11:20	General View	0	Load 3PG	-
46	10/01/20 11:20	General View	0	Load JPG	Ø
47	10/01/20 11:20	General View	0	Load JPG	V
48	10/01/20 11:20	General View	0	Load JPG	V
49	10/01/20 11:20	Reinspection Photo	0	Load JPG	V
50	10/01/20 11:20	Reinspection Photo	0	Load JPG	8
51	10/01/20 11:20	Reinspection Photo	0	Load JPG	V
52	10/01/20 11:20	Reinspection Photo	0	Load JPG	V
53	10/01/20 11:20	Reinspection Photo	0	Load JPG	1
54	10/01/20 11:20	Reinspection Photo	0	Load JPG	V
55	10/01/20 11:20	Reinspection Photo	0	Load JPG	V
56	10/01/20 11:20	Reinspection Photo	0	Load JPG	V
57	10/01/20 11:20	Reinspection Photo	0	Load JPG	V
-	T-100-100-100-100-100-100-100-100-100-10		0		V
58	10/01/20 11:20	Reinspection Photo		Load JPG	-
59	10/01/20 11:20	Reinspection Photo	0	Load JPG	V
60	10/01/20 11:20	Reinspection Photo	0	Load JPG	Z
61.	10/01/20 11:20	Reinspection Photo	0	Load JPG	V
62	10/01/20 11:20	Reinspection Photo	0	Load JPG	V
63	10/01/20 11:20	Reinspection Photo	0	Load JPG	V
64	10/01/20 11:20	Reinspection Photo	0	Load JPG	1
65	10/01/20 11:20	Reinspection Photo	0	Load JPG	V
66	10/01/20 11:21	After Repair Photo	0	Load JPG	V
67	10/01/20 11:21	After Repair Photo	0	Load JPG	Ø
68	10/01/20 11:21	After Repair Photo	0	Load JPG	V
		In the second se			-
Doc	umentation		1 per pa		100
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		humbnail	Prin
1	20/08/19 16:18	E-filed GIA report	0	Load PDF	
3	20/08/19 16:18	IC,DL,CI AUDATEX REPORT	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		humbnail	Prin
1	26/08/19 09:03	ESTIMATE	0	Load PDF	
2	16/01/20 11:03	SUPPLEMANTARY	Ö	Load PDF	
3	02/03/20 17:06	SUPPLEMENTARY2	Ö	Load PDF	

# **Linked Accident Report Documents**

View View in Browser

Page 3 of 3

Ass	essment Reports		1 per	page V	V
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnall	Print
1	04/09/19 02:18	Accident Statement	0	Load HTM	
Pho	tos/Images		3 per	page 🔽	<b>₩</b>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	13/08/19 12:11	Accident Photo	0	Load JPG	<b>V</b>
2	13/08/19 12:11	Accident Photo	0	Load JPG	V
3	13/08/19 12:11	Accident Photo	0	Load JPG	<b>W</b>
4	13/08/19 12:11	Accident Photo	0	Load 3PG	V
5	13/08/19 12:11	Accident Photo	0	Load JPG	V
6	13/08/19 12:11	Accident Photo	0	Load JPG	<b>W</b>
7	13/08/19 12:11	Accident Photo	0	Load JPG	V
8	13/08/19 12:11	Accident Photo	0	Load 3PG	V
9	13/08/19 12:11	Accident Photo	0	Load 3PG	V
10	13/08/19 12:11	Accident Photo	0	Load JPG	₩.
Doc	umentation		1 per	page 🔻	V
No	Finalized On	Sing Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	13/08/19 12:09	Sketch Plan	0	Load TIF	
2	13/08/19 12:11	POLICE REPORT	0	Load TIF	

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			Ŷ
Show Remarks To: Repairer Handling Insurer Rote: Remarks are private unless you show it to other parties.			

#### LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way, #21-01 SGX Centre 2

Our File No:

CS/MSG19014847/T1TF3E2

Singapore 068807

Date:

02/03/2020

REFERENCE

Date of Loss:

Insured/Claimant:

JNR MARINE ENGINEERING PTE. LTD.

Policy No: Nature of Claim: 29030963

Claim No: 602846

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

09/08/2019

Reg No:

**YP4890R** 

Make & Model:

MITSUBISHI CANTER, 3.0 D FEB21 (M)

Engine No:

OD

4P10C34220

Reg. Date:

16/11/2016 (Man. Year: 2016)

Chassis No:

FEB21EA20954

Colour: Engine Capacity: White 2998 cc Odometer:

38172 km

Market Value/New Car Price:

\$\$54,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable): Yes

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

195/85 R15

Rear Tyre Size:

195/85 R15 (D)

Front Left Side: Front Right Side: Bridgestone 6 mm Bridgestone 6 mm Rear Left Side: Rear Right Side: Bridgestone 6/6 mm Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,706.40	4,833.50	872.90	15.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,824.10	1,864.10	-40.00	-2.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,530.50	6,697.60	832.90	11.06
Approved Total (Overridden) (S\$)		5,350.00		
- Excess (S\$)	0.00	700.00	-700.00	
(S\$)	7,530.50	4,650.00	2,880.50	38.25
+ GST 7.00/7.00% (S\$)	527.14	325.50	201.64	38.25
Nett Amount (S\$)	8,057.64	4,975.50	3,082.14	38.25

INSPECTION

Date of Assignment:

22/08/2019 Present Location:

Sng Ah Tee Motor & Panel Service Pte Ltd

(Pioneer)

Date Inspected:

23/08/2019 Inspected At:

Sng Ah Tee Motor & Panel Service Pte Ltd

(Pioneer)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Estimated Period of Repair:

7.0 days

Adjuster Report Page 2 of 5

Adjuster: MOHD TAUFIKH BIN HAMID Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# REPAIR DETAILS

Referen	ce	
Part Source:		(Last Synchronised: 02 Mar 2020)
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted	no print-code for YP4890R)
Validity:		tes are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info	: Items/values	not in reference catalogue are prefixed with an asterisk *.

# Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*CONDENSER CPL	Bent	500.00 F	*500.00 F
2	1	NA	*COOLING FAN	Not Necessary	120.00 F	*-F
3	1	NA	*FRONT BUMPER	Bent	550.00 F	*550.00 F
4	1	NA	*FRONT GRILLE	Cut	600.00 F	*600.00 F
5	1	NA	*FRONT NUMBER PLATE	Bent	0.00 F	*-F
8	1	NA	*FRT GRILLE CLIP (WCP)	Necessary	60.00 F	*28.00 F
7	1	NA	*L/BADGE (NPA)	Necessary	0.00 F	*-F
В	1	NA	*L/F BUMPER (WCP)	Bent	115.00 F	*115.00 F
9	1	NA	*L/F BUMPER CORNER (WCP)	Missing	200.00 F	*200.00 F
10	1	NA	*L/F CORNER PANEL (WCP)	Deformed	260.00 F	*260.00 F
11	1	NA	*L/F HEADLAMP LOWER (WCP)	Torn	9.00 F	*22.00 F
12	1	NA	*L/F INDICATOR (WCP)	Cracked	160.00 F	*160.00 F
13	1	NA	*L/F STEP (WCP)	Cracked	300.00 F	*220.00 F
14	1	NA	*L/INN DOOR LOCK (WCP)	Not Necessary	190.00 F	*-F
15	1	NA	*L/POSITION LAMP (WCP)	Cracked	100.00 F	*100.00 F
16	1	NA	*LEFT FRONT DOOR (WCP)	Bent	1,050.00 F	*1,050.00 F
17	1	NA	*LEFT HEADLAMP ASSY (WCP)	Cracked	300.00 F	*280.00 F
18	1	NA	*R/F BUMPER (WCP)	Not Necessary	115.00 F	*-F
19	1	NA	*R/F BUMPER CORNER (WCP)	Not Necessary	200.00 F	*-F
20	1	NA	*RADIATOR SHROUD (WCP)	Not Necessary	240.00 F	*-F
21	1	NA	*SUNDRY PARTS (NPA)	Not Necessary	0.00 F	*-FS
22	1	NA	*FRT NUMBER PLATE NUMBER PLATE	Bent	15.00 FS	*15.00 FS
		entary #1	Victoria de Partire	2.7 (1)		220 22 2
23	1		*SCUFF PLATE LH (WCP)	Deformed	60.00 F	*60.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
24	1		*FRT DOOR AIR VENT LH (WCP)	Deformed	25.00 F	*25.00 F
25	1		*CORNER PANEL TOP COVER LH	Missing	20.00 F	*20.00 F
F=Fra	nchise	part. S=SpcN	lett.	December 2015		
				Sub Total (S\$)	5,189.00	4,205.00
			tems 10.00/15.00% (S\$)	517.40	628.50	
				Total Parts (S\$)	5,706.40	4,833.50
			Report was unsubmitted do	uring this print-out		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

#### Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items			
Total Paint Labour	New	620.00	620.00
Total Paint Materials	New	169.10	169.10
Total Panel/Mechanical Labour	New	1,035.00	1,015.00
TO REFILL AIRCON GAS	New		60.00
	Gross Labour Cost (S\$)	1,824.10	1,864.10
	our Items Total Paint Labour Total Paint Materials Total Panel/Mechanical Labour	Total Paint Labour New Total Paint Materials New Total Panel/Mechanical Labour New TO REFILL AIRCON GAS New	Total Paint Labour New 620.00 Total Paint Materials New 169.10 Total Panel/Mechanical Labour New 1,035.00 TO REFILL AIRCON GAS New -

Report was unsubmitted during this print-out.

< END OF ESTIMATES >