

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III19014857/GEA3Q2  
**Date:** 28/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	PC6339D	<b>Insured Vehicle No :</b>	SHD3474E
Date of Loss:	21/07/2019	Nature of Claim:	TP
		Claim No:	MCT19070545

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>PC6339D</b>	Engine No:	HIDDEN
Make & Model:	NISSAN NV350 CARAVAN, 2.5 5AT (A)	Chassis No:	DW4E26000365
Reg. Date:	01/01/2000 (Man. Year: 2000)	Odometer:	143867 km
Colour:	White/Blue		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	OHTSU 5 mm	Rear Left Side:	OHTSU 5 mm
Front Right Side:	OHTSU 5 mm	Rear Right Side:	OHTSU 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,560.00	4,520.00	2,040.00	31.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	1,080.00	3,220.00	74.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,860.00</b>	<b>5,600.00</b>	<b>5,260.00</b>	<b>48.43</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		

(S\$)	10,860.00	4,500.00	6,360.00	58.56
<b>+ GST 7.00/7.00% (S\$)</b>	760.20	315.00	445.20	58.56
<b>Nett Amount (S\$)</b>	<b>11,620.20</b>	<b>4,815.00</b>	<b>6,805.20</b>	<b>58.56</b>
<b>+ Loss of Use (6.0 x S\$120.00/day) (S\$)</b>		720.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,542.45</b>		

INSPECTION

Date of Assignment: 21/08/2019

Date Inspected: 03/09/2019

Estimated Period of Repair: 5.0 days

Inspected At:

Yang Yun Xin Bus Service (HQ)  
 50 Serangoon North Ave 4 #01-23 First Centre  
 Singapore 555856

**Adjuster:** XING GUO QIANG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 26 Apr 2021)	
<b>Parts:</b>	N/A	NISSAN NV350 CARAVAN 2.5 5AT (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC6339D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR	Buckled	4,500.00 F	*4,500.00 FL
2	1		*REAR DOOR WEATHERSTRIP	Necessary	650.00 F	*650.00 FL
3	1		*REAR BUMPER COVER	Deformed	580.00 F	*580.00 FL
4	1		*REAR UNDERCARRIAGE ENFORCEMENT BAR	Not Necessary	300.00 F	*- FL
5	1		*70KM STICKER	Necessary	30.00 F	*30.00 FL
6	1		*LOGO ARTWORK STICKER FOR PAINT SPRAYING	Necessary	250.00 FS	*100.00 FS
7	1		*TEL ARTWORK STICKER FOR PAINT SPRAYING	Necessary	250.00 FS	*100.00 FS
					<b>Sub Total (S\$)</b>	<b>6,560.00</b>
					<b>- List Item Discount on L Items 0.00/25.00% (S\$)</b>	<b>0.00</b>
					<b>Total Parts (S\$)</b>	<b>6,560.00</b>
						<b>4,520.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SUPPLY LABOUR AND MATERIALS TO REMOVE ,REPLACE AND ALIGN DAMAGED DOOR /BUMPER /PARTS	New	1,500.00	400.00
2	TO PUTTY AND SPRAY PAINT ALL AFFECTED AREA AND PANELS	New	1,800.00	450.00
3	TO DISMANTLE AND REINSTALL DOOR PANEL AND WINDOW	New	800.00	150.00
4	TO REMOVE AND REINSTALL POWER DOOR MOTOR	New	100.00	50.00
5	TO TEST AND RECONNECT ALL ELECTRICAL COMPOUND	New	100.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>4,300.00</b>	<b>1,080.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >