

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD19014864/R1PS3N2

**Date:** 19/08/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00005636

**Claimant**  
**Vehicle No :** SLF4827G **Insured Vehicle No :** SJW3205S

Date of Loss: 22/08/2019 Nature of Claim: TP Claim No: 1201900025091

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF4827G	Engine No:	FB20Y330565
Make & Model:	SUBARU FORESTER, 2.0 (A)	Chassis No:	JF1SJ5KC5GG074374
Reg. Date:	29/08/2016 (Man. Year: 2016)	Odometer:	63935 km
Colour:	Brown		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,526.03	5,034.60	2,491.43	33.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,710.00	3,150.00	1,560.00	33.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>12,236.03</b>	<b>8,184.60</b>	<b>4,051.43</b>	<b>33.11</b>
<b>+ Car Rental (16.0 x S\$150.00/day) (S\$)</b>		2,400.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>10,586.60</b>		
<b>Global Sum Settlement (S\$)</b>		<b>10,500.00</b>		

### INSPECTION

Date of Assignment: 22/08/2019

Date Inspected: 23/08/2019 Inspected At:

Xinya Auto Services Pte Ltd (HQ)  
Blk 1002, #01-75, Bukit Merah Lane 3  
Singapore 159719

Estimated Period of Repair: 12.0 days

**Adjuster:** MOHD RASUL

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2020)
<b>Parts:</b>	M1-SUV	SUBARU FORESTER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLF4827G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	600.30 FL	*600.30 FL
2	1		*REAR BUMPER ENFORCEMENT	Bent	320.30 FL	*320.30 FL
3	2		*REAR BUMPER BRACKET	Necessary	40.60 FL	*40.60 FL
4	1		*REAR BUMPER RETAINER	N/S Necessary	32.60 FL	*16.30 FL
5	1		*REAR BUMPER REFLECTOR	Cracked	22.80 FL	*22.80 FL
6	1		*REAR TAIL GATE	Bent	1,072.30 FL	*1,072.30 FL
7	1		*REAR TAIL GATE WEATHERSTRIP	Necessary	120.30 FL	*120.30 FL
8	1		*REAR TAIL GATE LOCK	Serviceable	176.40 FL	*- FL
9	1		*REAR WINDSCREEN SEALANT	Necessary	30.80 FL	*30.80 FL
10	4		*REAR WINDSCREEN CLIPS	Necessary	42.80 FL	*42.80 FL
11	1		*SUBARU LOGO	Necessary	72.30 FL	*72.30 FL
12	1		*4WD EMBLEM	Necessary	68.05 FL	*68.05 FL
13	1		*SUBARU EMBLEM	Necessary	72.30 FL	*72.30 FL
14	1		*XTI EMBLEM	Necessary	72.30 FL	*72.30 FL
15	1		*END PANEL	Repair	320.00 FL	*- FL
16	1		*END PANEL GARNISH	Serviceable	40.30 FL	*- FL
17	1		*FRONT BUMPER	Cracked	594.55 FL	*594.55 FL
18	1		*FRONT BUMPER ENFORCEMENT	Bent	320.30 FL	*320.30 FL
19	1		*REAR BUMPER RETAINER	N/S Necessary	40.60 FL	*20.30 FL
20	1		*REAR BUMPER WATER NOZZLE	Serviceable	79.20 FL	*- FL
21	1		*REAR BUMPER WATER NOZZLE COVER	Missing	54.30 FL	*54.30 FL
22	1		*FRONT GRILLE	Scratched	308.30 FL	*308.30 FL
23	1		*FRT GRILLE BASE	Serviceable	260.80 FL	*- FL
24	1		*FRONT HEADLAMP LEFT	Cracked	2,400.30 FL	*2,400.30 FL
25	1		*NOS PLATE HOLDER	Serviceable	150.80 FL	*- FL
26	1		*SPARE TYRE PANEL	Repair	432.50 FL	*- FL
27	1		*FRONT LH FENDER	Repair	458.60 FL	*- FL
28	1		*FENDER SPLASH GUARD	Serviceable	102.00 FL	*- FL
29	1		*NOS PLATE WITH CASING	Bent	50.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,356.70</b>	<b>6,284.50</b>
<b>- List Item Discount on L Items 10.00/20.00% (\$\$)</b>	830.67	1,249.90
<b>Total Parts (\$\$)</b>	<b>7,526.03</b>	<b>5,034.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE & REPLACE FRONT BUMPER & REAR BUMPER ,FENDER ,FRT & REAR ENFORCEMENT ,TAIL GATE ,HEADLAMP AND TO PANEL BEAT AND ALIGN	New	2,000.00	1,400.00
2	TO PUTTY & SPRAY PAINT FRONT & REAR BUMPER ,FENDER ,REAR TAIL GATE(INNER & OUTER),END PANEL ,SPARE TYRE PANEL & OTHER AFFECTED AREA	New	1,800.00	1,400.00
3	TO REMOVE & REFIT REAR SIDE BOARD ,GARNISH TO ENABLE HOT WORKS TO SPARE TYRE PANEL	New	350.00	80.00
4	TO REMOVE & FIT WINDSCREEN GLASS TO NEWS TAIL GATE AND CHECK FOR WATER TIGHT	New	150.00	120.00
5	TO CHECK & RECTIFY WIRING AND FOCUS HEADLAMP	New	60.00	30.00
6	TUFF KOTE	New	350.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,710.00</b>	<b>3,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >