

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5717C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RETAINER, RR BUMPER, LH (DISC 25%) (CONSISTENT)	BROKEN	111.50	83.63
10	CLIPS PIECE, FRT & RR BUMPER @ \$1.50 (DISC 25%) (CONSISTENT)	NECESSARY	15.00	11.25
2	PIXEL STICKER @ \$60.00 (SN) (CONSISTENT)	NECESSARY	120.00	120.00
1	LINER, REAR FENDER, LH (CONSISTENT)	NOT NECESSARY	135.80	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	318.80	-
1	COVER, RR BUMPER ASSY (CONSISTENT)	NOT NECESSARY	423.90	-
1	SEAL, RR BUMPER, LH (CONSISTENT)	NOT NECESSARY	85.20	-
1	FILLER, RR BUMPER, LH (CONSISTENT)	NOT NECESSARY	119.90	-
1	SENSOR REVERSE (CONSISTENT)	NOT NECESSARY	180.00	-
1	PANEL SUB-ASSY, REAR DOOR, LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,243.90	-
1	MOULDING ASSY, BODY ROCKER PANEL, LH (CONSISTENT)	TO REPAIR SEE LABOUR	576.00	-
1	PANEL SUB-ASSY, FENDER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	824.80	-
1	WHEEL, DISC (CONSISTENT)	TO REPAIR SEE LABOUR	1,555.10	-
1	COVER, RR BUMPER ASSY (CONSISTENT)	TO REPAIR SEE LABOUR	423.90	-
			6,133.80	214.88
	<u>LABOUR</u>			
	PANEL BEATING & BDOYWORK. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, REAR DOOR, LH; MOULDING ASSY, BODY ROCKER PANEL, LH; PANEL SUB-ASSY, FENDER REAR LH; WHEEL, DISC AND COVER, RR BUMPER ASSY.		507.00	300.00
	SPRAY PAINT.		1,494.00	800.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	_
	TO REPLACE SUNDRY PARTS.		80.00	20.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		100.00	20.00
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	120.00	-

Report Ref No. CC4/ASM19014877/Eps3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	NOT NECESSARY	120.00	-
			2,481.00	1,140.00
	GRAND TOTAL		8,614.80	1,354.88

RECOMMENDED COST OF REPAIRS		1,354.88

Report Ref No. CC4/ASM19014877/Eps3s2

la.

CHEN TSUE YEE

Automotive Assessor

Amonto

HO LEONG CHUAN

Automotive Assessor