

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19014882/KEA3Q2

Date: 24/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900092694

Claimant
Vehicle No : SMK9584K **Insured Vehicle No :** SKT1644A

Date of Loss: 19/08/2019 Nature of Claim: TP Claim No: 6269504455SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK9584K		
Make & Model:	MERCEDES-BENZ GLC 250, 2.0 4MATIC (A)	Engine No:	27492030703967
Reg. Date:	06/10/2016 (Man. Year: 2016)	Chassis No:	WDC2539462F102704
Colour:	Metallic Black	Odometer:	55527 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,153.75	2,397.24	756.51	23.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,270.00	610.00	660.00	51.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,423.75	3,007.24	1,416.51	32.02
+ GST 7.00/7.00% (\$\$)	309.66	210.51	99.15	32.02
Nett Amount (\$\$)	4,733.41	3,217.75	1,515.66	32.02
+ Car Rental (3.0 x S\$120.00/day + 7.00% GST) (\$\$)		385.20		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		3,604.95		

INSPECTION

Date of Assignment: 22/08/2019

Date Inspected: 22/08/2019 Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,216.00 FL	*1,216.00 FL
2	1		*REAR BUMPER SIDE RETAINER RH	Repair	129.50 FL	*- FL
3	12		*REAR BUMPER CLIPS	Necessary	102.00 FL	*102.00 FL
4	1		*REAR BUMPER LOWER COVER	Dented	574.60 FL	*574.60 FL
5	8		*REAR BUMPER LOWER COVER CLIPS	Necessary	62.40 FL	*62.40 FL
6	1		*REAR BUMPER LOWER COVER CHROME MOULDING	Cracked	708.60 FL	*708.60 FL
7	6		*REAR BUMPER REVERSE SENSOR SEAL	Serviceable	44.40 FL	*- FL
8	1		*REAR TAILGATE (NPA)	Repair	0.00 FL	*- FL
9	1		*SET REAR BUMPER REVERSE SENSOR	Serviceable	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,437.50	2,663.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	283.75	266.36
Total Parts (\$\$)	3,153.75	2,397.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,READJUST REAR ACCIDENT AREAS & ETC	New	400.00	250.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREAS &ETC	New	600.00	300.00
3	TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & TO RECONNECT WIRING SYSTEMS	New	120.00	60.00
4	TO DIAGNOSIS FAULTY CODE & TO PERFORM MEMORY SET	New	150.00	0.00
Gross Labour Cost (\$\$)			1,270.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >