

Date: 21.08.2019
Vehicle No: SMK9584K
Model: MERCEDES BENZ GLC 250
Chassis: WDC2539462F102704 - 2016
Reg.Year: 2016

Third Party Insurer: SKT1644A
Third Party Veh No: AIG
Date of Accident: 19.08.2019

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		\$1,216.00
2	REAR BUMPER SIDE BRACKET RH	1		\$129.50
3	REAR BUMPER CLIPS	12	\$8.50	\$102.00
4	REAR BUMPER LOWER COVER	1		\$574.60
5	REAR BUMPER LOWER COVER CLIPS	8	\$7.80	\$62.40
6	REAR BUMPER LOWER COVER CHROME MOULDING	1		\$708.60
7	REAR BUMPER REVERSE SENSOR SEAL	6	\$7.40	\$44.40
8	REAR TAILGATE			REPAIR
SUB TOTAL				\$2,837.50
LESS 10%				-\$283.75
PARTS TOTAL				\$2,553.75

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER REVERSE SENSOR SET	1		\$600.00
S/N TOTAL				\$600.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST REAR ACCIDENT AREAS & ETC

\$400.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREAS & ETC

\$600.00

TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & TO RECONNECT WIRING SYSTEMS

\$120.00

TO DIAGNOSIS FAULTY CODE & TO PERFORM MEMORY SET

\$150.00

Life-Air Conditions not working The Repair cost is following: • Front air filter & air duct cleaning • Front air filter & air duct cleaning • Rear air filter & air duct cleaning • Rear air filter & air duct cleaning • Front air filter & air duct cleaning		LABOUR TOTAL	\$1,270.00
ONG		TOTAL	\$4,423.75

Head office

8 Hong Chong Road Singapore 151143
Tel: (+65) 6472 1312 Fax: (+65) 6472 2113

Branch

5A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 Fax: (+65) 6452 9223

