

O.S.K. Auto Spare Parts Trading (1994)

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #04-09
 Singapore 568047 HP 91004390/HP 91254449 Fax 64841482
 Email: oskautomotiveamk@gmail.com

M/s	FWD Singapore Pte Ltd	DATE	27.08.2019
	6 Temasek Boulevard, #18-01	CAR NO	SMK 8976 U
	Suntec Tower Four, Singapore 038986	MAKE	Volvo V60 T4

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
 YOUR INSURED : SGR 282 A

Pc	Pcs	YV1FW48HBD1104483	UNIT PRICE	AMOUNT
1	pc	Front bumper / CUT		\$1,398.00
1	pc	Front bumper tow cover X		\$45.00
10	pcs	Front bumper clips / NPC	\$5.00	\$50.00
1	pc	Front right side head lamp / CUT		\$1,642.00
1	pc	Front bumper right side fog lamp garnish. / CUT		
		To dismantle and replace the above mentioned parts.	200	\$600.00
		Labour for respray front bumper assy.	200	\$400.00
		To check head lamp wiring.	30	\$100.00
		Rust-proofing on the rear accident affected portions.	30	\$150.00
		Steve (LKK) 8322 8813 Stevechin@lkk.com htl 27/8/19, 1.3pp 2 days L/S R, AL spy		
			Total	\$4,385.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: