

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19014955/KBA3Q2

**Date:** 09/07/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100483333-02

**Claimant**  
**Vehicle No :** SLR1419H **Insured Vehicle No :** SLG457L

Date of Loss: 21/08/2019 Nature of Claim: TP Claim No: 0532022719SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLR1419H</b>		
Make & Model:	TOYOTA C-HR HYBRID, 1.8 E S 5DR (A)	Engine No:	2ZR8118967
Reg. Date:	31/07/2017 (Man. Year: 2017)	Chassis No:	ZYX102043828
Colour:	Metallic Orange	Odometer:	47765 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	49.50	49.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	300.00	100.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>449.50</b>	<b>349.50</b>	<b>100.00</b>	<b>22.25</b>
<b>+ GST 7.00/7.00% (S\$)</b>	31.47	24.47	7.00	22.24
<b>Nett Amount (S\$)</b>	<b>480.97</b>	<b>373.97</b>	<b>107.00</b>	<b>22.25</b>
<b>+ Car Rental (1.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		107.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>482.97</b>		
<b>Global Sum Settlement (S\$)</b>		<b>480.00</b>		

### INSPECTION

Date of Assignment: 26/08/2019

Date Inspected: 26/08/2019 Inspected At: Optima Werkz Pte Ltd (HQ)  
9A Serangoon North Ave 5  
Singapore 554500

Estimated Period of Repair: 1.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (NPA)	Repair	0.00 FL	*- FL
2	12		*FRONT BUMPER CLIPS	Necessary	66.00 FL	*66.00 FL
					<b>Sub Total (\$\$)</b>	<b>66.00</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>16.50</b>
					<b>Total Parts (\$\$)</b>	<b>49.50</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACED FRONT BUMPER & ETC	New	100.00	80.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS	New	300.00	220.00
<b>Gross Labour Cost (\$\$)</b>			<b>400.00</b>	<b>300.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >