

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19014956/UEA3Q2

Date: 09/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994156

Claimant
Vehicle No : SLE414X **Insured Vehicle No :** GBB1549T

Date of Loss: 24/08/2019 Nature of Claim: TP Claim No: 3473859119SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE414X	Engine No:	2ARH704216
Make & Model:	TOYOTA ALPHARD, 2.5 (A)	Chassis No:	JTNGF3DH108004988
Reg. Date:	31/05/2016 (Man. Year: 2016)	Odometer:	120929 km
Colour:	Silver		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,794.00	9,421.20	23,372.80	71.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,930.00	2,600.00	2,330.00	47.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,724.00	12,021.20	25,702.80	68.13
Approved Total (Overridden) (S\$)		9,500.00		
(S\$)	37,724.00	9,500.00	28,224.00	74.82
+ GST 7.00/7.00% (S\$)	2,640.68	665.00	1,975.68	74.82
Nett Amount (S\$)	40,364.68	10,165.00	30,199.68	74.82
+ Car Rental (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,652.45		
Global Sum Settlement (S\$)		10,650.00		

INSPECTION

Date of Assignment: 26/08/2019

Date Inspected: 26/08/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	1,650.00 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	185.00 F	*185.00 FL
3	1		*TAILGATE	Badly Dented	2,880.00 F	*1,955.10 FL
4	1		*TAILGATE INNER LOCK	Dented / Jammed	650.00 F	*599.50 FL
5	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	845.30 F	*745.10 FL
6	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
7	1		*TAILGATE OUTER CHROME GARNISH	Not Necessary	488.00 F	*- FL
8	1		*TAILGATE ALPHARD EMBLEM	Necessary	105.00 F	*98.50 FL
9	2		*TAILGATE REFLECTORS	Cracked	1,900.20 F	*1,290.20 FL
10	1		*TAILGATE WEATHERSTRIP	Twisted	399.10 F	*399.10 FL
11	1		*REAR BUMPER	Dented / Deformed	2,251.00 F	*691.50 FL
12	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	210.00 F	*- FL
13	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
14	2		*REAR BUMPER BRACKETS	Not Necessary	290.00 F	*- FL
15	2		*REAR BUMPER REFLECTORS	Cracked	250.00 F	*250.00 FL
16	1		*REAR BUMPER TOW COVER	Deformed	48.00 F	*48.00 FL
17	4		*REAR BUMPER PDC SENSORS	Shorted (2 PCS ONLY)	1,060.00 F	*530.00 FL
18	1		*REAR END PANEL	Badly Dented	1,100.00 F	*788.10 FL
19	1		*REAR END PANEL TOP GARNISH	Twisted	362.00 F	*245.50 FL
20	1		*REAR END PANEL BUZZER	Cracked	215.00 F	*215.00 FL
21	1		*REAR FLOOR PANEL	Repair	1,480.00 F	*- FL
22	2		*REAR FLOOR PANEL TOP BOARDS	Warped / Deformed	1,300.00 F	*1,300.00 FL
23	2		*TAILLAMPS	Cracked	2,100.00 F	*625.50 FL
24	1		*TAILLAMP LOWER GARNISH	N/S Dented	1,710.00 F	*605.10 FL
25	2		*REAR FENDERS	Repair	2,960.20 F	*- FL
26	2		*REAR FENDER INNER TRIM BOARDS	Deformed / Cracked	1,904.20 F	*1,330.40 FL
27	1		*REAR EXHAUST	Not Necessary	991.00 F	*- FL
28	2		*REAR EXHAUST MOUNTINGS	Not Necessary	130.00 F	*- FL
29	1		*REAR AIR CON BLOWER	Not Necessary	2,990.00 F	*- FL
30	2		*REAR END SIDE PANELS	Repair	970.00 F	*- FL
31	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
32	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	300.00 FS	*- FS
33	1		*SET REAR REVERSE CAMERA	Shorted	650.00 FS	*380.00 FS
34	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
35	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	32,794.00	12,421.60
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	3,000.40
Total Parts (\$)	32,794.00	9,421.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REAR PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO TRANSFER TAILGATE MECHANISM	New	120.00	60.00
5	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
6	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
7	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
8	TO SPRAY RUST PROOFING	New	150.00	80.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	2,200.00	1,000.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	1,180.00
Gross Labour Cost (\$\$)			4,930.00	2,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >