

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19014964/R1PA3Q2

**Date:** 18/08/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MCV0002573
<b>Claimant Vehicle No :</b>	FBK789B	<b>Insured Vehicle No :</b>	XD4155E
Date of Loss:	29/07/2019	Nature of Claim:	TP
		Claim No:	MCV2019D0000954

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK789B	Engine No:	HIDDEN
Make & Model:	YAMAHA JUPITER LC135, 135cc	Chassis No:	MH350C006EK739336
Reg. Date:	01/02/2015 (Man. Year: 2015)	Odometer:	79593 km
Colour:	Multi-colour		
Engine Capacity:	134 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Maxxis 3 mm	Rear Left Side:	Maxxis 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,733.30	2,018.30	715.00	26.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	390.00	0.00	390.00	100.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,123.30</b>	<b>2,018.30</b>	<b>1,105.00</b>	<b>35.38</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,600.00</b>		
<b>(S\$)</b>	3,123.30	1,600.00	1,523.30	48.77
<b>+ GST 7.00/7.00% (S\$)</b>	218.63	112.00	106.63	48.77
<b>Nett Amount (S\$)</b>	<b>3,341.93</b>	<b>1,712.00</b>	<b>1,629.93</b>	<b>48.77</b>
<b>+ Loss of Use (4.0 x S\$25.00/day) (S\$)</b>		100.00		
<b>(S\$)</b>		1,812.00		
<b>Liabie Amount (50.00%) (S\$)</b>		<b>906.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>900.00</b>		

### INSPECTION

Date of Assignment: 23/08/2019

Date Inspected: 26/08/2019 Inspected At:

Southern Motor (HQ)  
BLK 1006 BUKIT MERAH LANE 2,

#01-10  
Singapore 159762

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MOHD RASUL

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 19 Jun 2020)	
<b>Parts:</b>	N/A	YAMAHA JUPITER LC135 135cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBK789B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET COVER	Cracked	580.00 FL	*580.00 FL
2	1		*HANDLE BAR	Bent	68.00 FL	*68.00 FL
3	1		*MIRROR	Missing	45.00 FL	*45.00 FL
4	1		*HANDLE GRIP	Cut	35.00 FL	*35.00 FL
5	1		*FRONT FOOTREST	Bent	68.00 FL	*68.00 FL
6	1		*FOOTREST RUBBER	Cut	20.00 FL	*20.00 FL
7	1		*EXHAUST PIPE	Scratched	580.00 FL	*580.00 FL
8	1		*REAR MUDGUARD	Cracked	65.00 FL	*65.00 FL
9	1		*BRAKE LEVER	Bent	68.00 FL	*68.00 FL
10	2		*REAR FOOTREST	Cracked	40.00 FL	*40.00 FL
11	1		*REAR HEADLIGHT	Serviceable	110.00 FL	*- FL
12	2		*REAR FOOTREST STAND	Cracked	110.00 FL	*110.00 FL
13	1		*STEERING CORN	Necessary	85.00 FL	*85.00 FL
14	1		*SEAT BAR	Scratched	55.00 FL	*55.00 FL
15	1		*GEAR LEVER	Bent	68.00 FL	*68.00 FL
16	1		*FRONT FORK COMPLETE (LOCAL REPAIR)	Scratched	342.00 FS	*100.00 FS
17	1		*SPOKE RIM (LOCAL REPAIR)	Scratched	432.00 FS	*100.00 FS
18	1		*REPAIR BRAKE BODY (LOCAL REPAIR)	Bent	162.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,933.00</b>	<b>2,207.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	199.70	188.70
<b>Total Parts (\$\$)</b>	<b>2,733.30</b>	<b>2,018.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT	New	40.00	0.00
2	LABOUR	New	350.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>390.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**