

On Wed, Aug 28, 2019 at 3:05 PM Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Adrian,

As instructed by our client , please proceed to repair the **insured vehicle GBH 5339A (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,



Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9030

Arrange By _____ Driver _____

Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792

Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made In Japan)

=====

GFORCE AUTOTECHNIK
10 KAKI BUKIT ROAD 2 #01-34
FIRST EAST CENTER

SINGAPORE 417868

TEL : 62058108

ATTN : AH LIM/ELLE (BOSS DEREK 85558300)

TAX INVOICE : AR201909-01179
DATE : 03/09/2019
CUSTOMER ID : GFO001
VEH REG. NO. : GBF5399A
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 3
CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8. N62221-3XA0A/B E26	FRT BUMPER SIDE BRACKET LH	WH WH	1	110.00	110.00
9. N27200-3XA1A/3XA2A E26	BLOWER MOTOR ASSY	WH WH	1	851.10	851.10
10. N28860-3XA0A E26 E25 DTI	WIPER LINK	WH WH	1	210.00	210.00
11. N96151-3XA0A E26	STEP GARNISH LH,	WH WH	1	65.00	65.00
12. N26075-3XA0D/3XA1D E26 NV350	HEADLAMP LH	WH WH	1	380.00	380.00
13. N62310-3XA0C E26 CHROME	RAD.GRILLE (CHROME)	WH WH	1	480.00	480.00
14. N62889-WB60A/WL000 ME51 M20 NV200	GRILLIE LOGO	WH WH	1	65.00	65.00

CONTINUE NEXT PAGE

[P] 03/09/2019 12:29:17PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 03/09/2019 12:03:59PM



日美汽車私人有限公司
JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9635

Arrange by _____ Driver _____



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made In Japan)

=====

GFORCE AUTOTECHNIK
10 KAKI BUKIT ROAD 2 #01-34
FIRST EAST CENTER

SINGAPORE 417868
TEL : 62058108
ATTN : AH LIM/ELLE (BOSS DEREK 85558300)

TAX INVOICE : AR201909-01179
DATE : 03/09/2019
CUSTOMER ID : GFO001
VEH REG. NO. : GBF5399A
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 3
CURR. : S\$

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	NF1202-3XAMA/F1B02-3X AMA	FRT PANEL	WH	1	858.60	858.60 ✓
	E26 14' LR		WH			
2.	N61261-3XA0A E26	SIDE PANEL LH	WH	1	477.60	477.60 ✓
			WH			
3.	NH010A-3XAMB E26	FRT DOOR LH	WH	1	1015.60	1,015.60 ✓
			WH			
4.	N62022-3XA0H E26 14' LR	FRT BUMPER	WH	1	514.70	514.70 ✓
			WH			
5.	N26150-3XA0A E26	FOG LAMP RH & LH	WH	1	311.80	311.80 ✓
			WH			
6.	N62257-3XA0B E26	FOG LAMP COVER LH W/HOLE	WH	1	91.60	91.60 ✓
			WH			
7.	N62030-3XA0B E26 V LR	FRT REINFORCEMENT	WH	1	591.90	591.90 ✓
			WH			

CONTINUE NEXT PAGE

[P] 03/09/2019 12:29:17PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 03/09/2019 12:03:59PM



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made In Japan)

GFORCE AUTOTECHNIK
10 KAKI BUKIT ROAD 2 #01-34
FIRST EAST CENTER

SINGAPORE 417868
TEL : 62058108
ATTN : AH LIM/ELLE (BOSS DEREK 85558300)

TAX INVOICE : AR201909-01179
DATE : 03/09/2019
CUSTOMER ID : GFO001
VEH REG. NO. : GBF5399A
TERMS : 30 days
PO NO. :
PAGE NO. : Page 3 of 3
CURR. : S\$

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
15. N80501-3XA1A E26 A/T	F/DOOR INNER LOCK LH	WH WH	1	250.00	250.00 ✓

SUB-TOTAL : 6,272.90
ADD GST 7.00 % 439.10

E. & O E TOTAL AMOUNT S\$: 6,712.00

[P] 03/09/2019 12:29:17PM

[E] 03/09/2019 12:03:59PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : JOE



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Jul 2019		26 Aug 2019 15:07 Edit Adj Rpt	S\$8,850.19 Edit Estimates	S\$8,850.19 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CFI TRANSPORT PTE LTD, Co. Reg. No.: 201806390H		
Vehicle Reg. No.:	GBH5339A	Date of Loss:	05/07/2019 16:00 - :59 [12 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 599644	Policy/Cover Note No.:	29087313MKC (Comprehensive) Coverage: 30/06/2019 - 29/06/2020
		Excess:	S\$600.00
Repairer:	Gforce Autotech Private Limited (HQ) 10 KAKI BUKIT RD 2, #01-34, 417868 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Nor Azian Binte Noordin - 6594 2558]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/09/2019]		
Driver/Custodian:	MOHD SUPRI BIN PAGI (44 / Male) , NRIC: S7442294B, Tel: +6582201107 Email: NOEMAIL		
Adj Asg. Remarks:	Car in. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Manual assigned to LKK via email on 26/08/19. Please revert with MV		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (04/09/2019): Alert - Adj Mandate Approved (S\$8850.19) - GBH5339A - Claim Handler: Nor Azian B...
- MSIG_SG (28/08/2019): Alert - Adj Mandate Approved (S\$5892.91) - GBH5339A - Claim Handler: Nor Azian B...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

*GBH5339A (599644)
OD
Jul 5 2019 4:00PM
[CFI TRANSPORT PTE LTD]
Gforce Autotech Private Limited

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View [View in Browser](#) ▼

Assessment Reports

No	Finalized On	VAC (Kaki Bukit)	1 per page	<input checked="" type="checkbox"/>
1	12/07/19 10:35	Accident Statement		Thumbnail Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Load HTM
1	27/08/19 13:51	Adjuster Immediate Advice		Thumbnail Print
2	03/09/19 15:47	Adjuster Immediate Advice		Load HTM
				Load HTM

Photos/Images

No	Finalized On	VAC (Kaki Bukit)	3 per page	<input checked="" type="checkbox"/>
1	11/07/19 12:09	Accident Photo [Linked Accident Report Documents]		Thumbnail Print
2	11/07/19 12:09	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
3	11/07/19 12:09	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
4	11/07/19 12:09	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
5	11/07/19 12:09	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
6	11/07/19 12:09	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
7	11/07/19 12:09	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
8	11/07/19 12:09	Accident Photo [Linked Accident Report Documents]		Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
2	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
3	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
4	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
5	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
6	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
7	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
8	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
9	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
10	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
11	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
12	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
13	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
14	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
15	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
16	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
17	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
18	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
19	27/08/19 12:53	General View		Load JPG <input checked="" type="checkbox"/>
20	02/09/19 11:38	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
21	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	02/09/19 11:38	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/07/19 11:18	Status of Driving Licence - Valid	 Load PDF	
2	21/08/19 14:45	Valid Road Tax	 Load PDF	
3	21/08/19 14:50	COE / PARF Value	 Load PDF	
4	26/08/19 12:10	Request for survey frm GForce Autotech	 Load PDF	
5	26/08/19 12:10	ESTIMATE	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	26/08/19 15:01	Survey Request - Manual Assigned	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/08/19 13:36	MARK ESTIMATE	 Load PDF	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
2	02/09/19 11:42	SUPPLEMENTARY		Load PDF
3	02/09/19 11:51	MARKING		Load PDF
4	05/09/19 09:24	PARTS INVOICE		Load PDF

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	VAC (Kaki Bukit)	1 per page	<input checked="" type="checkbox"/>
			Thumbnail	Print
1	19/08/19 11:51	Addendum Sheet		Load TIF
2	04/09/19 01:38	Accident Statement		Load HTM
3	04/09/19 01:54	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	11/07/19 12:09	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	11/07/19 12:09	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	11/07/19 12:09	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	11/07/19 12:09	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	11/07/19 12:09	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	11/07/19 12:09	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	11/07/19 12:09	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	11/07/19 12:09	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	12/07/19 10:35	Sketch Plan		Load TIF
2	12/07/19 10:35	Sketch Plan #2		Load TIF
3	19/08/19 11:51	Accident Sketch Plan		Load TIF
4	19/08/19 11:51	Accident Sketch Plan		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19014970/GVF3S2

Date: 05/09/2019

REFERENCE

Insured/Claimant:	CFI TRANSPORT PTE LTD	Policy No:	29087313MKC	Claim No:	599644
Date of Loss:	05/07/2019	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH5339A	Engine No:	YD25424660A
Make & Model:	NISSAN NV350, 2.5 (A)	Chassis No:	JN1MC2E26Z0009221
Reg. Date:	30/06/2018 (Man. Year: 2017)	Odometer:	39412 km
Colour:	Black		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	S\$54,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Compasal 5 mm	Rear Left Side:	Compasal 5 mm
Front Right Side:	Compasal 5 mm	Rear Right Side:	Compasal 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,898.95	7,000.19	6,898.76	49.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,810.00	1,850.00	2,960.00	61.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,708.95	8,850.19	9,858.76	52.70
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	18,108.95	8,250.19	9,858.76	54.44
+ GST 7.00/7.00% (S\$)	1,267.63	577.51	690.12	54.44
Nett Amount (S\$)	19,376.58	8,827.70	10,548.88	54.44

INSPECTION

Date of Assignment:	26/08/2019		
Date Inspected:	26/08/2019	Inspected At:	Gforce Autotech Private Limited (HQ) 10 KAKI BUKIT RD 2, #01-34 Singapore 417868
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Sep 2019)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH5339A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANELS (WCP)	Buckled	858.60 F	*858.60 F
2	1		*FRONT CORNER PANELS LH (WCP)	Buckled	477.60 F	*477.60 F
3	1		*FRONT DOOR L/H (WCP)	Buckled	1,015.60 F	*1,015.60 F
4	1		*FRONT DOOR INNER BOARD (WCP)	Serviceable	481.70 F	*- F
5	2		*FRONT DOOR HINGES (WCP)	Not Necessary	58.10 F	*- F
6	1		*DOOR PILLAR (WCP)	Repair	152.80 F	*- F
7	1		*FRONT DOOR REGULATOR MOTOR (WCP)	Not Necessary	147.90 F	*- F
8	1		*DOOR CHECK LINK (WCP)	Not Necessary	65.00 F	*- F
9	1		*FRONT BUMPER (WCP)	Cracked	514.70 F	*514.70 F
10	1		*FRONT BUMPER FOG LAMP L/H (WCP)	Cracked	311.80 F	*311.80 F
11	1		*FRONT BUMPER FOG LAMP COVERS L/H (WCP)	Cracked	91.60 F	*91.60 F
12	1		*FRONT BUMPER REINFORCEMENT L/H (WCP)	Bent	591.90 F	*591.90 F
13	1		*FRONT BUMPER REINFORCEMENT STAYS L/H (WCP)	Serviceable	91.70 F	*- F
14	1		*FRONT BUMPER BRACKET L/H (WCP)	Cracked	110.00 F	*110.00 F
15	1		*FRONT BUMPER TOW HOOK COVER (WCP)	Serviceable	19.40 F	*- F
16	1		*AIR CON BLOWER UNIT (WCP)	Cracked	851.10 F	*851.10 F
17	1		*AIR INTAKE DUCT (WCP)	Not Necessary	179.00 F	*- F
18	1		*FRONT WIPER MOTOR (WCP)	Serviceable	242.40 F	*- F
19	1		*SET FRONT WIPER GARNISH (WCP)	Not Necessary	432.00 F	*- F
20	1		*SET FRONT WIPER LINK (WCP)	Bent	210.00 F	*210.00 F
21	1		*INTERCOOLER (WCP)	Not Necessary	2,121.60 F	*- F
22	1		*INTERCOOLER HOSE (WCP)	Not Necessary	180.00 F	*- F
23	1		*FRONT STEP PANEL L/H (WCP)	Cut	65.00 F	*65.00 F
24	1		*FRONT HEADLAMP L/H (WCP)	Cut	380.00 F	*380.00 F
25	1		*FRONT GRILLE (WCP)	Missing	480.00 F	*480.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*FRONT GRILLE LOGO (WCP)	Necessary	65.00 F	*65.00 F
27	1		*AIR CON COOLING (AIRCON HOUSING) - FULL SET (WCP)	Not Necessary	2,100.00 F	*- F
28	1		*SET FRONT GRILLE CLIP	Necessary	45.00 FS	*45.00 FS
29	1		*SET FRONT BUMPER CLIP	Necessary	25.00 FS	*25.00 FS
30	1		*FRONT CAR PLATE	Bent	30.00 FS	*30.00 FS
31	1		*CAR CENTER DOOR (WCP)	Bent	250.00 F	*250.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$)	12,644.50	6,372.90
+ Margin on L,N Items 10.00/10.00% (\$)	1,254.45	627.29
Total Parts (\$)	13,898.95	7,000.19

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPLACED DAMAGED LAMPS & CHECKUP REAR WIRING.	New	80.00	30.00
2	TO REMOVE & REFIT INNER GARNISHES.	New	150.00	60.00
3	TO REMOVE, REPLACE AIR-CON AND CONDUCT LEAKAGE TEST.	New	200.00	0.00
4	TO REMOVE & REFIT DASHBOARD TO ASSIST REPAIR.	New	250.00	200.00
5	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS.	New	180.00	0.00
6	TO APPLY UNDERCOATING ON REPAIRED AND REPAIRED PANEL.	New	350.00	60.00
7	PANEL BEATING.	New	2,000.00	700.00
8	TO RE-SPRAY ON THE AFFECTED AREAS & POLISHING BACK.	New	1,600.00	800.00
Gross Labour Cost (S\$)			4,810.00	1,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >