

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG19014990/EPA3Q2**Date:** 11/05/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SMB142J **Insured Vehicle No :** SFM9212G

Date of Loss: 20/08/2019 Nature of Claim: TP Claim No: 8507445659SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMB142J**

Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D (A) Engine No: 90292600909583

Reg. Date: 18/03/2011 (Man. Year: 2010) Chassis No: WEB62808323120697

Colour: Multi-colour Odometer: 720143 km

Engine Capacity: 6374 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5

Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,241.00	884.00	357.00	28.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,241.00	884.00	357.00	28.77
+ Loss of Use (3.0 x S\$250.00/day) (S\$)		750.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,641.00		
Global Sum Settlement (S\$)		1,600.00		

INSPECTION

Date of Assignment: 23/08/2019

Date Inspected: 23/08/2019 Inspected At: Strides Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR LHS PORTION	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	446.00	354.00
Gross Labour Cost (S\$)			1,241.00	884.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >