

12/03/2007

REC. BY:

REF:

CS/FC19015073/DYF302

Special Instruction:

Surveyor

Bryan

ASSIGNMENT (Office)

From (Person):

Hung Kao

of

FCI

Date/Time:

27.8.2019 12:55p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 3517X

Insured:

SHC 7237C

Tel:

65427162

at Workshop m/s

Chunni Motor

of ANK Autopaint, Soon Hock motor #01-05706

Policy No:

Claim No:

D19005487MFSH

Sum Insured:

Excess:

D.O.A.

26.8.2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

27.8.19 1.00p.m

Person Contacted:

Lynn

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction

(✓) Estimate

SHC 7237C

NA 2011025799/H2400

D.O.A. 14/12/2011

SHC 3517X :x

REF:

ASSIGNMENT

CBE March 2022

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

9

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 3517 X

Yr Regn:

2014 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz E220 c.c 2143

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

701168

T/Radio: Insured / Std / NI / NA

Eng/No:

65192431513047

C/No:

WDD2120022A761435

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

S mm

R/Bal.

S mm

L/Bal.

S mm

L/Bal.

S mm

D.O.A.

26/08/2019

D.O.I.

27/08/2019

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front y 4/5 Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First report SHC 7237C

6/9/19 Sent email Preli Revised

24/09/19

Invoice 2/5 14000/- -> 9 days of work (Red \$17,061.16, 54%)

RECEIVED 25 SEP 2019

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

24/9/19 Typist

Days Of Repair:

9

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

14,000/-

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

26/9/19

21X15 = 315

170+315

50

50+50

120

755



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005487MFSH

Date: 06 Sep 2019

Our Ref: CS/FCI19015073/Dyf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC3517X

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/08/2019 at the premises of M/s CHUNNI MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>31,061.16</u>
Revised Estimate Amount	: S\$ <u>18,295.16</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the N/S FRONT PORTION & N/S BODY



Yours faithfully

Bryan Ang
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	26-08-2019	Our Ref No. D19005487MFSH
Accident Date	26-08-2019	Claim Type. Third Party
Insured Vehicle	SHC7237C	Third Party Vehicle. SHC3571X
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	65427162/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

*1 Reply email Ready.
open Ref
under Buyer
Name
:)*

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Friday, September 06, 2019 1:45 PM
To: 'CWS Motor Claims'
Cc: 'Henry Kao'; SUR
Subject: SURVEY ASSESSMENT - D19005487MFSH/1 VEHICLE NO: SHC3517X
Attachments: SHC3517X DOA 26082019 REVERT.pdf

Dear Sir/Madam

Enclosed preliminary revised of vehicle SHC3517X.
Date of survey : 27/08/2019
Number of days : 7 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, August 27, 2019 1:02 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005487MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 27 August 2019 12:55 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao <HenryKao@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19005487MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

FCI

16375.16

SHC 3517X

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 750.00 600/-
	Spray Painting Charge			\$ 1,000.00 700/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 40/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00 150/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 44
	Transfer of Door		1920.00	\$ 120.00 60/-
	Re-set Frt ABS System			\$ 200.00
	Re-set Frt Power Window System			\$ 200.00 } 280/-
	Re-set and Diagnosis			\$ 550.00
	TOTAL LABOUR			\$ 3,390.00
	ESTIMATE TOTAL			\$ 31,061.16
	27/08/2019 @ 1500hrs NA Actual 2/Sum 9 days. nyan 2kk Actual		18295.16 1/514000/-	
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 3517 X

Technician:

Mileage: 701168

Time Printed 27.8.19 3:35 PM

Mercedes-Benz 212 E class

Front : Left

Actual	BEFORE	Specified Range
-1°02'		-1°07' -0°27'
6°48'		-5°30' 15°30'
2°50'		-0°21' 0°49'
22°19'		
21°17'		
		-2°19' -1°19'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°43'		-1°07' -0°27'
6°55'		-5°30' 15°30'
0°35'		-0°21' 0°49'
13°36'		
12°53'		
		-2°19' -1°19'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°20'		-0°20' 0°20'
-0°06'		-1°30' 1°30'
8°43'		
3°25'		-0°41' 1°39'

Rear : Left

Actual	BEFORE	Specified Range
-1°56'		-1°32' -0°32'
0°22'		-0°05' 0°25'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°26'		-1°32' -0°32'
0°16'		-0°05' 0°25'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-0°30'		-0°30' 0°30'
0°38'		0°05' 0°35'
0°03'		-0°15' 0°15'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19015073/Dyf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-09-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7237C	Veh. Inspected	SHC 3517X
Policy No.		Coverage (\$)	0.00
Claim No.	D19005487MFSH	Excess (\$)	0.00
Assign From	HENRY KAO	Assign Date	27/08/2019
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E 220	c.c	2143
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD2120022A761435	Colour	WHITE
Odometer	701168	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/08/2019	Inspection Date	27/08/2019
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3517X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER ASSY,FRT	BENT / CUT	1,890.50	1,890.50
1	BUMPER BRACKET,FRT/LH	NOT NECESSARY	95.00	-
1	BUMPER INNER CLIP,FRT	NECESSARY	22.00	22.00
1	HEAD LAMP ASSY (LH)	CUT / CRACKED	2,380.00	2,380.00
1	HEAD LAMP BRACKET (LH)	BENT	300.00	300.00
1	HEAD LAMP PANEL (LH)	BENT	480.00	480.00
1	RADIATOR GRILLE	CRACKED	1,220.00	1,220.00
1	FENDER,FRT/LH	BUCKLED	996.08	996.08
1	FENDER SPLASHSHIELD,FRT/LH (FRONT)	DISLODGE	257.00	257.00
1	FENDER SPLASHSHIELD,FRT/LH (REAR)	NOT NECESSARY	263.00	-
1	WHEEL RIM,LH	CUT	1,250.00	1,250.00
1	TYRE 205/60R16 YOKOHAMA,LH	SERVICEABLE	480.00	-
1	WHEEL HUB BEARING,FRT,LH	DAMAGED	1,250.00	1,250.00
1	DOOR SHELL,FRT/LH	DENTED	2,970.00	2,970.00
1	MIRROR HOUSING W/SIGNAL LAMP,FRT/LH	CUT / CRACKED	890.00	890.00
1	S/ABSORBER,FRONT LH	DISTORTED	944.00	944.00
1	STRUT,FRT/LH	NOT NECESSARY	604.00	-
1	STEERING KNUCKLE ARM,FRT/LH	DISLODGE	1,119.00	1,119.00
1	LOWER ARM ASSY,FRT/LH	DISTORTED	661.05	661.05
1	LOWER ARM BOLT	NOT NECESSARY	55.00	-
1	TOP ARM ASSY,FRT/LH	DISTORTED	720.00	720.00
1	TORSION BAR ROD,FRT/LH	DISTORTED	375.00	375.00
1	TORSION BAR FRT/LH	DISTORTED	470.00	470.00
1	ENGINE CROSSMEMBER	NOT NECESSARY	2,985.50	-
2	ENGINE MOUNTING (LH/RH) @\$450.80	NOT NECESSARY	901.60	-
1	P/STEERING GEAR ASSY	NOT NECESSARY	7,167.00	-
	LESS 10% DISCOUNT		-3,074.57	-1,819.46
			27,671.16	16,375.17
LABOUR				
	PANEL BEATING.		750.00	600.00

Report Ref No. CS/FC119015073/Dyf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING CHARGE.	NOT NECESSARY	1,000.00	700.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	40.00
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	FRT WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	-
	TRANSFER OF DOOR.		120.00	60.00
	RE-SET AND DIAGNOSIS }.		550.00	280.00
	RE-SET FRT ABS SYSTEM }.		200.00	-
	RE-SET FRT POWER WINDOW SYSTEM }.		200.00	-
			3,390.00	1,920.00
GRAND TOTAL			31,061.16	18,295.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				14,000.00

Report Ref No. CS/FCI19015073/Dyf3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.