Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19015075/ADA3Q2

Date: 04/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800140227

Claimant

SLR9909H

Insured Vehicle No: GBJ197P

Vehicle No:

Date of Loss: 20/08/2019 Nature of Claim: TP Claim No: 3008562990SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR9909H

Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGHU630445

Reg. Date: 04/09/2017 (Man. Year: 2017) Chassis No: KMHD841CMJU533692

Colour: Blue Odometer: 69631 km

Engine Capacity: 1591 cc
Market Value/New Car
N/A

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Roadstone 6 mm Rear Left Side: Roadstone 6 mm
Front Right Side: Roadstone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,786.00	1,907.60	1,878.40	49.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	530.00	930.00	63.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,246.00	2,437.60	2,808.40	53.53
Approved Total (Overridden) (S\$)		1,950.00		
Nett Amount (S\$)	5,246.00	1,950.00	3,296.00	62.83
Global Sum S	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 26/08/2019

Date Inspected: 26/08/2019 Inspected At: Fong Motors - Kaki Bukit (HQ)

1 KAKI BUKIT AVE 6 #01-27/01-45

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	968.00 F	*475.00 FL
2	1		*FRONT BUMPER FORD LAMP COVER	Cracked	45.00 F	*45.00 FL
3	1		*FRONT BUMPER SIDE RETAINER	Necessary	68.50 F	*68.50 FL
4	8		*FRONT BUMPER CLIP	Necessary	40.00 F	*40.00 FL
5	1		*FRONT FENDER UNDERGARNISH	Not Necessary	118.50 F	*- FL
6	8		*FENDER UNDERGARNISH CLIP	Not Necessary	40.00 F	*- FL
7	1		*FRONT HEAD LAMP	Cut	1,756.00 F	*1,756.00 FL
8	1		*RIM	Not Necessary	750.00 FS	*-FS
F=Fra	anchise	part. S=Spcl	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	3,786.00	2,384.50
- List Item Discount on L Items 0.00/20.00% (S\$)				0.00	476.90	
				Total Parts (S\$)	3,786.00	1,907.60
			Report was unsubmitted during	this print-out.		

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO KNOCK AND CHANGE PARTS	New	700.00	250.00
2	TO SPRAY PAINT THE AFFECTED AREAR	New	600.00	250.00
3	TUFF KOTE	New	80.00	0.00
4	TO CHECK WIRING	New	80.00	30.00
		Gross Labour Cost (S\$)	1,460.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >