

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

KD1123 0030205

MZ EXPRESS
189A RIVERVALE DRIVE
#4-1018
S 541189

TPA 16.
Vic.

Date :29.08.2019
Vehicle No :PC 5681 X
Make/Model :TOYOTA HIACE
Accident date :03.08.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear tailgate camera <i>Not nec</i>	1	\$ 880 X
2	Rear tailgate <i>Dented</i>	1	\$ 2259.7 1955
3	Rear tailgate hinges @ \$ 71.50 <i>Not nec</i>	2	\$ 143 X
4	Rear tailgate upper lock <i>Damaged</i>	1	\$ 288.5 ✓
5	Rear tailgate lower lock <i>Not nec</i>	1	\$ 107.9 X
6	Rear tailgate shock absorber @ \$ 353.40 <i>Not nec</i>	2	\$ 706.8 X
7	Rear tailgate weather strip <i>Not nec</i>	1	\$ 416.8 X
8	Rear tailgate inner board <i>Not nec</i>	1	\$ 288.5 X
9	Rear tailgate centre emblem <i>Not nec</i>	1	\$ 78.8 ✓
10	Rear tailgate handle <i>Not nec</i>	1	\$ 149.6 X
11	Rear tailgate GL emblem <i>2</i>	1	\$ 30.8 ✓
12	Rear tailgate Hiace emblem <i>Not nec</i>	1	\$ 52.8 ✓
13	Rear tailgate 70 km sticker	1	\$ 27.5 10(SN)
14	Rear end inner panel <i>Repair</i>	1	\$ 1739 X
15	Rear end outer panel <i>Dented</i>	1	\$ 579 ✓ 579
16	Rear bumper <i>Deformed</i>	1	\$ 517 ✓ 517
17	Rear bumper reverse sensor (1 set) <i>Damaged</i>	1	\$ 418 200(SN)
18	Rear bumper clips (1 set) <i>Nec</i>	1	\$ 49.5 30
19	Rear bumper lower bracket @ \$ 24.20 <i>Best</i>	4	\$ 96.8 ✓
20	Rear spare tyre carriage <i>3677-50</i>	1	\$ 309.5 X
21	Rear end panel top garnish <i>2758-12</i>	1	\$ 114.2 X
22	Rear bumper side holder @ \$ 24.40 <i>Nec</i>	2	\$ 48.8 ✓
			\$ 9101.1
S.N: 210 Less 25% Disc			\$ 2275.3
Total			\$ 6825.8

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

MZ EXPRESS
189A RIVERVALE DRIVE
#4-1018
S 541189

Date :29.08.2019
Vehicle No :PC 5681 X
Make/Model :TOYOTA HIACE
Accident date :03.08.2019

No	DESCRIPTION	Qty	Amount (\$\$)
Labour Cost			
1	To supply rear end panel sealant		\$ 200 60
2	To supply rear windscreen sealant		\$ 50 ✓
3	Remove & reinstall rear windscreen		\$ 150 120
4	Remove & reinstall reverse sensor	2030	\$ 150 60
5	Remove & reinstall rear camera		\$ 80 60
6	Remove, replace & repair consistent to the accident		\$ 1500 900
7	Respray painting		\$ 1300 700
8	Tuff kote		\$ 100 80
Total			\$ 3530
Grand Total			\$ 10355.8

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 4998.12

H/S: AK ✓

06 Days