11/18/21, 10:14 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC6/AIG19015089/URA3Q2

Date:

18/11/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100337552 SKJ7124Y

Claimant Vehicle No:
Date of Loss:

GBB9179A 20/07/2019 Insured Vehicle No:
Nature of Claim:

TP

Claim No:

6580619559SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBB9179A

Make & Model: NISSAN URVAN, 3.0 5MT ABS AB 5DR LWB PANEL (A)

Engine No: HIDDEN
Chassis No: JN1MG4

Reg. Date: 01/09/2010 (Man. Year: 2010)

Odometer:

JN1MG4E25Z0794205

229593 km

Colour: White

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

195 R15 Austone 6 mm

Front Left Side: Front Right Side: Austone 6 mm
Austone 6 mm

Rear Left Side: Rear Right Side:

Austone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		768.00	0.00	768.00	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		850.00	700.00	150.00	17.65
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	1,618.00	700.00	918.00	56.74
	+ Loss of Use	(4.0 x S\$80.00/day) (S\$)	320.00		

(S\$)	1,020.00
Liable Amount (50.00%) (S\$)	510.00
+ Doc/Search Fee (S\$)	2.00
Nett Liability (S\$)	512.00

INSPECTION

Date of Assignment: 27/08/2019

Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ) Date Inspected:

Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit Inspected At: 28/08/2019

Singapore 417883

Estimated Period of Repair: 2.0 days

MARCUS CHUA Adjuster: Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*REAR BUMPER	Repair	720.00 F	*- F
2 1	*SET REAR BUMPER CLIPS	Repair	48.00 FS	*-FS
F=Franchise part. S=SpcNett.		Total Parts (S\$)	768.00	0.00
	Report w	ras unsubmitted during this print-out.		

11/18/21, 10:14 AM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount
Labour Items			
1 LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	400.00	300.00
2 TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED A	ARE New	450.00	400.00
	Gross Labour Cost (S\$)	850.00	700.00
Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >