

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00

SPRINGLEAF TOWER SINGAPORE 079909

INV No. AC2006487

INV Date 21/09/2020

Reference CC6/CTI19015110/Aba3n2

Code CT



PROFESSIONAL SERVICE FEE

Vehicle No. SJN 3481H

Insured Veh. GBE 2041T

Claim No. SNM19D203949

Policy No. DMCVSN3060071800

Accident Date 22/08/2019

Inspection Date 27/08/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile				
CHIN	A TAIPING INSU	URANCE (S) PTE LTD Ref: CC6/CTI19015110/Aba3n2			
	3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date: 21-09-2020 Code: CTI		
1.		Policy Particulars	- THIRD PARTY CLAIM		
	Insured Veh.	GBE 2041T	Veh. Inspected	SJN 3481H	
	Policy No.	DMCVSN3060071800	Coverage (\$)	0.00	
	Claim No.	SNM19D203949	Excess (\$)	0.00	
	Assign From		Assign Date	27/08/2019	
2.		Vehicle Partic	culars & Condition		
	Make & Model	HONDA FREED	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	GB31033276	Colour	MAROON	
	Odometer	152078	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.		Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	195/60 R15	FALKEN	6 mm	
	L/H Front Tyre	195/60 R15	FALKEN	6 mm	
	R/H Rear Tyre	195/60 R15	FALKEN	6 mm	
	L/H Rear Tyre	195/60 R15	FALKEN	6 mm	
4.		Description	on of Damages		
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA	AR PORTION.		
	DAMAGES SEE DI	ETAILS.			
5.		General	Information		
	Accident Date	22/08/2019	Inspection Date	27/08/2019	
	Survey held at	96 MOTORSPORTS PTE LTD			
		62/64 KAKI BUKIT AVENUE 6 SINGAPORE 417893 ARK @ KB			
5a.		Re	emarks		
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W		REPAIRS.	
5b.	Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	5 Working Days		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 3481H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL GATE	DENTED	1,460.30	1,247.00
1	TAIL GATE BADGE	NECESSARY	67.00	67.00
1	TAIL GATE EMBLEM (FREED)	NECESSARY	82.70	82.70
1	REAR BUMPER	DEFORMED	1,107.90	656.00
1	SIDE RETAINER LH	NECESSARY	126.80	126.80
1	REAR BUMPER ATTACHMENT RETAINER LH	NOT NECESSARY	80.00	-
1	SET REAR BUMPER CLIP	NECESSARY	20.00	20.00
1	REAR BUMPER TOWING CAP	NOT NECESSARY	56.30	-
1	REAR TAIL LAMP LH	CRACKED	879.00	372.00
1	SET REAR TAIL LAMP CLIP	NECESSARY	30.00	30.00
1	REAR SIDE TOP FENDER LH	NOT NECESSARY	620.00	-
1	END PANEL	TO REPAIR SEE LABOUR	590.80	-
1	END PANEL TOP TRIM	NOT NECESSARY	125.00	-
1	SET END PANEL TOP TRIM CLIP	NOT NECESSARY	40.00	-
	LESS 20% DISCOUNT		-1,057.16	-520.30
			4,228.64	2,081.20
2	REAR BUMPER REVERSE SENSOR L+R (ORIGINAL)(SN)	DAMAGED	500.00	200.00
	LESS 20% DISCOUNT		-100.00	-
			400.00	200.00
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
			100.00	60.00
	<u>LABOUR</u>			
	TO KNOCK,STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF END PANEL.		1,200.00	600.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.		1,000.00	600.00
	TO RUST PROOF ACCIDENT AFFECTED AREA.	NOT NECESSARY	120.00	-

Report Ref No. CC6/CTI19015110/Aba3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO R&R REVERSE SENSOR FUNCTION.		120.00	50.00
	TO R&R BOOT MECH.		120.00	80.00
	TO R&R REAR WINDSCREEN.		150.00	120.00
			2,710.00	1,450.00
	GRAND TOTAL		7,438.64	3,791.20

RECOMMENDED COST OF LUMP SUM REPAIRS		3,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/CTI19015110/Aba3n2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R


PHOTOGRAPHS FOR VEHICLE NO. SJN 3481H

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



