



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 2096Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (TOP) (CONSISTENT) (N)	DENTED / CRACKED	765.00	765.00
1	HEADLAMP LH (CONSISTENT) (N)	CUT	2,836.00	2,836.00
1	FRONT LH FENDER (CONSISTENT) (N)	BENT	635.00	635.00
1	FRONT LH WHEEL ARP GARNISH (CONSISTENT) (N)	DENTED	185.00	185.00
1	BONNET LOGO (CONSISTENT) (N)	NECESSARY	89.00	89.00
			4,510.00	4,510.00
	<u>LABOUR</u>			
	REMOVE AND REFIT FRT BUMPER ASSY ,HEADLAMPS ,FOGLAMPS,GRILLE,FRT LH FENDER ,KNOCK AND REPAIR FRT BUMPER REINFORCEMENT AND REALIGN THE SAME.		600.00	500.00
	PUTTY AND RESPRAY ON BONNET ,FRT LH FENDER ,FRT BUMPER AND OTHER AFFECTED AREAS.		750.00	660.00
	REMOVE AND REFIT FRT LH SPORTS RIM ,REPAIR BALANCING ,PUTTY & RESPRAY .	NOT NECESSARY	100.00	-
	TO CHECK FRT LH UNDERCARRIAGE AND CONDUCT COMPUTER WHEEL ALIGNMENT.		60.00	60.00
	RUSTPROOFING.		30.00	30.00
			1,540.00	1,250.00
GRAND TOTAL			6,050.00	5,760.00
RECOMMENDED COST OF REPAIRS				5,760.00

Report Ref No. CC4/ASM19015116/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.