



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19015116/Kpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 29-06-2020



ATTN:RICHARD

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 145L	Veh. Inspected	SKF 2096Z
Policy No.	GA294673	Coverage (\$)	0.00
Claim No.	S9M01YF1	Excess (\$)	0.00
Assign From		Assign Date	19/09/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. X1 (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WBAVL32030VP94309	Colour	METALLIC GREY
Odometer	133649	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	GOODYEAR	6 mm
L/H Front Tyre	225/50 R17	GOODYEAR	6 mm
R/H Rear Tyre	225/50 R17	GOODYEAR	6 mm
L/H Rear Tyre	225/50 R17	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/08/2019	Inspection Date	19/09/2019
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------