

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19015121/ABA3Q2

Date: 27/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994044

Claimant
Vehicle No : SMF1110Z **Insured Vehicle No :** SKB5740Z

Date of Loss: 24/08/2019 Nature of Claim: TP Claim No: 7606470787SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF1110Z	Engine No:	G4FGJH709490
Make & Model:	KIA CERATO, 1.6 EX (A)	Chassis No:	KNAF3416MK5020198
Reg. Date:	27/11/2018 (Man. Year: 2018)	Odometer:	20372 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,587.13	3,085.35	1,501.78	32.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	1,280.00	1,690.00	56.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	7,557.13	4,365.35	3,191.78	42.24
Approved Total (Overridden) (\$)		3,450.00		
(\$)	7,557.13	3,450.00	4,107.13	54.35
+ GST 7.00/7.00% (\$)	529.00	241.50	287.50	54.35
Nett Amount (\$)	8,086.13	3,691.50	4,394.63	54.35
+ Loss of Use (5.0 x \$60.00/day) (\$)		300.00		
+ Doc/Search Fee (\$)		7.45		
Nett Liability (\$)		3,998.95		
Global Sum Settlement (\$)		3,950.00		

INSPECTION

Date of Assignment: 26/08/2019

Date Inspected: 26/08/2019 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	890.30 FL	*890.30 FL
2	1		*BOOT LID LOGO	Necessary	80.00 FL	*80.00 FL
3	1		*BOOT LID EMBLEM FORTE	Necessary	66.00 FL	*66.00 FL
4	1		*BOOT LID EMBLEM CYCLE & CARRIAGE	Necessary	68.00 FL	*68.00 FL
5	1		*BOOT LID LOCK	Not Necessary	190.00 FL	*- FL
6	1		*BOOT LID WEATHERSTRIP	Not Necessary	184.00 FL	*- FL
7	1		*REAR BUMPER	Deformed	822.60 FL	*688.00 FL
8	1		*REAR BUMPER LOWER LIP	Deformed	360.00 FL	*360.00 FL
9	2		*REAR BUMPER SIDE RETAINER	Necessary	179.20 FL	*179.20 FL
10	1		*REAR BUMPER REFLECTOR	Cracked	233.50 FL	*233.50 FL
11	1		*REAR BUMPER REFLECTOR HOUSING	Cut	98.50 FL	*98.50 FL
12	1		*REAR BUMPER REINFORCEMENT	Cracked	498.00 FL	*318.00 FL
13	2		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	191.00 FL	*- FL
14	1		*REAR END PANEL	Repair	544.60 FL	*- FL
15	1		*REAR END PANEL TOP GARNISH	Deformed	180.00 FL	*180.00 FL
16	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
17	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
18	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
19	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	20.00 FS	*20.00 FS
20	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,045.70	3,401.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	458.57	316.15
Total Parts (\$\$)	4,587.13	3,085.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,WELDING GRAZING ,CUT ,JOINT ,STRAIGHTEN ALL AFFECTED PARTS	New	1,200.00	600.00
2	TO PUTTY,POLISH ,SPRAY PAINT ,WAX ALL AFFECTED PANELS	New	1,200.00	600.00
3	TUFF COAT	New	250.00	0.00
4	WIRING CHECK	New	120.00	30.00
5	TRANSFER BOOTLID MECHANISM	New	80.00	0.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	120.00	50.00
Gross Labour Cost (S\$)			2,970.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >