

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19015124/ABA3Q2

Date: 15/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMC6582C **Insured Vehicle No :** SKK5826M

Date of Loss: 20/08/2019 **Nature of Claim:** TP **Claim No:** 0737187149SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC6582C		
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Engine No:	G4FGJU205875
Reg. Date:	14/07/2018 (Man. Year: 2018)	Chassis No:	KMHD841CMJU704609
Colour:	Red	Odometer:	31636 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,026.00	3,535.60	5,490.40	60.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	1,110.00	1,130.00	50.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,266.00	4,645.60	6,620.40	58.76
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	11,266.00	3,700.00	7,566.00	67.16
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,407.45		
Global Sum Settlement (S\$)		4,400.00		

INSPECTION

Date of Assignment: 27/08/2019

Date Inspected: 27/08/2019 Inspected At:

Best Solution Autocare Pte Ltd (HQ)
53 UBI AVE 1 #03-01 PAYA UBI
INDUSTRIAL PARK
Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	585.00 F	*585.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	695.00 F	*- FL
3	1		*FRONT BUMPER LOWER LIP	Not Necessary	302.00 F	*- FL
4	1		*FRONT GRILLE	Not Necessary	1,082.00 F	*- FL
5	1		*O/S FRONT BUMPER SIDE RETAINER	Necessary	68.00 F	*68.00 FL
6	1		*O/S FOG LAMP	Cracked	295.00 F	*295.00 FL
7	1		*O/S FOG LAMP GARNISH	Deformed	65.00 F	*65.00 FL
8	1		*O/S FOG LAMP CHROME COVER	Not Necessary	155.00 F	*- FL
9	1		*O/S HEAD LAMP	Cut	1,886.00 F	*1,886.00 FL
10	1		*O/S HEAD LAMP LOWER BRACKET	Not Necessary	95.00 F	*- FL
11	1		*O/S FRONT FENDER	Dented	985.00 F	*520.50 FL
12	1		*O/S FRONT FENDER INNER SHIELD	Deformed	115.00 F	*115.00 FL
13	1		*SET O/S FRONT FENDER INNER SHIELD CLIP	Necessary	40.00 F	*30.00 FL
14	1		*O/S FRONT SPORT RIM	Cut	680.00 FS	*480.00 FS
15	1		*O/S FRONT TYRE	Cut	250.00 FS	*180.00 FS
16	1		*O/S FRONT SHOCK ABSORBER	Not Necessary	395.00 F	*- FL
17	1		*O/S FRONT LOWER ARM	Not Necessary	356.00 F	*- FL
18	1		*O/S FRONT KNUCKLE ARM	Not Necessary	435.00 F	*- FL
19	1		*O/S FRONT KNUCKLE ARM BEARING	Not Necessary	482.00 F	*- FL
20	1		*SET FRONT BUMPER CLIP	Necessary	30.00 F	*30.00 FL
21	1		*SET FRONT GRILLE CLIP	Not Necessary	30.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,026.00	4,254.50
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	718.90
Total Parts (\$\$)	9,026.00	3,535.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE DAMAGED PARTS ,PANEL BEAT ,REPAIR	New	800.00	500.00
2	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREA	New	700.00	500.00
3	AIR CON	New	80.00	0.00
4	WIRING	New	50.00	30.00
5	ANTI RUST	New	150.00	0.00
6	UNDERCARRIAGE	New	250.00	0.00
7	WHEEL ALIGNMENT	New	150.00	80.00
8	TOWING	New	60.00	0.00
Gross Labour Cost (\$\$)			2,240.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >