



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## General Details

Involving	1 2013 MERCEDES E250 (SKM9402R)
Date of Loss	23 August 2019
Time of Loss	18.15
Loss Description	SKM9402R (INSD) HIT REAR OF SLH6423P (TP)
Comment	

## Workshop Details

Total Rebate Amount	85962
Nett Loss Amount	\$34,038.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	20



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### Vehicle & Driver Details

Vehicle Registration# SKM9402R

Registration State SINGAPORE

Mileage 85886

Purchase Date dd/mm/yyyy

Registration Date \* 25/04/2014

Age of Vehicle 5

CATEGORY

POLICY INFORMATION

ASSESSMENT  
INFORMATION

Manufacturing  
Year

2013

2013

Make

MERCEDES

MERCEDES BI

### Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY  
INFORMATION

Driver Name



TAN HUI SEE

Date of Birth

13 August 1963

dd/mm

Model CATEGORY	E250 POLICY INFORMATION	E250 A INFORMATION
Type		<input type="text"/>
Type of Paint		<input type="text"/>
Chassis No	WDD2074472F212820	<input type="text" value="WDD2074472"/>
Engine No	27186030634292	<input type="text" value="27186030634"/>
Engine Capacity		<input type="text" value="1796"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="120000"/>

CATEGORY Age	FNOL INFORMATION 56	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text"/>
Driving Experience	14	
Driver License #		<input type="text"/>
License Type		<input type="text"/>
License Issue Date		<input type="text" value="dd/mm"/> 
License Expiration Date		<input type="text" value="dd/mm"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address	3 FLORA DRIVE, #01-16 DAHLIA PARK CONDOMINIUM, 507010, Singapore	<input type="text"/>
Address type	Residential	<input type="text" value="▼"/>
Gender	Female	<input type="text" value="▼"/>
Marital status	Married	<input type="text" value="▼"/>
Identification #	S1582348H	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

28/08/2019

Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver  
Excess

0

### Condition of Vehicle at time of survey

General condition

Fair

▼

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair

▼

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save





<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary













Parts























Add





















Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		FRONT BUMPER (WCP) (10%)	Dented	0	990	No					990	Reviewing
		0	1		FRONT BONNET (WCP) (10%)	Dented	0	1320	No					1320	Reviewing
		0	1		FRONT TOWING COVER (WCP) (10%)	Damaged	0	66	No					66	Reviewing
		0	2		FRONT PARKING SENSOR	Serviceable	0	0	No					0	Deny
		0	1		FRONT HEADLAMP WASHER COVER LH	Serviceable	0	0	No					0	Deny
		0	1		FRONT HEADLAMP WASHER COVER RH (WCP) (10%)	Missing	0	104.5	No					104.5	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		FRONT HEADLAMP WASHER NOZZLE	Serviceable	0	0	No					0	Deny
		0	2		FRONT HEADLAMP (WCP) (10%)	Broken	0	1100	No					2200	Reviewing
		0	1		FRONT GRILLE INNER BASE (WCP) (10%)	Broken	0	63.8	No					63.8	Reviewing
		0	1		FRONT BONNET STAR EMBLEM (WCP) (10%)	Broken	0	69.3	No					69.3	Reviewing
		0	1		FRONT NUMBER PLATE HOUSING (WCP) (10%)	Damaged	0	112.2	No					112.2	Reviewing
		0	2		BONNET LOCK (WCP) (10%)	Bent	0	27.5	No					55	Reviewing
		0	2		BONNET SPRING (WCP) (10%)	Broken	0	12.1	No					24.2	Reviewing
		0	1		BONNET DAMPER	Serviceable	0	0	No					0	Deny
		0	1		RADIATOR TOP COVER (RUBBER)	Serviceable	0	0	No					0	Deny
		0	1		RADIATOR SUPPORT PANEL (WCP) (10%)	Dented	0	170.5	No					170.5	Reviewing
		0	1		INTERCOOLER (WCP) (10%)	Bent	0	407	No					407	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		CONDENSOR (WCP) (10%)	Bent	0	605	No					605	Reviewing
		0	1		RADIATOR (WCP) (10%)	Broken	0	803	No					803	Reviewing
		0	1		OUTSIDE TEMPERATURE SENSOR (WCP) (10%)	Shorted	0	38.5	No					38.5	Reviewing
		0	1		FRONT RADIATOR UNDER CARRIAGE	Serviceable	0	0	No					0	Deny
		0	1		FRONT REINFORCEMENT CENTER SUPPORT (WCP) (10%)	Dented	0	184.8	No					184.8	Reviewing
		0	1		BONNET COVER SPONGE	Serviceable	0	0	No					0	Deny
		0	1		FRONT BUMPER LOWER GRILLE (WCP) (10%)	Broken	0	118.8	No					118.8	Reviewing
		0	1		FRONT LED FOGLAMP RH	Serviceable	0	0	No					0	Deny
		0	1		FRONT LED FOGLAMP COVER	Serviceable	0	0	No					0	Deny
		0	1		BONNET HANDLE	Serviceable	0	0	No					0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		BONNET CABLE	Serviceable	0	0	No					0	Deny
		0	1		FRONT REINFORCEMENT (WCP) (10%)	Dented	0	209	No					209	Reviewing
		0	1		FRONT BUMPER INNER SUPPORT (WCP) (10%)	Broken	0	112.2	No					112.2	Reviewing
		0	1		FRONT GRILLE CHROME ASSY (WCP) (10%)	Broken	0	550	No					550	Reviewing
		0	1		FRONT GRILLE STAR EMBLEM (WCP) (10%)	Broken	0	99	No					99	Reviewing
		0	1		FRONT BUMPER CLIP EACH-8PCS (WCP) (10%)	Necessary	0	2.2	No					2.2	Reviewing
		0	1		FRONT BUMPER SPONGE (WCP) (10%)	Broken	0	132	No					132	Reviewing

Labour

Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
		0		TO FIX & DISMANTLE AND REMOVE DAMAGED FRONT AND REAR PORTIONS	0	500	0	0	Reviewing	

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
		0		WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT	0	0	0	0	Deny	
		0		SPRAY PAINTING FOR FRONT AND REAR PORTIONS AFFECTED PARTS	0	500	0	0	Reviewing	
		0		DIAGNOSE ECU SYSTEM AND RESET ERROR CODE	0	100	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	DAYS OF REPAIR : 5 DAYS	Reviewing	0		
		0	FRONT CAR PLATE }	Reviewing	35	CUT	
		0	FRONT CAR PLATE HOLDER }	Reviewing	0	CUT	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
------	----------	------	--------	---------------------	--------------------	---------	--------



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$9,572.00		
CATEGORY	ESTIMATE	ADJUSTED					
Spare Parts	\$0.00	\$8,437.00					
Labour	\$0.00	\$1,100.00					
Miscellaneous	\$0.00	\$35.00					

Submit for Review





SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	FINAL LUMP SUM	Reviewing	7500		



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$7,500.00

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$7,500.00

Submit for Review