

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19015168/R1GA3N2

**Date:** 20/05/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SMH2121A	<b>Insured Vehicle No :</b>	SHA4352H
Date of Loss: 27/08/2019	Nature of Claim: TP	Claim No: MCT19080716

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH2121A	Engine No:	13737827N52B25AF
Make & Model:	BMW 325CI, 2.5 (A)	Chassis No:	WBADW32050E486898
Reg. Date:	19/08/2011 (Man. Year: 2011)	Odometer:	121539 km
Colour:	Red		
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	255/35Z R18	Rear Tyre Size:	255/35Z R18
Front Left Side:	Sumitomo 6 mm	Rear Left Side:	Sumitomo 6 mm
Front Right Side:	Sumitomo 6 mm	Rear Right Side:	Sumitomo 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	20,434.75	2,769.85	17,664.90	86.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,170.00	1,040.00	4,130.00	79.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>25,604.75</b>	<b>3,809.85</b>	<b>21,794.90</b>	<b>85.12</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,050.00</b>		
<b>Nett Amount (S\$)</b>	<b>25,604.75</b>	<b>3,050.00</b>	<b>22,554.75</b>	<b>88.09</b>
<b>+ Loss of Use (8.0 x S\$80.00/day) (S\$)</b>		640.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,697.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,650.00</b>		

### INSPECTION

Date of Assignment:	28/08/2019		
Date Inspected:	28/08/2019	Inspected At:	AMA AUTOCARE PTE. LTD. 42 TOH GUAN ROAD EAST #01-79 ENTERPRISE HUB SINGAPORE 608583
Estimated Period of Repair:	4.0 days		

**Adjuster:** MOHD RASUL**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 30 Apr 2020)	
<b>Parts:</b>	N/A	BMW 325CI 2.5 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMH2121A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,278.00 FL	*1,450.00 FL
2	1		*REAR LOWER BUMPER	Cut	963.00 FL	*423.00 FL
3	1		*REAR BUMPER UNDER COVER	Serviceable	642.00 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER L/R	Serviceable	277.60 FL	*- FL
5	2		*REAR INNERSHIELD L/R	Serviceable	520.00 FL	*- FL
6	1		*BOOTLID	Repair	2,430.00 FL	*- FL
7	1		*BOOTLID BMW LOGO BADGE	Not Necessary	520.00 FL	*- FL
8	1		*BOOTLID INNER TRIM	Serviceable	725.00 FL	*- FL
9	1		*BOOTLID MECHANISM LOCK	Serviceable	139.40 FL	*- FL
10	2		*BOOTLID HINGES	Serviceable	588.00 FL	*- FL
11	1		*BOOTLID WEATHERSTRIP	Serviceable	472.00 FL	*- FL
12	1		*REAR FENDER LHS	Serviceable	1,644.00 FL	*- FL
13	1		*TAILLAMP LHS	Serviceable	1,565.00 FL	*- FL
14	1		*TAILLAMP REFLECTOR LHS	Cracked	970.00 FL	*270.00 FL
15	1		*REAR REINFORCEMENT	Bent	1,080.00 FL	*520.00 FL
16	1		*REAR END PANEL	Repair	1,763.00 FL	*- FL
17	1		*REAR END PANEL OUTER BRACKET	Serviceable	292.00 FL	*- FL
18	1		*REAR END PANEL TOP GARNISH	Serviceable	678.00 FL	*- FL
19	1		*REAR EXHAUST SILENCER ASSEMBLY	Serviceable	1,850.00 FL	*- FL
20	1		*REAR EXHAUST SILENCE HEAT SHIELD	Serviceable	610.00 FL	*- FL
21	2		*REAR EXHAUST SILENCER ASSEMBLY MONTINGS	Serviceable	298.00 FL	*- FL
22	1		*SET REAR BUMPER CLIPS	Necessary	120.00 FS	*40.00 FS
23	1		*REVERSE SENSOR	Not Working	420.00 FS	*200.00 FS
24	1		*LHS REAR FENDER GLASS SEALANT	Not Necessary	120.00 FS	*- FS
25	1		*REAR INNERSHIELD CLIPS	Not Necessary	60.00 FS	*- FS
26	1		*SET BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
27	1		*BOOTLID WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
28	1		*REAR END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
29	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>21,450.00</b>	<b>2,903.00</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b>	1,015.25	133.15
<b>Total Parts (\$\$)</b>	<b>20,434.75</b>	<b>2,769.85</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	2,000.00	400.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED	New	1,800.00	500.00
3	TO REMOVE ,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION	New	220.00	0.00
4	TO REMOVE/REFIT INNER TRIMS ,FITTINGS ,GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR	New	200.00	60.00
5	TO REMOVE AND REFIX LHS REAR FENDER GLASS	New	150.00	0.00
6	TO REMOVE AND REFIX REAR BOOTLID WINDSCREEN GLASS	New	220.00	0.00
7	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTION	New	120.00	60.00
8	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	210.00	20.00
9	TO REMOVE AND REPLACE REAR EXHAUST SILENCER ASSEMBLY ,REALIGN TO FIT AND CHECK SYSTEM FUNCTION	New	250.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,170.00</b>	<b>1,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >