

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 2613B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOTLID (CONSISTENT)	DENTED	1,564.00	1,564.00
1	BOOTLID LOGO (CONSISTENT)	NECESSARY	112.00	86.40
1	BOOTLID EMBLEM 'A3' (CONSISTENT)	NECESSARY	42.00	42.00
1	BOOTLID WEATHERSTRIP (CONSISTENT)	DISTORTED	235.00	235.00
4	BOOTLID STOPPER @\$28.00 (CONSISTENT)	SERVICEABLE	112.00	-
1	BOOTLID SENSOR (CONSISTENT)	BROKEN	850.00	140.97
1	BOOTLID LOCK ASSEMBLY (CONSISTENT)	NOT NECESSARY	225.00	-
1	BOOTLID OUTER HANDLE (CONSISTENT)	SERVICEABLE	274.00	-
1	BOOTLID INNER TRIM (CONSISTENT)	SERVICEABLE	312.00	-
1	BOOTLID INNER TRIM COVER (CONSISTENT)	NOT APPLICABLE	186.00	-
2	BOOTLID LAMP @\$1841.00 (CONSISTENT)	SCRATCHED	765.20	425.00
1	REAR FENDER (CONSISTENT)	SERVICEABLE	1,841.00	-
1	REAR FENDER AIR VENT (CONSISTENT)	NOT NECESSARY	183.50	-
1	REAR FENDER INNER COWLING (CONSISTENT)	SERVICEABLE	248.00	-
1	REAR FENDER INNER TRIM (CONSISTENT)	SERVICEABLE	270.00	-
1	REAR FENDER QUARTER GLASS MOULDING (CONSISTENT)	SERVICEABLE	68.50	-
1	REAR FENDER QUARTER GLASS GARNISH (CONSISTENT)	SERVICEABLE	102.30	-
1	REAR BUMPER (CONSISTENT)	DENTED	1,664.00	1,434.40
1	REAR BUMPER LOWER (CONSISTENT)	DISLODGE	385.30	385.30
2	REAR BUMPER BRACKET @\$68.00 (CONSISTENT)	BROKEN	136.00	136.00
2	REAR BUMPER RETAINER @\$75.00 (CONSISTENT)	NECESSARY	150.00	150.00
1	REAR BUMPER TOW COVER (CONSISTENT)	DISLODGE	85.00	50.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	DENTED	693.00	693.00
1	REAR BUMPER REINFORCEMENT BRACKET (CONSISTENT)	NOT APPLICABLE	147.50	-
1	REAR BUMPER REFLECTOR (CONSISTENT)	BROKEN	88.50	88.50
1	REAR END PANEL (CONSISTENT)	DENTED	625.00	625.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	SERVICEABLE	266.00	-
2	TAILLAMP @\$1200.00 (CONSISTENT)	BROKEN	2,400.00	1,784.06
1	SPARE TYRE PANEL (CONSISTENT)	SERVICEABLE	871.40	-

Report Ref No. CC4/ASM19015181/Bbs3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	EXHAUST MUFFLER (CONSISTENT)	TO REPAIR SEE LABOUR	230.80	-
4	REVERSE SENSOR @\$200.00 (CONSISTENT)	CUT (2 PCS ONLY)	800.00	400.00
	LESS 5% DISCOUNT		-796.65	-411.98
			15,136.35	7,827.65
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)(CONSISTENT)	NOT APPLICABLE	60.00	-
1	REAR BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	50.00	30.00
1	REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	SERVICEABLE	50.00	-
1	REAR FENDER INNER COWLING CLIPS (SN) (CONSISTENT)	SERVICEABLE	50.00	-
1	REAR FENDER INNER TRIM CLIPS (SN)(CONSISTENT)	SERVICEABLE	50.00	-
1	TAILLAMP CLIPS (SN)(CONSISTENT)	NECESSARY	50.00	30.00
1	TAILLAMP INNER SEAL (SN)(CONSISTENT)	NOT APPLICABLE	80.00	-
1	REAR END PANEL SEALANT (SN)(CONSISTENT)	NECESSARY	100.00	30.00
1	SPARE TYRE PANEL SEALANT (SN)(CONSISTENT)	NOT NECESSARY	100.00	-
			590.00	90.00
	<u>LABOUR</u>			
	R&R REVERSE SENSOR .		100.00	60.00
	R&R BOOTLID COMPONENT.		100.00	80.00
	R&R EXHAUST SYSTEM TO ASSIST REPAIR .	NOT NECESSARY	180.00	-
	RUST PROOFING .		100.00	30.00
	PANEL BEAT REAR .INCLUSIVE OF THE REPAIR OF EXHAUST MUFFLER.		1,200.00	800.00
	SPRAY PAINTING REAR .		1,200.00	800.00
	BOOTLID WATER LEAKING TEST.	NOT NECESSARY	80.00	-
	SPARE REVERSE SENSOR .		50.00	50.00
	RESETTING OF FAULT CODE.	NOT NECESSARY	80.00	-
	RUST PROOFING REAR.		150.00	30.00
			3,240.00	1,850.00
	GRAND TOTAL		18,966.35	9,767.65

Report Ref No. CC4/ASM19015181/Bbs3q2



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS		7,850.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM19015181/Bbs3q2

**LIM TEOW GUAN** 

**Automotive Assessor** 

Amonto

HO LEONG CHUAN

**Automotive Assessor**