



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2003219
INV Date 16/04/2020
Reference CC3/CTI19015195/K1ea3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SH 8440T
Insured Veh. SJN 8531P
Claim No. SNM19D204054
Policy No. DMPCSN3022521900
Accident Date 25/08/2019
Inspection Date 27/08/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI19015195/K1ea3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 16-04-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 8531P	Veh. Inspected	SH 8440T	
Policy No.	DMPCSN3022521900	Coverage (\$)	0.00	
Claim No.	SNM19D204054	Excess (\$)	0.00	
Assign From		Assign Date	27/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU003560808	Colour	BLUE	
Odometer	244179	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DAVANTI	7 mm	
L/H Front Tyre	195/65 R15	DAVANTI	7 mm	
R/H Rear Tyre	195/65 R15	DAVANTI	7 mm	
L/H Rear Tyre	195/65 R15	DAVANTI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/08/2019	Inspection Date	27/08/2019	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8440T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TRUNK LID COVER	BUCKLED	1,126.60	1,126.60
1	REAR TRUNK LID LOCK	SERVICEABLE	457.90	-
1	REAR TRUNK LID GLASS (BLACK COLOR)	NECESSARY	733.50	733.50
1	GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	TO REPAIR SEE LABOUR	889.70	-
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (HYRID)	NECESSARY	52.90	52.90
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	47.00	47.00
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER REINFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER UNDER COVER	DEFORMED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	602.10	-
1	REAR END PANEL GARNISH	SERVICEABLE	165.80	-
1	REAR TRUNK LID W/SCREEN GLASS (ADDITIONAL)	NECESSARY	1,569.70	1,569.70
	LESS 25% DISCOUNT		-1,790.70	-1,233.65
			5,372.10	3,700.95
<u>SPECIAL NETT ITEMS</u>				
1	REAR NO.PLATE WITH TRIM COVER (SN)	CRACKED	100.00	55.00
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO.STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
			335.70	290.70
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE AND REAR END PANEL .		800.00	400.00
	SPRAY PAINTING CHARGE.		900.00	600.00
	WIRING CHARGE.		50.00	20.00

Report Ref No. CC3/CTI19015195/K1ea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.		50.00	20.00
	REMOVE/REFIX REVERSE SENSOR .		80.00	30.00
			1,880.00	1,070.00
GRAND TOTAL			7,587.80	5,061.65
RECOMMENDED COST OF REPAIRS				5,061.65

Report Ref No. CC3/CT19015195/K1ea3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.