

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 9370P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR COVER BUMPER (WCP) (CONSISTENT)	CRACKED	350.00	350.00
1	LWR T-GATE MOULDING (WCP) (CONSISTENT)	CUT	160.00	160.00
1	REAR CROSSMEMBER (WCP) (CONSISTENT)	SERVICEABLE	280.00	-
1	REAR BUMPER REP SET (WCP) (CONSISTENT)	SERVICEABLE	30.00	-
1	REAR NUMBER PLATE (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	L/R OUT PARK AID SEN (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	R/R OUT PARK AID SEN (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	L/R IN PARK SYS SENS (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	R/R IN PARK SYS SENS (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	RR SENSOR BRKT SET (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	BOOTLID / TAILGATE (WCP) (CONSISTENT)	BENT	1,150.00	1,150.00
1	TAILGATE SEAL (WCP) (CONSISTENT)	NECESSARY	85.00	85.00
1	TAILGATE LOCK (WCP) (CONSISTENT)	SERVICEABLE	45.00	-
1	REAR BADGE -VW- (WCP) (CONSISTENT)	NOT NECESSARY	50.00	-
1	L/R BADGE (WCP) (CONSISTENT)	NOT NECESSARY	35.00	-
1	R/R UPPER BADGE (WCP) (CONSISTENT)	NOT NECESSARY	38.00	-
1	REAR SCREEN BOND KIT (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	RR-SCREEN ACTIVATOR (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	CLEANING SOLUTION (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR SCREEN PRIMER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	APPLICTOR (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	APPLICATOR (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR SCREEN PRIMER (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	L/R LAMP (WCP) (CONSISTENT)	SERVICEABLE	100.00	-
1	L/R REFLECTOR (WCP) (CONSISTENT)	CRACKED	25.00	25.00
1	TAILGATE TRIM (WCP) (CONSISTENT)	CRACKED	45.00	45.00
1	HI-LEVEL BRAKELAMP (WCP) (CONSISTENT) (ADDITIONAL)	NECESSARY	70.00	70.00
1	RR BUMPER CLAMP KIT (WCP) (CONSISTENT) (ADDITIONAL)	NECESSARY	6.00	6.00

Report Ref No. CC4/ASM19015212/R1ga3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

3,501.85

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	COST PLUS 15%		370.35	283.65
			2,839.35	2,174.65
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN) (CONSISTENT)	SCRATCHED	35.00	35.00
1	REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	250.00	-
1	WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
			325.00	75.00
	LABOUR			
	TO APPLY ANTI RUST COATING.		100.00	50.00
	TOTAL LABOUR.		423.00	409.50
	PAINT WORK: LABOUR COST.		531.00	531.00
	PAINT WORK: MATERIAL COST.		248.20	248.20
	UNDERBODY SEALER.		13.50	13.50
			1,315.70	1,252.20
	GRAND TOTAL		4,480.05	3,501.85

Report Ref No. CC4/ASM19015212/R1ga3s2

MOHAMMED RASUL BIN MOHD YUNUS

RECOMMENDED COST OF REPAIRS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor