



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19015212/R1ga3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: PETER WANG			Date : 14-08-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJQ 6446A	Veh. Inspected	SLV 9370P	
Policy No.	VPA/P2090407	Coverage (\$)	0.00	
Claim No.	S9M01YLV	Excess (\$)	0.00	
Assign From	PETER WANG	Assign Date	28/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN CADDY 1.4	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WV2ZZZ2KZJX054074	Colour	BLUE	
Odometer	38417	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/50 R17	GOODYEAR	6 mm	
L/H Front Tyre	205/50 R17	GOODYEAR	6 mm	
R/H Rear Tyre	205/50 R17	GOODYEAR	6 mm	
L/H Rear Tyre	205/50 R17	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/08/2019	Inspection Date	04/09/2019	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		