

Cecilia

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference:
Repairer Reference: SLV9370P TP AXA
Date calculated: 29/08/2019 9:39 AM

Full Report
Registration: SLV9370P
Printed: 29/08/2019 10:03 AM

Summary Information

Claim		Work Provider:	AXA Insurance Pte Ltd
Location:	Singapore (SG)	Currency:	SGD
Printed by:	DARREN SNG	Date of Incident:	26/08/19
Claim Reference:		Hire Car Start:	
Estimated Repair Time:		Hire Car End:	
Actual Repair Days:			

Vehicle Details

Vehicle			
Manufacturer:	VW		
Model:	CADDY IV (TYP SA)		
Sub Model:	HIGHLINE		
Model Sheet Number:	06 CL 06		
Registration:	SLV9370P		
VIN number:	WV2ZZZ2KZX054074		
Odometer:			
Model Specs			
FROM 09/2017	S/PAN/SLDG DOOR WDW	S/PAN/SLDG DOOR WDW	INSTR PANEL COMFORT
AUTO LIGHT CONTROL	PARKING AID/CAMERA	CLIMATRONIC	ELECTRIC WINDOWS
VEH W/PASS CAR REGIS	REAR SCREEN	ELEC/HEATED D/MIRROR	WIPER/RAIN SENSOR
RADIO "COMP MEDIA"	6 SPEAKER	PHONE PREPARATION	FOG LAMPS
XENON/CORNERING LAMP	HEADLAMP WASHERS	DIPPING INNER MIRROR	REAR WIPER
LEATHER-/ALCANT CVR	FRT HEIGHT ADJ SEATS	HEATED FRONT SEATS	2 SEAT CUSH 2ND ROW
DRIVER'S SEAT COMF	PASS SEAT COMFORT	TRIM COMFORT	START & STOP SYSTEM
LUGGAGE COMP COVER	ARMREST W/LONGIT ADJ	1.4 LTR 92KW	7-SPEED DSG
BLUE MOTION TECHNO	ALTERNATOR 140A	DEACTIVATED P/AIRBAG	STRG WHEEL LEATHER
CRUISE CONTROL	TYRES 205/55 HR 16	WHEELS 6J X 16	WHEELBASE LONG
HD COOLING	SPARE WHEEL	B-REST FOLDING TABLE	EMISSION STD EURO 6
SIDE AIRBAGS	FRONT BRAKE 312 X 25	ROOF RAILS	L/SLIDING DOOR
R/SLIDING DOOR	SPORTS SUSP 16 INCH	PAINTED BUMPER	TWO COAT METALLIC
PREPARE OFF VEHICLE			

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference:
 Repairer Reference: SLV9370P TP AXA
 Date calculated: 29/08/2019 9:39 AM


Full Report
 Registration: SLV9370P
 Printed: 29/08/2019 10:03 AM

Vehicle Condition

Vehicle Status
 Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
55 59 19 00	R + R TAILGATE INCLUDES: R + R TAILGATE TRIM, DETACHED HARNESS. ADJUST TAILGATE.		13.0	58.50
55 59 55 55	REPLACE TAILGATE (WITH UNIT REMOVED) INCLUDES: REMOVE/REFIT ALL COMPONENT PARTS		22.0	99.00
94 31 19 00	R + R LEFT TAIL LAMP		2.0	9.00
55 70 19 00	R + R REAR CLOSURE RUBBER SEAL		3.0	13.50
63 69 19 06	R + R REAR BUMPER COVER		8.0	36.00
63 69 55 65	RENEW REAR BUMPER (REAR BUMPER REMOVED AND DRILLED) INCLUDES: PARKING HELP SYSTEM SENSORS REMOVE AND REFIT.		13.0	58.50
NO NUMBER	RENEW REAR NUMBER PLATE (REMOVED)		1.0	4.50
63 50 19 50	R + R REAR CROSSMEMBER (BUMPER COVER REMOVED)		2.0	9.00
51 01 73 00)	APPLY UNDERSEALANT ON BODY SHELL		2.0	9.00
51 01 73 50	APPLY UNDERSEALANT ON REAR BOOT FLOOR (COMPOSITE WORK)		1.0	4.50
2711	REAR PANEL REPAIR		20.0*	90.00

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference:
 Repairer Reference: SLV9370P TP AXA
 Date calculated: 29/08/2019 9:39 AM

Full Report
 Registration: SLV9370P
 Printed: 29/08/2019 10:03 AM

Code	Description	WU	Price SGD
4255	REAR FLOOR PANEL REPAIR	10.0*	45.00
4255	REAR FLOOR PANEL UNDERBODY SEALANT		
Labour Cost		Hrs	WU
Panel / Mechanical Labour		9.40	94.0
			423.00
Total of Labour			423.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR CROSSMEMBER SURFACE PAINT	4.0
	BOOTLID/TAILGATE NEW PART PAINTING	21.0
	REAR COVER BUMPER NEW PART PAINT K1N	12.0
	L/R OUT PARK AID SEN NEW PART PAINT K1N	3.0
	R/R OUT PARK AID SEN NEW PART PAINT K1N	3.0
	L/R IN PARK SYS SENS NEW PART PAINT K1N	3.0
	R/R IN PARK SYS SENS NEW PART PAINT K1N	3.0
	REAR PANEL REPAIR PAINTING >50%	13.0
	L/SIDE PANEL SURFACE PAINT	11.0
	REAR FLOOR PANEL SURFACE PAINT	12.0

Paint Material Per Part

Code	Description	Price SGD
2640	REAR CROSSMEMBER SURFACE PAINT	0.50
2931	BOOTLID/TAILGATE NEW PART PAINTING	67.08
2583	REAR COVER BUMPER NEW PART PAINT K1N	51.70
2781	L/R OUT PARK AID SEN NEW PART PAINT K1N	0.56
2782	R/R OUT PARK AID SEN NEW PART PAINT K1N	0.56
2783	L/R IN PARK SYS SENS NEW PART PAINT K1N	0.56
2784	R/R IN PARK SYS SENS NEW PART PAINT K1N	0.56
2711	REAR PANEL REPAIR PAINTING >50%	8.69
3481	L/SIDE PANEL SURFACE PAINT	34.86
4255	REAR FLOOR PANEL SURFACE PAINT	41.83

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor		85.0	
Time Paint	2.50	25.0	112.50
Preparation Main Work Metal	0.80	8.0	36.00
Preparation Comp. Work Plastic			
Total	10 WU/h	118.0	531.00

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference:
 Repairer Reference: **SLV9370P TP AXA**
 Date calculated: **29/08/2019 9:39 AM**

Full Report
 Registration: **SLV9370P**
 Printed: **29/08/2019 10:03 AM**

Material Cost - Paint	Price SGD
New Part Painting	67.08
New Part Painting - Plastic K1N	53.94
Repair Painting	8.69
Surface-/Blend Paint	77.19
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	248.20

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
2583	REAR COVER BUMPER	2K5 807 417 A	CR ✓	350.00 ✓
		GRU		
2591	LWR T-GATE MOULDING	2K5 853 079	cut ✓	160.00 ✓
2640	REAR CROSSMEMBER	2K5 807 305 B	✓ XSL	280.00
2652	REAR BUMPER REP SET	D 007 700	sa XSL	30.00
2702	REAR NUMBER PLATE	KNPL6		0.00
2781	L/R OUT PARK AID SEN	5Q0 919 275 B	*	0.00
		GRU		
2782	R/R OUT PARK AID SEN	5Q0 919 275 B		0.00
		GRU		
2783	L/R IN PARK SYS SENS	5Q0 919 275 B		0.00
		GRU		
2784	R/R IN PARK SYS SENS	5Q0 919 275 B		0.00
		GRU		
2795	RR SENSOR BRKT SET	2K5 998 491		0.00
2931	BOOTLID/TAILGATE	2K5 827 025 C	bt ✓	1,150.00 ✓
2944	TAILGATE SEAL	2K0 829 193 AA	✓	85.00 ✓
2975	TAILGATE LOCK	2K5 827 505 E	✓ XSL	45.00
3011	REAR BADGE -VW-	7E0 853 630 D	✓ Xnn	50.00
		DPJ		
3013	L/R BADGE	2K5 853 687	739 Xnn	35.00
3019	R/R UPPER BADGE	5G0 853 675 A	✓ Xnn	38.00
		JZQ		
3160	REAR SCREEN BOND KIT	D 004 660 M2	✓	0.00
3161	RR-SCREEN ACTIVATOR	D 181 802 M1		0.00
3162	CLEANING SOLUTION	D 009 401 04		0.00
3165	REAR SCREEN PRIMER	D 009 200 02		0.00
3166	APPLICATOR	D 009 500 25		0.00
3167	APPLICATOR	D 009 500 25		0.00
3172	REAR SCREEN PRIMER	D 009 200 02		0.00
3281	L/R LAMP	2K2 945 095 M	✓ XSL	100.00
3417	L/R REFLECTOR	2K5 945 105 D	✓ CR	25.00 ✓
4907	TAILGATE TRIM	2K0 867 605 D	CR ✓	45.00 ✓
		TZ6		

f: OEM Parts
 n: Non-OEM Parts
 u: Used parts
 Audatex System Using Manufacturer Times

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference:
 Repairer Reference: SLV9370P TP AXA
 Date calculated: 29/08/2019 9:39 AM

Full Report
 Registration: SLV9370P
 Printed: 29/08/2019 10:03 AM

Savings	0.00
Subtotal	2,393.00
Addition(+15.00%)	358.95
Total	2,751.95

Code	Description	Price SGD
1000	REAR NUMBER PLATE . <i>sea</i>	35.00* ✓
1001	REAR BUMPER REVERSE SENSOR <i>? X</i>	200 250.00* ✓
1002	WINDSCREEN SEALANT <i>sea</i>	40.00* ✓
1003	TO APPLY ANTI RUST COATING <i>sea</i>	50 100.00* ✓
Total Extras		425.00

Final Calculation		SGD	SGD
Parts		2,393.00	
Addition(+15.00%)		358.95	
Total Parts			2,751.95
Labour Time Base 10 WU/h		423.00	
Total 94.0 WU X 45.00 SGD/h			423.00
Additional Costs			
Underbody Sealer		13.50	
Rate 3.0 WU X 45.00 SGD/h			13.50
Total Of Additional Costs			425.00
Total Of Extras			
Paint Work Time Base 10 WU/h		531.00	
Labour Cost 118.0 WU X 45.00 SGD/h		248.20	
Material Cost			779.20
Total Paint Including Material			4,392.65
Repair Cost Excludes GST			307.49
GST (+7.0%)			4,700.14
Repair Cost Included GST			

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference:

Repairer Reference: SLV9370P TP AXA

Date calculated: 29/08/2019 9:39 AM

Full Report

Registration: SLV9370P

Printed: 29/08/2019 10:03 AM

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resue
Ap 90010568
5 days
P/P
04/09/19 @ 1030
Reming before paint

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference:
Repairer Reference: SLV9370P TP AXA
Date calculated: 12/03/2020 10:03 AM

Full Report
Registration: SLV9370P
Printed: 12/03/2020 10:04 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	SNG AH TEE	Currency:	SGD
Claim Reference:		Date of Incident:	26/08/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	VW
Model:	CADDY IV (TYP SA)
Sub Model:	HIGHLINE
Model Sheet Number:	06 CL 06
Registration:	SLV9370P
VIN number:	WV2ZZZ2KZJX054074
Odometer:	

Model Specs

FROM 09/2017	S/PAN/SLDG DOOR WDW	S/PAN/SLDG DOOR WDW	INSTR PANL MOULDING
AUTO LIGHT CONTROL	PARKING AID/CAMERA	CLIMATRONIC	ELECTRIC WINDOWS
VEH W/PASS CAR REGIS	REAR SCREEN	ELEC/HEATED D/MIRROR	WIPER/RAIN SENSOR
RADIO "COMP MEDIA"	6 SPEAKER	PHONE PREPARATION	FOG LAMPS
XENON/CORNERING LAMP	HEADLAMP WASHERS	DIPPING INNER MIRROR	REAR WIPER
LEATHER-/ALCANT CVR	FRT HEIGHT ADJ SEATS	HEATED FRONT SEATS	2 SEAT CUSH 2ND ROW
DRIVER'S SEAT COMF	PASS SEAT COMFORT	TRIM COMFORT	START & STOP SYSTEM
LUGGAGE COMP COVER	ARMREST W/LONGIT ADJ	1.4 LTR 92KW	7-SPEED DSG
BLUE MOTION TECHNO	ALTERNATOR 140A	DEACTIVATED P/AIRBAG	STRG WHEEL LEATHER
CRUISE CONTROL	TYRES 205/55 HR 16	WHEELS 6J X 16	WHEELBASE LONG
HD COOLING	SPARE WHEEL	B-REST FOLDING TABLE	EMISSION STD EURO 6
SIDE AIRBAGS	FRONT BRAKE 312 X 25	ROOF RAILS	L/SLIDING DOOR
R/SLIDING DOOR	SPORTS SUSP 16 INCH	PAINTED BUMPER	TWO COAT METALLIC
PREPARE OFF VEHICLE			

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
55 59 19 00	R + R TAILGATE INCLUDES: R + R TAILGATE TRIM, DETACHED HARNESS. ADJUST TAILGATE.		13.0	58.50
55 59 55 55	REPLACE TAILGATE (WITH UNIT REMOVED) INCLUDES: REMOVE/REFIT ALL COMPONENT PARTS		22.0	99.00
94 38 20 50	R + R REFLECTOR		1.0	4.50
55 70 19 00	R + R REAR CLOSURE RUBBER SEAL		3.0	13.50
63 69 19 06	R + R REAR BUMPER COVER		8.0	36.00
63 69 55 65	RENEW REAR BUMPER (REAR BUMPER REMOVED AND DRILLED) INCLUDES: PARKING HELP SYSTEM SENSORS REMOVE AND REFIT.		13.0	58.50
NO NUMBER	RENEW REAR NUMBER PLATE (REMOVED)		1.0	4.50
51 01 73 00)	APPLY UNDERSEALANT ON BODY SHELL		2.0	9.00
51 01 73 50	APPLY UNDERSEALANT ON REAR BOOT FLOOR (COMPOSITE WORK)		1.0	4.50
2711	REAR PANEL REPAIR		20.0*	90.00
4255	REAR FLOOR PANEL REPAIR		10.0*	45.00
4255	REAR FLOOR PANEL UNDERBODY SEALANT			
Labour Cost			Hrs	WU
Panel / Mechanical Labour			9.10	91.0
Total of Labour				409.50