Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19015266/UBA3Q2

Date: 22/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100423725

Claimant
Vehicle No: SJD10G

Insured Vehicle No: SKU6292T

Date of Loss: 28/08/2019 Nature of Claim: TP Claim No: 6611140013SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJD10G

Make & Model: PORSCHE CAYENNE, 3.6 V6 E5 TIPTRONIC (A) Engine No: B06356

Reg. Date: 28/03/2011 (Man. Year: 2011) Chassis No: WP1ZZZ92ZBLA05264

Colour: Black Odometer: 118075 km

Engine Capacity: 3598 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55 R18 Rear Tyre Size: 255/55 R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,931.00	11,365.47	15,565.53	57.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,160.00	1,490.00	56.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,581.00	12,525.47	17,055.53	57.66
Approved Total (Overridden) (S\$)	10,000.00			
(S\$)	29,581.00	10,000.00	19,581.00	66.19
+ GST 7.00/7.00% (S\$)	2,070.67	700.00	1,370.67	66.19
Nett Amount (S\$)	31,651.67	10,700.00	20,951.67	66.19
+ Car Rental (5.0 x S\$180.00/day) (S\$) (S\$) Liable Amount (50.00%) (S\$) + Doc/Search Fee (S\$)		900.00		
		11,600.00		
		5,800.00		
		2.00		
Ne	5,802.00			
				

INSPECTION

Date of Assignment: 29/08/2019

Date Inspected: 29/08/2019 Inspected At: Fastech Auto Pte Ltd (HQ)

1 Kaki Bukit Ave 6, #01-46/48/50

Autobay

Singapore 417883

Adjuster Report Page 2 of 4

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Warped	2,880.00 F	*1,988.30 FL
2	1		*FRONT BUMPER SIDE HOLDER N/S	Not Necessary	199.00 F	*- FL
3	1		*FRONT BUMPER PDC SENSOR N/S	Shorted	315.00 F	*288.50 FL
4	1		*FRONT BUMPER DAYLIGHT LAMP N/S	Cracked	1,005.00 F	*836.90 FL
5	1		*FRONT BUMPER FOG LAMP N/S	Cracked	625.00 F	*482.30 FL
6	1		*FRONT BUMPER SIDE GRILLE N/S	Cut	245.00 F	*245.00 FL
7	1		*FRONT BUMPER SIDE LAMP N/S	Scratched	399.00 F	*311.20 FL
8	1		*FRONT BUMPER LOWER GARNISH	Grazed 899.00		*712.10 FL
9	1		*FRONT BUMPER SPONGE	Not Necessary	288.00 F	*- FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary 995.00		*- FL
11	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
12	1		*HEADLAMP N/S	Scratched	3,880.00 F	*3,267.10 FL
13	1		*FRONT FENDER N/S	Repair	1,095.00 F	*- FL
14	1		*FRONT FENDER OUTER PROTECTOR GARNISH N/S	Grazed	422.00 F	*388.20 FL
15	1		*FRONT SHOCK ABSORBER N/S	Bent	895.00 F	*822.00 FL
16	1		*FRONT LOWER ARM N/S	Bent	1,225.00 F	*899.50 FL
17	1		*FRONT KNUCKLE ARM N/S	Bent	1,680.00 F	*1,425.20 FL
18	1		*FRONT KNUCKLE ARM BEARING N/S	Necessary	560.00 F	*420.00 FL
19	1		*FRONT STEERING RACK ASSY	Serviceable	4,880.00 F	*- FL
20	1		*FRONT STEERING TIE ROD END N/S	Bent 482.00 F		*482.00 FL
21	1		*FRONT SPORT RIM N/S 18 INCH	Repair	1,800.00 F	*- FL
22	1		*FRONT DRIVE SHAFT N/S	Serviceable	2,102.00 F	*- FL
F=Fra	nchise	part. L=L	istItemDisc.			
Sub Total (S\$) - List Item Discount on L Items 0.00/10.00% (S\$)					•	12,628.30 1,262.83

Total Parts (S\$) 26,931.00 11,365.47

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	TO CHECK WIRING	New	80.00	20.00					
2	TO DISMANTLE & REFIX FRONT PDC SENSOR	New	80.00	50.00					
3	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00					
4	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE	New	380.00	150.00					
5	TO SPRAY RUST PROOFING	New	80.00	0.00					
6	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	980.00	400.00					
7	TO PUTTY & SPRAY PAINTING	New	900.00	480.00					
	Gross Labour Cost (S\$)		2,650.00	1,160.00					

Report was unsubmitted during this print-out.

< END OF ESTIMATES >