

# DELGRO ENGINEERING PTE LTD

: SHD 4585L

DATE

:

: HYUNDAI SONATA

Parts Description/ Labour	Type
Boot Lid Lamp (RH) <i>X old Damage</i>	
Rear Bumper <i>de</i>	
Rear Bumper Clip <i>nec</i>	
Rear Bumper Protector (RH) <i>X nh</i>	
SUB TOTAL	
LESS 20%	
DISCOUNTED TOTAL	
Rear Bumper Advertisement Logo <i>nec</i>	
Rear Fender Advertisement Logo (LH/RH) <i>nec</i>	
Labour Charge	
Panel Beating	
Spray Painting Charge	
Wiring Charge	
Remove/Refix Reverse Sensor	
TOTAL LABOUR	
ESTIMATE TOTAL	

0. c  
 578.4 +  
 22. =  
 600.40 \*  
 40  
 600.4 x  
 80. %  
 480.32 \*  
 00  
 0. c  
 .60  
 .72  
 200. +  
 200. +  
 30. =  
 430.00 \*  
 0. c  
 50.00  
 50.00  
 200. =  
 250.00 \*  
 .50.00  
 0. c  
 480.32 +  
 430. +  
 250. =  
 1,160.32 \*  
 200  
 350.00  
 1,160.32 x  
 250.00  
 80. %  
 50.00  
 928.26 \*  
 120.00  
 0. c  
 770.00  
 453.8 900.00  
 1,714.88

AIG

Nett  
Nett

200  
X nh  
2

1/2 hr 16/11/19  
 29/8/19 1225 hr.  
 2 by 1.  
 4/5  
 After Repair pld

I hereby acknowledge and agree to indemnify the repairer for any loss or damage to the vehicle or its contents arising from the following:

- The use of any materials or parts during the repair
- Parts used are subject to repairer's selection
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be removed and is subject to final approval from insurance company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.