

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19015286/ABA3Q2

Date: 03/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800042660-01

Claimant
Vehicle No : SLP6531T **Insured Vehicle No :** SLZ1668M

Date of Loss: 19/08/2019 Nature of Claim: TP Claim No: 8782622887SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP6531T		
Make & Model:	HONDA VEZEL, 1.5 (A)	Engine No:	L15B4404478
Reg. Date:	13/06/2017 (Man. Year: 2016)	Chassis No:	RU11204477
Colour:	Black	Odometer:	92661 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	500.00	50.00	450.00	90.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	660.00	2,370.00	78.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,530.00	710.00	2,820.00	79.89
Approved Total (Overridden) (S\$)		550.00		
Nett Amount (S\$)	3,530.00	550.00	2,980.00	84.42
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 28/08/2019

Date Inspected: 29/08/2019 Inspected At:

Revolution Automotive Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #01-49,
Premier@Kaki Bukit
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (NPA)	Repair	0.00 FS	*- FS
2	1		*REAR BUMPER RETAINER LH (NPA)	Not Necessary	0.00 FS	*- FS
3	1		*REAR BUMPER RETAINER RH (NPA)	Not Necessary	0.00 FS	*- FS
4	1		*REAR BUMPER REFLECTOR RH (NPA)	Not Necessary	0.00 FS	*- FS
5	1		*REAR CORNER BUMPER RH (NPA)	Not Necessary	0.00 FS	*- FS
6	1		*REAR FENDER ARCH GARNISH RH (NPA)	Cut	0.00 FS	*- FS
7	1		*TAIL LAMP RH (NPA)	Not Necessary	0.00 FS	*- FS
8	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
9	1		*REAR FENDER INNER SHIELD RH (NPA)	Not Necessary	0.00 FS	*- FS
10	1		*REAR DOOR RH (NPA)	Not Necessary	0.00 FS	*- FS
11	1		*REAR DOOR LOCK RH (NPA)	Not Necessary	0.00 FS	*- FS
12	1		*ROCKER PANEL GARNISH RH (NPA)	Not Necessary	0.00 FS	*- FS
13	1		*REAR WHEEL RIM RH (NPA)	Cut	0.00 FS	*- FS
14	1		*REAR ABSORBER RH (NPA)	Not Necessary	0.00 FS	*- FS
15	1		*REAR ABSORBER TOP MOUNTING (NPA)	Not Necessary	0.00 FS	*- FS
16	1		*REAR WHEEL BEARING RH (NPA)	Not Necessary	0.00 FS	*- FS
17	1		*REAR AXLE (NPA)	Not Necessary	0.00 FS	*- FS
18	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
19	1		*SET REAR FENDER ARCH GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
20	1		*SET ROCKER PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS
21	1		*SET REAR FENDER INNER SHIELD CLIP	Not Necessary	50.00 FS	*- FS
22	1		*REAR WHEEL TYRE	Not Necessary	250.00 FS	*- FS
23	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
				Total Parts (\$\$)	500.00	50.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO R&R REAR BUMPER REVERSE SENSOR	New	80.00	50.00
2	TO CHECK WIRING & LIGHTING SYSTEM	New	80.00	30.00
3	TO SUPPLY UNDERCOATING/PUTTY ON PARTS REPLACED	New	80.00	0.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	60.00	0.00
5	TO R&R REAR DOOR MECHANISM	New	300.00	0.00
6	TO CONDUCT WHEEL ALIGNMENT BEFORE & AFTER	New	180.00	80.00
7	TO R&R REAR WHEEL RIM, TYRE & BALANCING	New	50.00	0.00
8	TO R&R REAR UNDER-CARRIAGE DAMAGED PARTS	New	350.00	0.00
9	TO REPAIR, REPLACE & REALIGN DAMAGED AREAS	New	900.00	200.00
10	TO SPRAY PAINTING ON AFFECTED AREAS	New	800.00	300.00
11	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	150.00	0.00
Gross Labour Cost (\$)			3,030.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >