



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 208C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT (CONSISTENT)	TO REPAIR SEE LABOUR	1,259.42	-
1	BUMPER SPOILER FRT (CONSISTENT)	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT (CONSISTENT)	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT RH (CONSISTENT)	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT (CONSISTENT)	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT (CONSISTENT)	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT (CONSISTENT)	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE RH (CONSISTENT)	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT (CONSISTENT)	TO REPAIR SEE LABOUR	914.08	-
1	HEADLAMP RH (CONSISTENT)	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT RH (CONSISTENT)	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER RH (CONSISTENT)	SERVICEABLE	15.79	-
1	FENDER INSULATOR RH (CONSISTENT)	SERVICEABLE	130.84	-
1	TOW COVER FRT (CONSISTENT)	SERVICEABLE	28.61	-
1	FRONT BRACE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	177.22	-
1	RADIATOR GRILLE (CONSISTENT)	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE 'RENAULT' (CONSISTENT)	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME (CONSISTENT)	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT BRACKET (CONSISTENT)	TO REPAIR SEE LABOUR	89.79	-
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR (CONSISTENT)	SERVICEABLE	405.73	-
1	BONNET STRUT LH (CONSISTENT)	SERVICEABLE	88.61	-
1	BONNET STRUT RH (CONSISTENT)	SERVICEABLE	88.61	-
1	BONNET HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	348.31	-

Report Ref No. CC3/ASM19015294/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE (CONSISTENT)	SERVICEABLE	119.19	-
1	BONNET CABLE COVER (CONSISTENT)	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER (CONSISTENT)	SERVICEABLE	92.36	-
1	BONNET SEAL INNER (CONSISTENT)	SERVICEABLE	157.28	-
1	DOOR PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR MIRROR ASSY RH (CONSISTENT)	SERVICEABLE	1,483.40	-
1	WIPER RESERVOIR MOTOR (CONSISTENT)	SERVICEABLE	270.06	-
1	WIPER RESERVOIR (CONSISTENT)	SERVICEABLE	348.25	-
1	WIPER RESERVOIR NECK (CONSISTENT)	SERVICEABLE	136.11	-
1	DOOR HARNESS WIRE RH (CONSISTENT)	SERVICEABLE	2,670.00	-
1	FRAME FULL SUPPORT PANEL (CONSISTENT)	SERVICEABLE	615.90	-
	LESS 10% DISCOUNT		-2,252.54	-
			20,272.83	-
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR STICKER 'TRANS-CAB' (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	FRONT DOOR STICKER 'CLASSIC' (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	BUMPER CLIP FRT (SN) (CONSISTENT)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	10.50	-
1	BUMPER GRILLE LOWER CLIP (SN) (CONSISTENT)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN) (CONSISTENT)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	WHEELARCH CLIP FRT RH (SN) (CONSISTENT)	NOT NECESSARY	30.50	-
1	FRONT RIGHT TYRE (SN) (CONSISTENT)	SERVICEABLE	300.00	-
1	FRONT RIGHT TYRE RIM (SN) (CONSISTENT)	SERVICEABLE	380.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN) (CONSISTENT)	SERVICEABLE	80.00	-

Report Ref No. CC3/ASM19015294/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET RADIATOR GRILLE SCREW (SN) (CONSISTENT)	NOT NECESSARY	16.00	-
1	SET RADIATOR GRILLE FRAME CLIP (SN) (CONSISTENT)	NOT NECESSARY	52.00	-
1	WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN MOULDING (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
6	BONNET INSULATOR CLIP L70Y (SN) (CONSISTENT)	NOT NECESSARY	7.30	-
2	BONNET STRUT L70Y (SN) (CONSISTENT)	SERVICEABLE	88.61	-
2	BONNET CABLE CLIP L70Y (SN) (CONSISTENT)	NOT NECESSARY	6.31	-
2	BONNET CABLE COVER SCREW L70Y (SN) (CONSISTENT)	NOT NECESSARY	10.85	-
			1,882.87	-
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		6,000.00	220.00
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	NOT NECESSARY	6,000.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS .	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST .	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING .	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			15,180.00	220.00
GRAND TOTAL			37,335.70	220.00
RECOMMENDED COST OF REPAIRS				220.00

Report Ref No. CC3/ASM19015294/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.