

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19015305/K1EA3Q2

**Date:** 22/04/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900103900

**Claimant**  
**Vehicle No :** SHA2344U **Insured Vehicle No :** SML7867C

Date of Loss: 28/08/2019 Nature of Claim: TP Claim No: 1884535436SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2344U		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B84935
Reg. Date:	07/01/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU703077820
Colour:	Blue	Odometer:	111006 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 9 mm	Rear Left Side:	Davanti 9 mm
Front Right Side:	Davanti 9 mm	Rear Right Side:	Davanti 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,181.07	4,139.30	4,041.77	49.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	1,620.00	1,210.00	42.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>11,011.07</b>	<b>5,759.30</b>	<b>5,251.77</b>	<b>47.70</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	770.77	403.15	367.62	47.70
<b>Nett Amount (\$\$)</b>	<b>11,781.84</b>	<b>6,162.45</b>	<b>5,619.39</b>	<b>47.70</b>
<b>+ Loss of Use (3.0 x S\$50.00/day) (\$\$)</b>		150.00		
<b>+ Car Rental (3.0 x S\$129.68/day) (\$\$)</b>		389.04		
<b>+ Doc/Search Fee (\$\$)</b>		7.49		
<b>Nett Liability (\$\$)</b>		<b>6,708.98</b>		

### INSPECTION

Date of Assignment: 29/08/2019

Date Inspected: 29/08/2019 Inspected At: ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 4.0 days

**Adjuster:** KALVIN ANG WEI KUN**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Cracked	499.90 FL	*499.90 FL
2	1		*FRONT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER, LH	Serviceable	77.00 FL	*- FL
4	1		*UNIT ASSY, HEADLAMP, LH (LED)	Serviceable	3,455.00 FL	*- FL
5	1		*FENDER SUB-ASSY, FRONT LH	Buckled	945.30 FL	*945.30 FL
6	1		*FRONT FENDER SHIELD, LH	Serviceable	196.60 FL	*- FL
7	1		*FRONT FENDER SHIELD CLIP	Not Necessary	3.80 FL	*- FL
8	1		*FRONT FENDER HYBRID EMBLEM, LH	Necessary	52.50 FL	*52.50 FL
9	1		*PANEL SUB-ASSY, FRONT DOOR, LH	Repair	1,264.00 FL	*- FL
10	1		*GLASS, SUB-ASSY, FRONT DOOR, LH	Cut	780.00 FL	*780.00 FL
11	1		*MIRROR ASSY, OUTER REAR VIEW, LH	Broken	1,390.10 FL	*1,390.10 FL
12	1		*WINDOW ASSY, QUARTER, LH	Repair	168.10 FL	*- FL
13	1		*MOULDING, REAR DOOR WINDOW FRAME, FRONT LH	Serviceable	69.20 FL	*- FL
14	1		*FRONT WHEEL RIM (LH)	Grazed	1,555.10 FL	*1,555.10 FL
15	1		*REAR DOOR (LH) (NPA)	Repair	0.00 FL	*- FL
16	1		*REAR FENDER (LH) (NPA)	Repair	0.00 FL	*- FL
17	1		*WING MIRROR OUTER COVER	Missing	89.50 FL	*89.50 FL
18	1		*REAR DOOR APP LOGO	Necessary	80.00 FS	*80.00 FS
19	1		*FRONT DOOR COMFORT LOGO	Necessary	75.00 FS	*75.00 FS
20	1		*REAR DOOR ADVERTISEMENT LOGO	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,823.10</b>	<b>5,467.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,642.03	1,328.10
<b>Total Parts (\$\$)</b>	<b>8,181.07</b>	<b>4,139.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING	New	850.00	500.00
2	SPRAY PAINTING CHARGE	New	1,400.00	1,050.00
3	WIRING CHARGE	New	100.00	0.00
4	TUFF KOTE	New	150.00	20.00
5	TOWING CHARGE	New	90.00	0.00
6	TRANSFER OF DOOR	New	160.00	50.00
7	FRT WHEEL ALIGNMENT	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,830.00</b>	<b>1,620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >