

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19015310/EGA3Q2

Date: 24/06/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MFL0002658
Claimant Vehicle No :	SHC4510H	Insured Vehicle No :	PA7245U
Date of Loss:	24/08/2019	Nature of Claim:	TP
		Claim No:	MFL2019D0000981

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4510H		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS099076
Reg. Date:	12/10/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU003573106
Colour:	Maroon	Odometer:	295911 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,531.00	1,122.39	10,408.61	90.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,797.00	930.00	2,867.00	75.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	15,328.00	2,052.39	13,275.61	86.61
+ Loss of Use (6.5 x S\$40.00/day) (S\$)		260.00		
+ Car Rental (6.5 x S\$116.63/day) (S\$)		758.10		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,077.49		
Global Sum Settlement (S\$)		3,500.00		

INSPECTION

Date of Assignment:	28/08/2019	
Date Inspected:	28/08/2019 Inspected At:	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2020)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC4510H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FR BUMPER (DISC 25%)	Broken	495.50 F	*371.63 F
2	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	15.00 F	*11.25 F
3	1		*FENDER SUB-ASSY ,FR ,LH (DISC 25%)	Dented	933.10 F	*699.83 F
4	1		*EMBLEM ,SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
5	1		*LAMP ASSY ,FOG ,LH	Not Necessary	910.20 F	*- F
6	1		*GRILLE ,RADIATOR	Not Necessary	165.00 F	*- F
7	1		*UNIT,HEADLAMP ,LH	Not Necessary	2,558.90 F	*- F
8	1		*COMPUTER SUB-ASSY ,HEADLAMP ,LH NO.1	Not Necessary	486.40 F	*- F
9	1		*SUPPORT S/A LH	Not Necessary	237.00 F	*- F
10	1		*LINER ,FR FENDER ,LH	Not Necessary	194.30 F	*- F
11	1		*PAD ,FR WHEEL LH	Not Necessary	57.70 F	*- F
12	1		*WHEEL ,DISC	Not Necessary	1,555.10 F	*- F
13	1		*CAP SUB-ASSY ,WHEEL	Not Necessary	175.80 F	*- F
14	1		*PANEL SUB-ASSY ,FRONT DOOR LH	Not Necessary	1,249.60 F	*- F
15	1		*STICKER DECAL SMRT (DOOR)	Not Necessary	60.00 F	*- F
16	1		*MIRROR ASSY ,OUTER REAR VIEW ,LH	Not Necessary	1,283.90 F	*- F
17	1		*LAMP ASSY ,SIDE MIRROR TURN SIGNAL ,LH	Not Necessary	162.20 F	*- F
18	1		*HOOD SUB-ASSY	Not Necessary	938.40 F	*- F

F=Franchise part.

Total Parts (S\$) 11,531.00 1,122.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	845.00	400.00
2	SPRAY PAINT	New	2,232.00	450.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO REMOVE AND REFIX WING MIRROR	New	120.00	20.00
5	TO APPLY RUST -PROOFING ON AFFECTED AREA	New	120.00	20.00
6	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
7	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
8	TO REPLACE SUNDRY PARTS	New	100.00	20.00
9	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			3,797.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >