

ASS. REC. BY:

REF:

CS/FCI 19015330 /Avf302

Special Instructions:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Joanny

of FCI

Date/Time: 30.8.19 9.30a.m

Estimated Cost:

Bill to:

OD / TP / RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBH 5449R

Insured: SHC 8187G

at Workshop m/s MG SOLUTION

Tel: 67444165

of 23 Kaki Bukit Ave 4 # 02-03

Policy No:

Claim No: D19065568MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 30.8.19 9.37a.m

Person Contacted:

MS Hong

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBH 5449R: X
	SHC 8187G: NS/INC19011362/h2td302 D.O.A. 25/06/2019
30/8/19	Informed FCI pending workshop est by email
35/9/19	Adrian confirmed LS \$9000 (Red 5436.48, 38/1)
26/9/19	Email preli revised to FCI

REF: FCI

ASSIGNMENT

From: Date: 30.8.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 5449R

at Workshop m/s MG solution

of 23 Kari Bukit Ar 4 A02-03

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: GBH5449R, Yr Regn: 2018 July.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace

c.c 2982

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 34612

T/Radio: Insured / Std / NI / NA

Eng/No:

CI/No:

JTFHT02P800243695

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C

R: 195 R15C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 30/08/19

Survey held at

MG solution

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP / 1st Cap.

RECEIVED 28 SEP 2019

Date/Time, File Pass to?

☐ : Preli. Report

Date/Time, File Return to?

☐ : Final Report

1) xla - typist

Report Format: cws

Lump Sum / I.B.I: (\$) 9000p

Days Of Repair: 12

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation

) S + RS \$

) Photos

) Other

TOTAL

4x15=60

1704
60
50
50
74

404



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19005568MFSH

Our ref: CS/FC119015330/Avf3

Date : 26/9/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GBH 5449R


We thank you for your instruction on 30/8/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/8/2019 at the premises of M/s MG SOLUTION PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$14,436.48
Revised Estimate Amount	: S\$9,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	28-08-2019	Our Ref No. D19005568MFSH
Accident Date	26-08-2019	Claim Type. Third Party
Insured Vehicle	SHC8187G	Third Party Vehicle. GBH5449R
Survey Location	23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03	
Contact Person.	SHARON CHIA	
Contact No.	65073848/ 0	Fax No. 65073849
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MG SOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 26 September 2019 9:43 AM
To: 'CWS Motor Claims'; SUR
Cc: 'Joanne Yong'
Subject: RE: SURVEY ASSESSMENT - D19005568MFSH/1-GBH 5449R
Attachments: GBH 5449R PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle GBH 5449R
Date of survey: 30/8/2019
Number of days (estimated) : 12 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Friday, 30 August 2019 4:45 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Cc: 'Joanne Yong' <Joanneyong@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19005568MFSH/1-GBH 5449R

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBH 5449R on 30/8/2019 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 30 August 2019 9:39 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Joanne Yong' <Joanneyong@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19005568MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>

Sent: Friday, 30 August, 2019 9:30 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong
<JoanneYong@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19005568MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 30 August 2019 4:45 PM
To: 'CWS Motor Claims'; SUR
Cc: 'Joanne Yong'
Subject: RE: SURVEY ASSESSMENT - D19005568MFSH/1-GBH 5449R

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBH 5449R on 30/8/2019 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Friday, 30 August 2019 9:39 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Joanne Yong' <Joanneyong@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19005568MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Friday, 30 August, 2019 9:30 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005568MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: FIRST CAPITAL	DATE	: 30-Aug-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: GBH5449R		
MODEL	: TOYOTA HIACE COMMUTER		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 26-Aug-19
		TIME	: 00:30HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>dent</i>	1	\$ 540.00	\$ 540.00
2	FRONT BUMPER SIDE RETAINER LH <i>new</i>	1	\$ 190.00	\$ 190.00
3	HEADLAMP LH <i>cut</i>	1	\$ 650.00	\$ 650.00
4	FRONT DOOR LH <i>dent</i>	1	\$ 1,550.00	\$ 1,550.00
5	TAILGATE <i>Distorted</i>	1	\$ 1,866.90	\$ 1,866.90
6	TAILGATE LOGO <i>new</i>	1	\$ 60.00	\$ 60.00
7	TAILGATE TOYOTA HIACE STICKER <i>new</i>	1	\$ 80.00	\$ 80.00
8	TAILGATE LOCK <i>dent</i>	1	\$ 320.00	\$ 320.00
9	TAILGATE WEATHERSTRIP <i>cut</i>	1	\$ 422.10	\$ 422.10
10	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 180.00	\$ 180.00
11	REAR BUMPER <i>Distorted</i>	1	\$ 530.00	\$ 530.00
12	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 55.40	\$ 110.80
13	TAILLAMP <i>cut</i>	1	\$ 322.40	\$ 322.40
14	TAILLAMP LOWER APPRON <i>dent</i>	1	\$ 155.50	\$ 155.50
15	TAILLAMP LOWER APPRON SIDE RETAINER <i>new</i>	1	\$ 62.00	\$ 62.00
16	TAILLAMP PANEL <i>new</i>	1	\$ 555.60	\$ 555.60
17	REAR FENDER LH <i>Buckled</i>	1	\$ 1,980.00	\$ 1,980.00
18	REAR FENDER AIR VENT LH <i>cut</i>	1	\$ 80.00	\$ 80.00
19	REAR END PANEL(OUTER) <i>Distorted</i>	1	\$ 680.00	\$ 680.00

~~REAR END PANEL (INNER) Distorted~~

20	REAR END PANEL TOP GARNISH <i>Not Me Bent</i>	1	\$ 280.00	\$ 280.00	<i>✓</i>
----	---	---	-----------	-----------	----------

9680-60

7260-45

TOTAL PRICE \$ 10,615.30
LESS 25% \$ 2,653.83
SUB TOTAL PRICE \$ 7,961.48

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 25.00	\$ 25.00	<i>1</i>
2	COMPANY LTA ADDRESS <i>new</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
3	HEADLAMP CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	<i>10</i>
4	REAR NUMBER PLATE <i>Painted</i>	1	\$ 50.00	\$ 50.00	<i>30</i>
5	TAILGATE 70KM/H <i>new</i>	1	\$ 30.00	\$ 30.00	<i>10</i>
6	TAILGATE WINDSCREEN SEALANT <i>3 new</i>	1	\$ 120.00	\$ 120.00	<i>40</i>
7	TAILGATE WINDSCREEN INNER SEAL	1	\$ 100.00	\$ 100.00	<i>40</i>
8	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	<i>1</i>
9	TAILLAMP LOWER APPRON RIVERT <i>new</i>	1	\$ 30.00	\$ 30.00	<i>20</i>
10	REAR END PANEL INSULATION SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	<i>60</i>
11	REAR REVERSE SENSOR <i>Paint</i>	1	\$ 220.00	\$ 220.00	<i>200</i>

485

TOTAL \$ 785.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 600.00	<i>300.</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 600.00	<i>400</i>	
3	TUFF COAT	\$ 150.00	<i>X</i>	
4	WIRING CHECK	\$ 80.00	<i>30</i>	
5	TO REMOVE RAND REFIX FRONT DOOR MECHANISM	\$ 180.00	<i>80</i>	

TOTAL

\$1,610.00

810

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	<i>1400</i>	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>1100.</i>	
3	TUFF COAT	\$ 150.00	<i>X</i>	
4	WIRING CHECK	\$ 80.00	<i>30</i>	
5	TO REMOVE AND REFIX TAILGATE MECHANISM	\$ 150.00	<i>80</i>	
6	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN	\$ 180.00	<i>120.</i>	

7	TO REMOVE AND REFIX REVERSE SENSOR	\$ 120.00	50.	
---	---------------------------------------	-----------	-----	--

TOTAL

\$4,080.00

2780

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,746.48
TOTAL LABOUR COST : \$ 5,690.00
TOTAL REPAIR COST : \$ 14,436.48

APPROVED DETAILS

SURVEYOR :
CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :

Adrian L

L/S 30/08/19.

12 Days.

total: 1133545

L/S: 9K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19015330/Avf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-10-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8187G	Veh. Inspected	GBH 5449R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005568MFSH	Excess (\$)	0.00	
Assign From	JOANNEY	Assign Date	30/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFHT02P800243695	Colour	SILVER	
Odometer	34612	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/08/2019	Inspection Date	30/08/2019	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 5449R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	540.00	540.00
1	FRONT BUMPER SIDE RETAINER LH	NOT NECESSARY	190.00	-
1	HEADLAMP LH	CUT	650.00	650.00
1	FRONT DOOR LH	DENTED	1,550.00	1,550.00
1	TAILGATE	DISTORTED	1,866.90	1,866.90
1	TAILGATE LOGO	NECESSARY	60.00	60.00
1	TAILGATE TOYOTA HIACE STICKER	NECESSARY	80.00	80.00
1	TAILGATE LOCK	DAMAGED	320.00	320.00
1	TAILGATE WEATHERSTRIP	CUT	422.10	295.00
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	180.00	180.00
1	REAR BUMPER	DISTORTED	530.00	530.00
2	REAR BUMPER SIDE RETAINER @\$55.40	NECESSARY	110.80	110.80
1	TAILLAMP	CUT	322.40	322.40
1	TAILLAMP LOWER APRON	DAMAGED	155.50	155.50
1	TAILLAMP LOWER APRON SIDE RETAINER	NOT NECESSARY	62.00	-
1	TAILLAMP PANEL	TO REPAIR SEE LABOUR	555.60	-
1	REAR FENDER LH	BUCKLED	1,980.00	1,980.00
1	REAR FENDER AIR VENT LH	CRACKED	80.00	80.00
1	REAR END PANEL (OUTER)	DISTORTED	680.00	680.00
1	REAR END PANEL TOP GARNISH	BENT	280.00	280.00
	LESS 25% DISCOUNT		-2,653.83	-2,420.15
			7,961.47	7,260.45
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	25.00	25.00
1	COMPANY LTA ADDRESS (SN)	NECESSARY	50.00	30.00
1	SET HEADLAMP CLIP (SN)	NECESSARY	20.00	10.00
1	REAR NUMBER PLATE (SN)	DENTED	50.00	30.00
1	TAILGATE 70KM/H (SN)	NECESSARY	30.00	10.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	120.00	40.00
1	TAILGATE WINDSCREEN INNER SEAL (SN)	NECESSARY	100.00	40.00

Report Ref No. CS/FCI19015330/Avf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIP (SN)	NECESSARY	20.00	20.00
1	TAILLAMP LOWER APRON RIVERT (SN)	NECESSARY	30.00	20.00
1	REAR END PANEL INSULATION SEALANT (SN)	NECESSARY	120.00	60.00
1	REAR REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			785.00	485.00
	LABOUR			
	PANEL BEATING,REMOVAL AND REPLACING PARTS.		600.00	300.00
	TO SPRAY PAINT AFFECTED AREA.		600.00	400.00
	TUFF COAT.	NOT NECESSARY	150.00	-
	WIRING CHECK.		80.00	30.00
	TO REMOVE AND REFIX FRONT DOOR MECHANISM.		180.00	80.00
	PANEL BEATING,REMOVAL AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL.		2,000.00	1,400.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	1,100.00
	TUFF COAT.	NOT NECESSARY	150.00	-
	WIRING CHECK.		80.00	30.00
	TO REMOVE AND REFIX TAILGATE MECHANISM.		150.00	80.00
	TO REMOVE AND REFIX REVERSE SENSOR.		120.00	50.00
	TO REMOVE AND REFIX REAR TAILGATE WINDSCREEN.		180.00	120.00
			5,690.00	3,590.00
GRAND TOTAL			14,436.47	11,335.45
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,000.00

Report Ref No. CS/FCI19015330/Avf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.