

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Chhia Nyuk Pui of MSIG Date/Time: 29/08/2019

Merimen

Estimated Cost: _____ Bill to: _____

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH 8963B Insured: SLE 9495C

at Workshop m/s Soon Hock Motor Pte Ltd Tel: 6483 6016

of Blk 10 Ang Mo Kio Industrial Park 2A #01-05106

Policy No: 80460632 AMY Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27/08/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS "wp" H.O.D. Endorsement: _____

Date/Time: 05:39pm @ 29/08/2019 Person Contacted: Jvnu Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLE 9495C : x
	SH 8963B : NA / ENC 08021387/r D.O.A. = 29/07/2008
<u>06/09/19</u>	<u>@ 16:19 pm received PA to Chhia Nyuk Pui via merimen.</u>


Shreeya

REF:

ASSIGNMENT

05 June 2024

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured:
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 12 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SH 8963 B Yr Regn: 2016 / June
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai I40 c.c 1685
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 556289 T/Radio: Insured / Std / NI / NA
 Eng/No: D4FDGU626251
 C/No: KMHLB41UMGU090125
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: Hankook 205/60R16
 R: — " —
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Hankook
 Front S mm Rear S mm
 R/Bal. S mm L/Bal. S mm
 D.O.A. 27/08/19 D.O.I. 30/08/19
 Survey held at Chunni AMC
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rev y of Pint o/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSIG SLE 9495C SLE 9495C
08/10/19	Invoice 2/5 16000/- with 12 days 7 rev (16,330.38 Rev 5%)

RECEIVED 09 OCT 2019

Date/Time, File Pass 1/7: 09/10/19
 1) Typist : Preli. Report : Final Report
 Date/Time, File Return to? _____
 2) _____
 Report Format : _____
 Lump Sum / I.B.I: (\$ 16,000/- 4/5)
 Days Of Repair: 12
 Resurvey No. of Trip: 2
 Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)
 Survey Fee: _____
 Transportation: _____
 S + RS, SI _____
 Photos _____
 Others _____
 TOTAL: 261

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 06 Sep 2019

Preliminary Advice

Insured Vehicle No	: SLE9495C	Accident Date	: 27/08/2019
TP Vehicle No	: SH8963B	Assignment Date	: 29/08/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 9 days
Date of Inspection	: 30/08/2019		
Inspection At	: Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,830.38
Revised Amount	:S\$	20,693.06
Check Items (Estimated)	:S\$	0.00
Total	:S\$	20,693.06
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019		29 Aug 2019 17:31 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	JAIME CHONG MEOW CHUEN (ZHANG MIAOJUAN) , ID: 57909258D, Tel: +6596422245, Email: JAIMECHONG79@GMAIL.COM		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SH8963B	Date of Loss:	27/08/2019 13:00 - :59 [38 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	80460632QMY (Comprehensive) Coverage: 08/08/2019 - 07/08/2020
Vehicle Reg. No. (Insured):	SLE9495C	Policy No. (Claimant):	
Repairer:	Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 30/08/2019]		
Driver/Custodian (Insured):	JAIME CHONG MEOW CHUEN (ZHANG MIAOJUAN) (40 / Female), NRIC: 57909258D, Tel: +6596422245 Email: JAIMECHONG79@GMAIL.COM		
Adj Asg. Remarks:	on WP. Liab: 100%. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lynn or Ms Irene at 65425119 / 6542 7162.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD0819113362 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 28/08/2019 08:57
 SUBMITTED BY: Janet Lim Siong Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 28/08/2019 08:57
 Date Of Accident 27/08/2019 13:40
 Exact Location Of Accident ANCHORVALE ROAD TWDS SENGKANG EAST AVE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SH8963B
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number MCOM0015
 Cover Note Number
 Driver
 Name of Driver NGOO KEEW SEEK
 NRIC No S25701111
 Date Of Birth 01/06/1960
 Occupation OUTDOOR
 Date Of Driving Pass 04/12/1979
 Driving Experience 39 YEARS AND 8 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97873384
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address BLK 441B FERVALE ROAD
#06-321
Postcode 792441
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 3
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLE9495C
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver JAIME CHONG MEOW CHUEN
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRONT
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLT8757A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TORENCE HOH SONG WEI
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	RH FRONT
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 27.08.2019@1630hrs


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: June

SKETCH PLAN



A- SH 8963B
 B- SLE 9495C
 C- SLT-8757A

Along Anchorvale Rd Twds Sengkang East AVE

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27.08.2019 @ 1340hrs I was travelling along Anchorvale Rd Twds Sengkang East AVE with no passenger onboard.

As I wanted a make left turn into the carpark suddenly veh(B) SLE 9495C hit onto my vehicle rear portion and caused my vehicle to surge forward and hit onto Veh(C) SLT 8757A.

As it took place too fast I could not take evasive action to prevent the accident.

I have company video and photos at scene to support my claims .

No injury in this accident .

Veh(B) SLE 9495C MS Jaime Chong Meow Chuen
 Veh(C) SLT 8757A MR Tarence Hoh Song Wei

DECLARATION

I/We declare the foregoing particulars are true in every respect.
 COMFORT TRANSPORTATION PTE LTD
 CO. REG. NO. 199303821R

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 27.08.2019@1630hrs

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.: June

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 8963B

DATE : 27.08.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

MSIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>ist</i>			\$ 2,265.90
	Bonnet Lock <i>NN</i>			\$ 36.90
	Bonnet Insulator <i>NN</i>			\$ 196.50
	Bonnet Insulator Clips <i>NN</i>			\$ 8.40
	Radiator Grille <i>broken</i>			\$ 1,110.10
	Radiator Grille H Emblem <i>new</i>			\$ 39.50
	Front Bumper Cover <i>torn</i>			\$ 1,052.20
	Front Bumper Sponge <i>torn</i>			\$ 99.20
	Front Bumper Reinforcement <i>Dented / ist</i>			\$ 402.10
	Front Bumper Grille (RH) <i>ist</i>			\$ 93.60
	Front Bumper Grille Airduct (RH) <i>broken</i>			\$ 26.20
	Front Bumper Lip <i>new</i>			\$ 54.90
	Front Bumper Bracket Top (RH) <i>new</i>			\$ 22.40
	Front Bumper Bracket (RH) <i>broken</i>			\$ 24.60
	Headlamp Support Top Cover <i>new</i>			\$ 222.60
	Headlamp Support Panel Assy <i>broken</i>			\$ 907.40
	Headlamp (RH) <i>broken</i>			\$ 1,388.00
	Radiator <i>ist / punctured</i>			\$ 698.30
	Radiator Fan Blade, Cowling, Motor Assy <i>new</i>			\$ 792.95
	Radiator Expansion Tank <i>new</i>			\$ 28.30
	Radiator Guard <i>new</i>			\$ 20.00
	Horn Unit (RH) <i>new</i>			\$ 73.80
	Horn Wire <i>new</i>			\$ 156.50
	Front Fender (RH) <i>enc</i>			\$ 566.30
	Front Fender Apron Panel (RH) <i>Dented / ist</i>			\$ 637.00
	Front Fender Shield (RH) <i>dented</i>			\$ 174.90
	Aircon Condenser <i>ist / punctured</i>			\$ 927.50
	Aircon Suction & Liquid Hose <i>ist</i>			\$ 624.00
	Aircon Discharge Hose <i>ist</i>			\$ 162.60
	Wiper Container <i>broken</i>			\$ 61.90
	Wiper Container Motor <i>new</i>			\$ 75.00
	Front Shock Absorber (Assy) (RH) <i>new dented</i>			\$ 342.20
	Front Shock Absorber Mounting (RH) <i>new</i>			\$ 108.80
	STG Tie End <i>new</i>			\$ 62.60
	Stabilizer Bar <i>new</i>			\$ 252.30
	Stabilizer Bar Bush (RH) <i>new</i>			\$ 16.40
	Stabilizer Bar Link <i>new</i>			\$ 61.10
	Stabilizer Bracket <i>new</i>			\$ 24.00
	Front Suspension Lower Arm (RH) <i>new dented</i>			\$ 529.30
	Knuckle Arm (RH) <i>new dented</i>			\$ 552.00
	ABS Sensor <i>new</i>			\$ 234.00
	Electric Power Steering <i>new</i>			\$ 3,641.00
			12759.80	
			10207.84	
				\$ 18,773.25
				\$ 3,754.65
				\$ 15,018.60
				SUB TOTAL
				LESS 20%
				DISCOUNTED TOTAL

Handwritten checkmarks and 'X' marks in the right margin, indicating item status. Includes a 'photo' label next to the Front Fender Apron Panel row.

SH 8963B

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Number Plate <i>distorted</i>			\$ 25.00	Nett ✓
	Front No Plate Trim Cover <i>broken</i>		45/-	\$ 30.00	Nett ✓
	Front Fender Advertisement Logo (RH) <i>hec</i>			\$ 100.00	Nett ✓
	Front Door Comfort Logo (RH) <i>hec NH</i>			\$ 75.00	Nett X
	Front Door Advertisement Logo (RH) <i>NH</i>		145.00	\$ 100.00	Nett X
	Front Tyre (RH) <i>NH</i>			\$ 216.00	Nett X
				\$ 546.00	
	Labour Charge				
	Panel Beating			\$ 800.00	600/-
	Spray Painting Charge			\$ 650.00	500/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 80.00	40/-
	Towing Charge			\$ 50.00	NH
	Remove/Refix Undercarriage (FRT)		1310.00	\$ 120.00	NH 80/-
	FRT Wheel Alignment			\$ 120.00	NH 60/-
	TOTAL LABOUR			\$ 1,870.00	
	Boot Lid <i>st</i>			\$ 2,174.90	✓
	Boot Lid Rubber <i>detmed</i>			\$ 96.50	✓
	Boot Lid Hinge (LH/RH) <i>NH</i>		\$ 142.30	\$ 284.60	X
	Boot Lid Lock Upper <i>not done</i>			\$ 102.60	✓
	Boot Lid Lock Lower <i>st</i>			\$ 31.70	✓
	Boot Lid 'H' Emblem <i>hec</i>			\$ 28.70	✓
	Boot Lid CRDI Plate <i>hec</i>			\$ 27.90	✓
	Boot Lid Lamp (LH) <i>ctac</i>			\$ 565.60	✓
	Licence Lamp (RH) <i>NH</i>			\$ 33.95	X
	Licence Lamp Garnish <i>rem</i>			\$ 380.80	X
	Licence Lamp Cover <i>rem</i>			\$ 100.00	X
	Rear Boot Protector <i>NH</i>			\$ 980.80	X
	Boot Lid Trimboard <i>NH</i>			\$ 116.40	X
	Boot Lid Trimboard Clips (10pcs) <i>NH</i>			\$ 11.00	X
	Bootlid Moulding <i>NH</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>NH</i>			\$ 27.90	X
	Bootlid Lower Garnish <i>NH</i>			\$ 227.90	X
	Rear Bumper <i>distorted / mounting st</i>			\$ 553.00	✓
	Rear Bumper Reinforcement <i>NH</i>			\$ 428.40	X
	Rear Bumper Reinforcement Bracket (LH/RH) <i>NH</i>		\$ 80.30	\$ 160.60	X
	Rear Bumper Clip 10 pcs <i>hec</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>NH</i>		\$ 35.60	\$ 71.20	X
	Rear Bumper Sponge <i>NH</i>			\$ 118.40	X
	Rear Bumper Under Cover <i>distorted</i>			\$ 228.00	✓

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SH 8963 B
Technician:
Mileage: 556289
Time Printed 30.8.19 11:10 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-0°27'		-3°00' 3°00'
4°10'		-0°19' 5°41'
-0°12'		-1°30' 1°30'
16°10'		
15°43'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°12'		-3°00' 3°00'
4°15'		-0°19' 5°41'
2°37'		-1°30' 1°30'
19°15'		
19°03'		

Front

	Actual	BEFORE	Specified Range
Cross Camber	-0°15'		-3°00' 3°00'
Cross Caster	-0°05'		-3°00' 3°00'
Cross SAI	-3°05'		-3°00' 3°00'
Total Toe	2°25'		-3°00' 3°00'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
-1°49'		-3°30' 2°30'
0°06'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-2°09'		-3°30' 2°30'
0°04'		-1°30' 1°30'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	0°20'		-3°00' 3°00'
Total Toe	0°10'		-3°00' 3°00'
Thrust Angle	0°01'		-3°00' 3°00'

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015333/DSF3N2

Date: 11/10/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80460632QMY
Claimant Vehicle No :	SH8963B	Insured Vehicle No :	SLE9495C
Date of Loss:	27/08/2019	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8963B	Engine No:	D4FDGU626251
Make & Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU090125
Reg. Date:	09/06/2016 (Man. Year: 2016)	Odometer:	556289 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	28,640.38	17,018.90	11,621.48	40.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,190.00	3,040.00	1,150.00	27.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	32,830.38	20,058.90	12,771.48	38.90
Approved Total (Overridden) (\$\$)		16,000.00		
(\$\$)	32,830.38	16,000.00	16,830.38	51.26
+ GST 7.00/7.00% (\$\$)	2,298.13	1,120.00	1,178.13	51.26
Nett Amount (\$\$)	35,128.51	17,120.00	18,008.51	51.26

INSPECTION

Date of Assignment:	29/08/2019	Inspected At:	Chunni Motor Work Pte Ltd - Amk
Date Inspected:	30/08/2019		Bik 10 #01-05/06, AMK Autopoint
			Singapore 568047

Estimated Period of Repair: 12.0 days

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2019)
Parts: 143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH8963B)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,265.90 FL	*2,265.90 FL
2	1		*BONNET LOCK	Not Necessary	36.90 FL	*- FL
3	1		*BONNET INSULATOR	Not Necessary	196.50 FL	*- FL
4	1		*BONNET INSULATOR CLIPS	Not Necessary	8.40 FL	*- FL
5	1		*RADIATOR GRILLE	Broken	1,110.10 FL	*1,110.10 FL
6	1		*RADIATOR GRILLE H EMBLEM	Necessary	39.50 FL	*39.50 FL
7	1		*FRONT BUMPER COVER	Torn	1,052.20 FL	*1,052.20 FL
8	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented/Bent	402.10 FL	*402.10 FL
10	1		*FRONT BUMPER GRILLE (RH)	Cut	93.60 FL	*93.60 FL
11	1		*FRONT BUMPER GRILLE AIRDUCT (RH)	Broken	26.20 FL	*26.20 FL
12	1		*FRONT BUMPER LIP	Not Necessary	54.90 FL	*- FL
13	1		*FRONT BUMPER BRACKET TOP (RH)	Not Necessary	22.40 FL	*- FL
14	1		*FRONT BUMPER BRACKET (RH)	Broken	24.60 FL	*24.60 FL
15	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
16	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
17	1		*HEADLAMP (RH)	Broken	1,388.00 FL	*1,388.00 FL
18	1		*RADIATOR	Bent/Punctured	698.30 FL	*698.30 FL
19	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Not Necessary	792.95 FL	*- FL
20	1		*RADIATOR EXPANSION TANK	Not Necessary	28.30 FL	*- FL
21	1		*RADIATOR GUARD	Not Necessary	20.00 FL	*- FL
22	1		*HORN UNIT (RH)	Not Necessary	73.80 FL	*- FL
23	1		*HORN WIRE	Not Necessary	156.50 FL	*- FL
24	1		*FRONT FENDER (RH)	Buckled	566.30 FL	*566.30 FL
25	1		*FRONT FENDER APRON PANEL (RH)	Dented/Bent	637.00 FL	*637.00 FL
26	1		*FRONT FENDER SHIELD (RH)	Deformed	174.90 FL	*174.90 FL
27	1		*AIRCON CONDENSER	Bent/Punctured	927.50 FL	*927.50 FL
28	1		*AIRCON SUCTION & LIQUID HOSE	Bent	624.00 FL	*624.00 FL
29	1		*AIRCON DISCHARGE HOSE	Bent	162.60 FL	*162.60 FL
30	1		*WIPER CONTAINER	Broken	61.90 FL	*61.90 FL
31	1		*WIPER CONTAINER MOTOR	Damaged	75.00 FL	*75.00 FL
32	1		*FRONT SHOCK ABSORBER (ASSY)(RH)	Distorted	342.20 FL	*342.20 FL
33	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Not Necessary	108.80 FL	*- FL
34	1		*STG TIE END	Not Necessary	62.60 FL	*- FL
35	1		*STABILIZER BAR	Not Necessary	252.30 FL	*- FL
36	1		*STABILIZER BAR BUSH (RH)	Not Necessary	16.40 FL	*- FL
37	1		*STABILIZER BAR LINK	Not Necessary	61.10 FL	*- FL
38	1		*STABILIZER BRACKET	Not Necessary	24.00 FL	*- FL
39	1		*FRONT SUSPENSION LOWER ARM (RH)	Distorted	529.30 FL	*529.30 FL
40	1		*KNUCKLE ARM (RH)	Distorted	552.00 FL	*552.00 FL
41	1		*ABS SENSOR	Not Necessary	234.00 FL	*- FL
42	1		*ELECTRIC POWER STEERING	Not Necessary	3,641.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*BOOT LID	Bent	2,174.90 FL	*2,174.90 FL
44	1		*BOOT LID RUBBER	Distorted	96.50 FL	*96.50 FL
45	2		*BOOT LID HINGE (LH/RH)	Not Necessary	284.60 FL	*- FL
46	1		*BOOT LID LOCK UPPER	Damaged	102.60 FL	*102.60 FL
47	1		*BOOT LID LOCK LOWER	Bent	31.70 FL	*31.70 FL
48	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
49	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
50	1		*BOOT LID LAMP LH	Cracked	565.60 FL	*565.60 FL
51	1		*LICENCE LAMP (RH)	Not Necessary	33.95 FL	*- FL
52	1		*LICENCE LAMP GARNISH	Repair	380.80 FL	*- FL
53	1		*LICENCE LAMP COVER	Repair	100.00 FL	*- FL
54	1		*REAR BOOT PROTECTOR	Not Necessary	980.80 FL	*- FL
55	1		*BOOT LID TRIMBOARD	Not Necessary	116.40 FL	*- FL
56	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
57	1		*BOOTLID MOULDING	Not Necessary	85.00 FL	*- FL
58	1		*BOOTLID 140 EMBLEM	Not Necessary	27.90 FL	*- FL
59	1		*BOOTLID LOWER GARNISH	Not Necessary	227.90 FL	*- FL
60	1		*REAR BUMPER	Distorted/Mounting Bent	553.00 FL	*553.00 FL
61	1		*REAR BUMPER REINFORCEMENT	Not Necessary	428.40 FL	*- FL
62	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	160.60 FL	*- FL
63	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
64	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
65	1		*REAR BUMPER SPONGE	Not Necessary	118.40 FL	*- FL
66	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
67	1		*TAIL LAMP (LH)	Mounting Cracked	697.80 FL	*697.80 FL
68	1		*TAIL LAMP QUARTER PANEL (LH)	Not Necessary	226.50 FL	*- FL
69	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
70	1		*REAR PANEL GARNISH	Not Necessary	57.70 FL	*- FL
71	1		*REAR PANEL LOWER PANEL	Damaged	495.50 FL	*495.50 FL
72	1		*EXHAUST PIPE INSULATOR,LH	Not Necessary	58.55 FL	*- FL
73	1		*EXHAUST SILENCER,LH	Not Necessary	967.70 FL	*- FL
74	1		*EXHAUST PIPE HANGER,LH	Not Necessary	58.55 FL	*- FL
75	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
76	1		*REAR FENDER (LH)	Dented	4,736.80 FL	*2,020.00 FL
77	1		*REAR FENDER INNER LINING (LH)	Not Necessary	169.30 FL	*- FL
78	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
79	1		*FRONT NO PLATE TRIM COVER }	Broken	30.00 FS	*45.00 FS
80	1		*FRONT NUMBER PLATE }	Dislodged	25.00 FS	*- FS
81	1		*FRONT FENDER ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
82	1		*FRONT DOOR COMFORT LOGO (RH)	Not Necessary	75.00 FS	*- FS
83	1		*FRONT DOOR ADVERTISEMENT LOGO (RH)	Not Necessary	100.00 FS	*- FS
84	1		*FRONT TYRE (RH)	Not Necessary	216.00 FS	*- FS
85	1		*BOOTLID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
86	1		*BOOTLID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
87	1		*REAR NO PLATE	Bent	25.00 FS	*25.00 FS
88	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
89	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
90	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
91	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 35,517.30 21,090.70
 - List Item Discount on L Items 20.00/20.00% (\$\$) 6,876.92 4,071.80

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	28,640.38	17,018.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	1,400.00
2	SPRAY PAINTING CHARGE	New	1,450.00	1,200.00
3	WIRING CHARGE	New	100.00	60.00
4	TUFF KOTE	New	130.00	80.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	120.00	80.00
7	FRT WHEEL ALIGNMENT	New	120.00	60.00
8	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	100.00	80.00
9	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
Gross Labour Cost (\$\$)			4,190.00	3,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >