

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19015376/T1PA3Q2

**Date:** 25/06/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	M497634
<b>Claimant</b>	<b>Insured Vehicle No :</b>	PC3929X
<b>Vehicle No :</b> SLS7565Z		
Date of Loss: 29/08/2019	Nature of Claim:	TP Claim No: MC20192231

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLS7565Z</b>		
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Engine No:	2ZRS083210
Reg. Date:	03/10/2017 (Man. Year: 2017)	Chassis No:	ZVW506090636
Colour:	White	Odometer:	147025 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,713.00	975.00	1,738.00	64.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	480.00	1,070.00	69.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,263.00</b>	<b>1,455.00</b>	<b>2,808.00</b>	<b>65.87</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,263.00</b>	<b>1,150.00</b>	<b>3,113.00</b>	<b>73.02</b>
<b>+ Car Rental (3.0 x S\$120.00/day) (S\$)</b>		360.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>1,517.45</b>		

#### INSPECTION

Date of Assignment:	25/09/2019	
Date Inspected:	25/09/2019	Inspected At: Ama Automotive Pte Ltd 36 Toh Guan Road East #01-36 Singapore 608580
Estimated Period of Repair:	2.0 days	

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 29 May 2020)
<b>Parts:</b> 144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLS7565Z)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Repair	1,294.00 FL	*- FL
2	1		*FRONT DOOR HANDLE RH	Repair	279.00 FL	*- FL
3	1		*FRONT DOOR HINGES LH	Not Necessary	214.00 FL	*- FL
4	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	236.00 FL	*- FL
5	1		*SIDE MIRROR COVER RH	Distorted	363.00 FL	*363.00 FL
6	1		*SIDE MIRROR GLASS RH	Distorted	280.00 FL	*280.00 FL
7	1		*SIDE MIRROR MOTOR RH	Distorted	473.00 FL	*473.00 FL
8	1		*SIDE MIRROR SIGNAL LIGHT RH	Distorted	184.00 FL	*184.00 FL
9	1		*SIDE MIRROR SIDE GARNISH RH	Not Necessary	241.00 FL	*- FL
10	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>3,604.00</b>	<b>1,300.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	891.00	325.00
<b>Total Parts (S\$)</b>	<b>2,713.00</b>	<b>975.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,REPLACE DAMAGED PARTS AND COMPONENTS	New	600.00	200.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED	New	600.00	250.00
3	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	150.00	30.00
4	TO REMOVE AND REFIX/REPLACE REAR TRIMS ,GARNISH AND FITTINGS SO AS TO FACILITATE REPAIRS AT REAR COMPARTMENT	New	100.00	0.00
5	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	100.00	0.00
			<b>Gross Labour Cost (\$\$)</b>	<b>480.00</b>
			<b>1,550.00</b>	<b>1,550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >