

T AUTOWORKS

Repair Estimate

Date: 28/08/2019

Refer
A

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SMH 595D
CHASSIS NO.: WVWZZZ13ZBV004660
ENGINE NO.: CAV210503

TP A14
Khanchar

Name of insured : Dickson Soh Ming Hao
Date of accident.: 24/08/2019

We append hereunder the estimated cost of repairs to be carried out

Parts

| No. | Qty | Part Description | |
|-----|-----|-----------------------------------|----------|
| 1 | 1 | REAR BUMPER Distal | 0.00 |
| 2 | 1 | REAR BUMPER REFLECTOR RH Bent New | 40.00 |
| 3 | 1 | REINFORCEMENT, RR END PANEL Bent | 0.00 |
| 4 | 1 | REAR BUMPER GUIDE CENTER New | 40.00 |
| 5 | 1 | REAR BUMPER GUIDE LH New | 40.00 |
| 6 | 1 | REAR VW EMBLEM | 0.00 |
| 7 | 1 | LETTERING SCIROCCO 2 New | 0.00 |
| 8 | 1 | REAR TAILGATE Bented | 1,761.30 |
| | | Reverse sensor | 1,080.00 |
| | | End | 40.00 |
| | | 10.57 | 2,881.30 |
| | | 1761.30 | 2,881.30 |
| | | Parts | 80.00 |
| | | Less | 2,305.04 |
| | | T | 0.00 |

Labour

| No. | Labour Description | |
|-----|---|--------------|
| 1 | To dismantle / renew the accident damaged portion, to pan beating, reshape, straighten, orientate and align repair / replacement parts. | 0.00 |
| 2 | Carry out spray painting on accident affected area. (Rear Tailgate, Rear bumper, Rear end panel) | L/S 2,300.00 |
| 3 | To disconnect wire harness of electrical component to faci repairs, reconnect and check electrical function after repair | 1080 |
| 4 | Remove and refit reverse sensor (Labour) | 130.00 S2 |

Labour Total : 4,280.00

Adrian Lij
L/S 29/08/19.
04 Days.

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel: 6844 1985 Fax: 6844 5185