

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19015378/AKA3N2  
**Date:** 21/07/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** SMH595D **Insured Vehicle No :** SKG1605G

Date of Loss: 24/08/2019 Nature of Claim: TP Claim No: 8279492263SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMH595D</b>	Engine No:	CAV210503
Make & Model:	VOLKSWAGEN SCIROCCO, 1.4 (A)	Chassis No:	WVWZZZ13ZBV004660
Reg. Date:	04/10/2010 (Man. Year: 2010)	Odometer:	195809 km
Colour:	White		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	3,952.30	1,801.30	2,151.00	54.42	
Miscellaneous Items	0.00	0.00	0.00		
Labour	4,280.00	1,080.00	3,200.00	74.77	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>8,232.30</b>	<b>2,881.30</b>	<b>5,351.00</b>	<b>65.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>2,300.00</b>			
	<b>(S\$)</b>	8,232.30	2,300.00	5,932.30	72.06
<b>+ GST 7.00/7.00% (S\$)</b>	576.26	161.00	415.26	72.06	
<b>Nett Amount (S\$)</b>	<b>8,808.56</b>	<b>2,461.00</b>	<b>6,347.56</b>	<b>72.06</b>	
<b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b>		240.00			
	<b>Nett Liability (S\$)</b>	<b>2,701.00</b>			
	<b>Global Sum Settlement (S\$)</b>	<b>2,700.00</b>			

#### INSPECTION

Date of Assignment: 29/08/2019

Date Inspected: 29/08/2019 Inspected At: 1st Autoworks Pte Ltd (HQ)  
23 Kaki Bukit Ave 4, #04-01  
Singapore 415933

Estimated Period of Repair: 4.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,200.00 FL	*1,200.00 FL
2	1		*REAR BUMPER REFLECTOR RH	Not Necessary	130.00 FL	*- FL
3	1		*REINFORCEMENT ,RR END PANEL	Bent	390.00 FL	*390.00 FL
4	1		*REAR BUMPER GUIDE CENTER	Not Necessary	130.00 FL	*- FL
5	1		*REAR BUMPER GUIDE LH	Damaged	87.00 FL	*87.00 FL
6	1		*REAR VW EMBLEM	Not Necessary	120.00 FL	*- FL
7	1		*LETTERING SCIROCCO	Not Necessary	110.00 FL	*- FL
8	1		*REAR TAILGATE	Not Necessary	1,800.00 FL	*- FL
9	1		*REVERSE SENSOR	Damaged	280.00 FL	*280.00 FL
10	1		*SEALANT	Not Necessary	50.00 FS	*- FS
11	1		*REAR NUMBER PLATE	Not Necessary	40.00 FS	*- FS
12	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>4,377.00</b>	<b>1,997.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	424.70	195.70
<b>Total Parts (\$)</b>	<b>3,952.30</b>	<b>1,801.30</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	2,100.00	400.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (REAR TAILGATE ,REAR BUMPER ,REAR END PANEL)	New	1,900.00	600.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	150.00	30.00
4	REMOVE AND REFIT REVERSE SENSOR	New	130.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,280.00</b>	<b>1,080.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >