

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG19015528/T1SF3E2

Date: 15/12/2020

REFERENCE

Insured/Claimant:	SCOTT GRAHAM	Policy No:	2100387642		
Date of Loss:	29/08/2019	Nature of Claim:	OD	Claim No:	3464167061SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP6895E	Engine No:	CHP172623
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZ8U2ER118740
Reg. Date:	30/09/2014 (Man. Year: 2014)	Odometer:	79443 km
Colour:	Silver		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$82,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/40 R19	Rear Tyre Size:	255/40 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,800.60	5,071.92	6,728.68	57.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,092.00	4,592.00	5,500.00	54.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,892.60	9,663.92	12,228.68	55.86
+ GST 7.00/7.00% (S\$)	1,532.48	676.47	856.01	55.86
Nett Amount (S\$)	23,425.08	10,340.39	13,084.69	55.86

INSPECTION

Date of Assignment:	03/09/2019		
Date Inspected:	02/09/2019	Inspected At:	24 BENOI SECTOR Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	11.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER LOWER SPOILER (NPA)	Not Necessary	0.00 FS	*- FS
2	1		*WHEEL ARCH TRIMS	Cut	373.60 FS	*373.60 FS
3	1		*FRONT DOOR - RH	Bent	2,412.00 FS	*1,929.60 FS
4	1		*OUTER DOOR SEAL - RH	Necessary	151.00 FS	*121.20 FS
5	1		*PROTECTIVE FILM	Not Necessary	24.00 FS	*- FS
6	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	97.00 FS	*- FS
7	1		*FRONT DOOR CATCH	Not Necessary	109.00 FS	*- FS
8	1		*BONDING AGENT	Necessary	45.00 FS	*35.92 FS
9	1		*FRONT DOOR MOUNTING BAR	Not Necessary	110.00 FS	*- FS
10	1		*EXTERIOR DOOR HANDLE	Not Necessary	137.00 FS	*- FS
11	1		*DOOR HANDLE CAP - PASSENGER DOOR	Not Necessary	27.00 FS	*- FS
12	1		*OUTER WINDOW APERTURE SEAL - RH	Not Necessary	152.00 FS	*- FS
13	1		*WINDOW REGULATOR WITHOUT MOTOR - RH	Not Necessary	250.00 FS	*- FS
14	1		*REAR DOOR - RH	Bent	2,412.00 FS	*1,929.60 FS
15	1		*OUTER DOOR SEAL - RH	Necessary	157.00 FS	*125.60 FS
16	1		*DOOR SEAL BRACKET - RH REAR	Not Necessary	17.00 FS	*- FS
17	1		*REAR DOOR CATCH	Not Necessary	109.00 FS	*- FS
18	1		*DOOR SEAL BRACKET - RH REAR	Not Necessary	17.00 FS	*- FS
19	1		*WINDOW APERTURE SEAL - RH OUTER	Not Necessary	185.00 FS	*- FS
20	1		*DOOR COVER (NPA)	Not Necessary	0.00 FS	*- FS
21	1		*ALUMINIUM RIM (NPA)	Not Necessary	0.00 FS	*- FS
22	1		*GOOD YEAR EAGLE F1	Punctured	450.00 FS	*450.00 FS
23	1		*SUNDRIES	Necessary	600.00 FS	*76.32 FS
24	1		*HEADLIGHT RHS	Not Necessary	1,885.00 FS	*- FS
25	1		*WATER DEFLECTOR RHS	Not Necessary	61.00 FS	*- FS
26	1		*DATA PLATE FOR TYRE PRESSURE	Necessary	38.00 FS	*30.08 FS
27	1		*DOOR COVER RHS FRONT	Not Necessary	233.00 FS	*- FS
28	1		*FRONT BUMPER	Repair	1,749.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 11,800.60 5,071.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH RHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	560.00	560.00
3	TO DISMANTLE AND RENEW FRONT BUMPER ASSY, RHS FRONT AND REAR DOORS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,000.00
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT AND REAR DOORS, DOOR HANDLE, AND RHS WING MIRROR COVER	New	4,300.00	1,650.00
5	TO RENEW RHS FRONT RIM AND TYRE. CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO RESPRAY BONNET	New	1,200.00	550.00
Gross Labour Cost (S\$)			10,092.00	4,592.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >