

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19015548/R1KA3Q2

Date: 15/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100426626

Claimant
Vehicle No : SKN3595B **Insured Vehicle No :** SGJ2052B

Date of Loss: 31/08/2019 Nature of Claim: TP Claim No: 7296510061SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN3595B		
Make & Model:	VOLKSWAGEN GOLF, 1.4 TSI (A)	Engine No:	CXS092598
Reg. Date:	05/06/2014 (Man. Year: 2014)	Chassis No:	WVWZZZAUZEW359494
Colour:	White	Odometer:	104040 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,391.88	0.00	1,391.88	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,360.00	3,760.00	2,600.00	40.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,751.88	3,760.00	3,991.88	51.50
+ GST 7.00/7.00% (S\$)	542.63	263.20	279.43	51.50
Nett Amount (S\$)	8,294.51	4,023.20	4,271.31	51.50
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,445.20		

INSPECTION

Date of Assignment: 05/09/2019

Date Inspected: 05/09/2019 Inspected At: Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Repair	1,080.14 FS	*- FS
2	1		*REAR DIFFUSOR SATIN BLACK	Not Necessary	277.23 FS	*- FS
3	1		*GUIDE PIECE	Not Necessary	34.51 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					1,391.88	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	0.00
3	LABOUR	New	3,200.00	1,680.00
4	SPRAY PAINTING	New	2,400.00	1,600.00
Gross Labour Cost (\$\$)			6,360.00	3,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >