

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19015550/R1PA3Q2

Date: 09/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SGX7879B	Insured Vehicle No :	SHD3231P
Date of Loss: 27/08/2019	Nature of Claim: TP	Claim No: MCT19080706

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGX7879B		
Make & Model:	HONDA CIVIC, 2.0 (A)	Engine No:	K20Z22501661
Reg. Date:	12/11/2007 (Man. Year: 2007)	Chassis No:	JHMF26407S201662
Colour:	Black	Odometer:	156581 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	966.21	613.97	352.24	36.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	990.00	190.00	16.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,146.21	1,603.97	542.24	25.27
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	2,146.21	1,300.00	846.21	39.43
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,307.45		

INSPECTION

Date of Assignment:	02/09/2019	
Date Inspected:	04/09/2019 Inspected At:	AUTOCLINIC PTE LTD 48 TOH GUAN ROAD EAST #02-136, ENTERPRISE HUB, SINGAPORE 608586
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2020)
Parts:	143	HONDA CIVIC 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGX7879B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*24 REAR BOOT LOCK	Scratched	347.75 F	*194.50 FL
2	1		*27 REAR BOOT RUBBER	Cut	160.50 F	*115.00 FL
3	1		*15 REAR BUMPER	Deformed	457.96 F	*457.96 FL
					Sub Total (\$\$)	966.21 767.46
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 153.49
					Total Parts (\$\$)	966.21 613.97

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR WORKS FOR SPRAY PAINTING	New	680.00	600.00
2	CHECK WIRING AND LIGHTING	New	60.00	40.00
3	REMOVE AND REFIT REAR UNDERCARRIAGE PANEL PARTS }	New	320.00	350.00
4	PANEL BEATING (LABOUR CHARGES) }	New	120.00	0.00
Gross Labour Cost (\$\$)			1,180.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >