

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 6349A

DATE 2/9/2019 13:06

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 459.40	
	Rear Bumper Reinforcement ?			\$ 294.80	
	Rear Bumper Reinforcement Bracket (LH) ?			\$ 138.10	
	Rear Bumper Centre Moulding Assy ✓			\$ 451.25	
	Rear Bumper Side Bracket (LH) X			\$ 33.10	
	Rear Bumper Cover Clips ✓			\$ 22.00	
	Rear Bumper Side Under(LH) X			\$ 27.50	
	Rear Bumper Reflector Lamp (LH) ✓			\$ 31.90	
	Rear Bumper Towing Cover ✓			\$ 98.80	
	Tail Lamp (LH) X			\$ 870.40	
	<i>Rear Fender (LH) X repair</i>				
	<i>Rear Tail/Lights X repair</i>				
	SUB TOTAL			\$ 2,427.25	
	LESS 20%			\$ 485.45	
	DISCOUNTED TOTAL			\$ 1,941.80	
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating-Repair Rear LH Fender			\$ 400	
	Spray Painting Charge			\$ 500.00	
	Wiring Charge			\$ 50.00	
	Remove/Refix Reverse Sensor			\$ 120.00	
	TOTAL LABOUR			\$ 1,170.00	
	ESTIMATE TOTAL			\$ 3,297.50	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalina 10/10/19

2/9/19 1525hrs.
3 Days.

PIP
Before Part photo

600

800

X

20