

15/5/2019

INS. CASE OWNER:

CC3 / CTI1901

5580

Keb352

LKK:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT
2/1/19

Date / Time:

Malay

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDN 8203H

Claim No.:

Name of Insured:

THASNEEM PARVEEN D/O SIKANDAR

Policy No.:

DMPICN210187900

Insured Tel No.:

HP:

Make / Model:

Toyota

Excess Sec II :SS

D.O.A.:

29/8/19

Place of Accident:

JUNE OF BANGKOK EXT DR

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHD 9723Y

INSRS:
WSP: Tams
Tel:
Liability: CUB
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
04-12-19	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	EMAIL 26.09.19
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☒ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☒ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA:	☒ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD:	☒ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSC

Repair Cost:

45 SS 6,800

(7 days) Reduction:

90 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 05.03.20

Confirm with: W/44

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

w/451

SS 7,216.00

OI SWEETED INTO TP

HIT TP STATIONARY YES

Loss of Rental (LOR):

SS 892.43

(11 days) x 81.13

Loss of Use (LOU):

SS -

(\$ x 11 days)

Loss of Income (LOI):

SS 550.00

(\$ 50 x 11 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LO ☒

[Tick only one]

GIA/LTA Search

SS 1.49

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 8,725.93

Global Sum SS:

FINAL PAYMENT

Date/Time: 05.03.20

Confirm with: W/44

Email ☒ Call ☐

Payee 1:

SS 8,725.93

Name 1:

TRANS-CAB AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.):

SS

Name 2:

Payee 3: (Strike if N.A.):

SS

Name 3:

COPY SENT
24/10/20

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

9400

ASS. REC. BY:

REF:

C12/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 97034

Yr Regn:

12, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Renault Coradia

c.c

1995

Colour:

N. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

684410

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABU15AUC 276073

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N / S / Rim / STD A / Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

29/8/19

D.O.I.

2/9/19

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

O/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

45: +6,800 (RED: +64,087.26 90%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTII9015580/Keb3

Date: 03.09.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SHD9723Y

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02.09.2019 at the premises of M/s Trans-cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	70,887.26
Revised Estimate Amount	: S\$	8,503.29
"Check" Items Amount	: S\$	5,794.86
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
O/S Body



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 7 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9723Y**AAD1908-236***Not Authoink**61 Smp 8*

Vehicle No.:

02 SEP 2019

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9723Y

VF1ABL15AUC276073

RENAULT

LATITUDE

29.8.19

CHINA TAIPING

4/12/2013

PART**LIST**

- | | | |
|----|---|---------------------------------|
| 1 | 1 | BUMPER COVER REAR |
| 2 | 1 | BUMPER LOWER REAR |
| 3 | 1 | BUMPER BRACKET CTR REAR |
| 4 | 1 | BUMPER BRACKET SIDE RH REAR |
| 5 | 1 | BUMPER RETAINER RH REAR |
| 6 | 1 | BUMPER REFLECTOR RH |
| 7 | 1 | BUMPER BEAM REAR |
| 8 | 1 | BUMPER BEAM BRACKET RH REAR |
| 9 | 1 | FENDER PANEL INNER TRIM REAR RH |
| 10 | 1 | FENDER PANEL REAR RH |
| 11 | 1 | WHEELARCH REAR RH |
| 12 | 1 | BOOT REFLECTOR LAMP RH |
| 13 | 1 | TAILLAMP RH |
| 14 | 1 | TAILLAMP PANEL RH |
| 15 | 1 | KNUCKLE ARM REAR RH L70Y |
| 16 | 1 | BRAKE DISC REAR L70Y |
| 17 | 1 | WHEEL HUB NUT L70Y |
| 18 | 1 | WHEEL HUB CAP L70Y |
| 19 | 1 | ABS SENSOR REAR RH L70Y |
| 20 | 1 | REAR AXLE L70Y |
| 21 | 1 | AXLE ARM RH L70Y |
| 22 | 1 | LOWER ARM REAR RH L70Y |
| 23 | 1 | ABSORBER REAR |
| 24 | 1 | STABILIZER BAR REAR RH |
| 25 | 1 | BRAKE CALIPER REAR RH |
| 26 | 1 | DOOR PANEL REAR RH |
| 27 | 1 | DOOR LOCK REAR RH |
| 28 | 1 | DOOR CATCH REAR RH |
| 29 | 1 | DOOR PANEL FRONT RH |
| 30 | 1 | DOOR MIRROR ASSY RH |

\$	<i>Bu</i>	1,108.46	✓
\$	<i>Sn</i>	811.44	X
\$	<i>Sn</i>	196.00	X
\$	<i>Sn</i>	161.73	X
\$	<i>Sn</i>	108.40	X
\$	<i>Sn</i>	43.61	X
\$	<i>N</i>	1,068.21	X
\$	<i>N</i>	225.95	X
\$	<i>Sn</i>	671.45	X
\$	<i>Bu</i>	3,866.40	✓
\$	<i>Sn</i>	543.47	X
\$	<i>Sn</i>	547.07	X
\$	<i>Sn</i>	616.81	X
\$	<i>N</i>	986.70	X
\$		930.04	X
\$		525.91	X
\$		83.60	X
\$		61.00	X
\$		255.75	X
\$	<i>Sn</i>	6,851.28	X
\$		139.00	X
\$		1,070.70	X
\$		428.08	X
\$	<i>Sn</i>	843.00	X
\$	<i>Sn</i>	1,300.67	X
\$	<i>N</i>	2,844.66	X
\$	<i>N</i>	922.92	X
\$	<i>N</i>	179.10	X
\$	<i>N</i>	2,844.66	X
\$	<i>Sn</i>	1,483.40	?

Trans-cab Auto Services Pte Ltd

AAD1908-236

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9723Y

31	1	BUMPER COVER FRT	\$	R	1,494.40	X
32	1	BUMPER RETAINER FRT RH	\$	Sn	199.76	X
33	1	BUMPER SUPPORT FRT	\$	Sn	123.88	X
34	1	BUMPER FOG LAMP GRILLE RH	\$	Sn	207.21	X
35	1	HEADLAMP RH	\$	Sn	1,468.61	X
36	1	HEADLAMP PANEL FRT RH	\$	R	251.60	X
37	1	BONNET	\$	R	2,586.02	X
38	1	BONNET HINGE RH	\$	R	467.68	X
39	1	FENDER INSULATOR RH	\$	Sn	132.60	X
40	1	FENDER PANEL FRT RH	\$	R	828.80	✓
41	1	WHEELARCH FRT RH	\$	Sn	442.46	} X
42	1	FENDER BRACKET LOWER RH	\$	Sn	23.60	
43	1	WIPER RESERVOIR	\$	Sn	497.50	
44	1	WIPER RESERVOIR NECK	\$	Sn	218.29	
45	1	WIPER RESERVOIR MOTOR	\$	Sn	627.76	
46	1	ROCKER PANEL INNER GARNISH RH	\$	Sn	466.51	
47	1	ROCKER PANEL INNER RH	\$	R	1,024.79	
48	1	ROCKER PANEL OUTER RH	\$	R	1,184.99	
49	1	ROCKER PANEL CENTER RH	\$	R	990.25	
50	1	LOWER ARM RH L70Y	\$	Sn	685.76	
51	1	KNUCKLE ARM RH L70Y	\$	Sn	948.60	
52	1	ABSORBER FRT RH L70Y	\$	Sn	400.90	
53	1	DRIVESHAFT RH	\$	R	2,670.73	
54	1	STABILIZER BAR FRT	\$	Sn	843.00	
55	1	DOOR HARNESS WIRE RH	\$	Sn	2,670.00	
TOTAL			\$		53,175.18	
10%			\$		5,317.52	
			\$		47,857.66	

Special Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	Sn	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	Sn	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	Sn	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	Sn	20.00	X
6	1SET	BUMPER LOWER REAR CLIP	\$	Sn	66.00	X
7	1SET	FENDER WHEELARCH REAR RH CLIP	\$	Sn	35.00	X
8	1	FENDER INNER TRIM CLIP RH	\$	Sn	28.00	X

Trans-cab Auto Services Pte Ltd

AAD1908-236

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9723Y

9	1	TAILLAMP CLIP RH	\$	nn	5.00	X	
10	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	40sn	
11	1	WINDSCREEN MOULDING	\$	nn	100.00	✓	
12	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	30sn	
13	1SET	BUMPER CLIP FRT	\$	nn	66.00	} X	
14	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00		
15	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50		
16	1	WHEELARCH CLIP FRT RH	\$	nn	30.50		
17	1	BONNET STRUT L70Y	\$	sn	106.60		
18	1	REAR RH DOOR STICKER '6555-3333'	\$	nn	80.00		
19	1	FRONT DOOR STICKER 'Trans-Cab'	\$	nn	80.00		} X
20	1	FRONT DOOR STICKER 'Classic'	\$	nn	80.00		
21	1	FRONT RIGHT TYRE	\$	sn	300.00		
22	1	FRONT RIGHT TYRE RIM	\$	sn	380.00	} 80sn	
23	1	REAR RIGHT TYRE	\$	nd0	sn		300.00
24	1	REAR RIGHT TYRE RIM	\$	sn	380.00		✓
25	1	FRONT RH HUB CAP	\$	nn	61.00	✓	

TOTAL	\$	3,129.60
--------------	-----------	-----------------

TOTAL PARTS	\$	50,987.26
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	9401
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	9001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	380.00	X

Trans-cab Auto Services Pte Ltd

AAD1908-236

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9723Y

To Check Electrical Lighting Concerned.	\$	170.00	201
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
Towing Fees	\$	170.00	601 501
To check steering geometry and computer wheel alignment	\$	220.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	} 1001
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	340.00	
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 180.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	4 180.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	4 170.00	X
To Transfer Of Rear Fender Fittings, Attachments And Perform Water Seepage Test.	\$	4 340.00	X
To check ABS and brake efficiency, final checking and testing.	\$	4 380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	4 380.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	4 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1908-236**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9723Y

To transfer of tire, rim and on wheel balancing.	\$	170.00	201
TOTAL	\$	19,900.00	
Over All Total	\$	70,887.26	

Repair Days (LUMP SUM)**25 DAYS**
7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD9723Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Aug 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000709
Chassis No.:	VF1ABL15AUC276073
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	04 Dec 2013
First Registration Date:	04 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Dec 2021
PARF Rebate Amount:	\$8,748.00

Intended COE Rebate Details

COE Expiry Date:	03 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$62,740.00
COE Rebate Amount:	\$17,708.00
Total Rebate Amount:	\$26,456.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Aug 2019

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI19015580/Kea3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 23-03-2020	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDN 8203H	Veh. Inspected	SHD 9723Y	
Policy No.	DMPCSN3002181900	Coverage (\$)	0.00	
Claim No.	SNM19D204066	Excess (\$)	0.00	
Assign From		Assign Date	02/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	VF1ABL15AUC276073	Colour	METALLIC WHITE / RED	
Odometer	684410	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/08/2019	Inspection Date	02/09/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9723Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	SERVICEABLE	811.44	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	196.00	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	161.73	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	108.40	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	1,068.21	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	BENT	3,866.40	3,866.40
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	547.07	-
1	TAILLAMP RH	SERVICEABLE	616.81	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	KNUCKLE ARM REAR RH L70Y	SERVICEABLE	930.04	-
1	BRAKE DISC REAR L70Y	SERVICEABLE	525.91	-
1	WHEEL HUB NUT L70Y	SERVICEABLE	83.60	-
1	WHEEL HUB CAP L70Y	SERVICEABLE	61.00	-
1	ABS SENSOR REAR RH L70Y	SERVICEABLE	255.75	-
1	REAR AXLE L70Y	SERVICEABLE	6,851.28	-
1	AXLE ARM RH L70Y	SERVICEABLE	139.00	-
1	LOWER ARM REAR RH L70Y	SERVICEABLE	1,070.70	-
1	ABSORBER REAR	SERVICEABLE	428.08	-
1	STABILIZER BAR REAR RH	SERVICEABLE	843.00	-
1	BRAKE CALIPER REAR RH	SERVICEABLE	1,300.67	-
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR LOCK REAR RH	TO REPAIR SEE LABOUR	922.92	-

Report Ref No. CC3/CT119015580/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR CATCH REAR RH	TO REPAIR SEE LABOUR	179.10	-
1	DOOR PANEL FRONT RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	BUMPER COVER FRT	TO REPAIR SEE LABOUR	1,494.40	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	199.76	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	HEADLAMP RH	SERVICEABLE	1,468.61	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	251.60	-
1	BONNET	TO REPAIR SEE LABOUR	2,586.02	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	467.68	-
1	FENDER INSULATOR RH	SERVICEABLE	132.60	-
1	FENDER PANEL FRT RH	BENT	828.80	828.80
1	WHEELARCH FRT RH	SERVICEABLE	442.46	-
1	FENDER BRACKET LOWER RH	SERVICEABLE	23.60	-
1	WIPER RESERVOIR	SERVICEABLE	497.50	-
1	WIPER RESERVOIR NECK	SERVICEABLE	218.29	-
1	WIPER RESERVOIR MOTOR	SERVICEABLE	627.76	-
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL OUTER RH	TO REPAIR SEE LABOUR	1,184.99	-
1	ROCKER PANEL CENTER RH	TO REPAIR SEE LABOUR	990.25	-
1	LOWER ARM RH L70Y	SERVICEABLE	685.76	-
1	KNUCKLE ARM RH L70Y	SERVICEABLE	948.60	-
1	ABSORBER FRT RH L70Y	SERVICEABLE	400.90	-
1	DRIVESHAFT RH	TO REPAIR SEE LABOUR	2,670.73	-
1	STABILIZER BAR FRT	SERVICEABLE	843.00	-

Report Ref No. CC3/CTI19015580/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR HARNESS WIRE RH	SERVICEABLE	2,670.00	-
	LESS 10% DISCOUNT		-5,317.51	-580.37
			47,857.66	5,223.29
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NOT NECESSARY	66.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	SET BUMPER CLIP FRT (SN)	NOT NECESSARY	66.00	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	WHEELARCH CLIP FRT RH (SN)	NOT NECESSARY	30.50	-
1	BONNET STRUT L70Y (SN)	SERVICEABLE	106.60	-
1	REAR RH DOOR STICKER '6555-3333' (SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR STICKER 'TRANS-CAB' (SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR STICKER 'CLASSIC' (SN)	NOT NECESSARY	80.00	-
1	FRONT RIGHT TYRE (SN)	SERVICEABLE	300.00	-
1	FRONT RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	REAR RIGHT TYRE (@ \$300.00 DISC 80%) (SN)	PUNCTURE	300.00	240.00
1	REAR RIGHT TYRE RIM (SN)	BENT	380.00	380.00
1	FRONT RH HUB CAP (SN)	MISSING	61.00	61.00
			3,129.60	950.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		7,500.00	940.00

Report Ref No. CC3/CT19015580/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR, BUMPER BEAM BRACKET RH REAR, TAILLAMP PANEL RH, DOOR PANEL REAR RH, DOOR LOCK REAR RH, DOOR CATCH REAR RH, DOOR PANEL FRONT RH, BUMPER COVER FRT, HEADLAMP PANEL FRT RH, BONNET, BONNET HINGE RH, ROCKER PANEL INNER RH, ROCKER PANEL OUTER RH, ROCKER PANEL CENTER RH AND DRIVESHAFT RH.		7,500.00	900.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO DISMANTLE AND REFIT REAR AXLE HOUSING ASSY, REMOVE AND RENEWAL OF PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TOWING FEES.		170.00	50.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR. }		380.00	100.00
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		340.00	-
	TO TRANSFER OF FRONT BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	180.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	340.00	-
	TO CHECK ABS AND BRAKE EFFICIENCY, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-

Report Ref No. CC3/CTI19015580/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.		170.00	20.00
			19,900.00	2,330.00
GRAND TOTAL			70,887.26	8,503.29
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,800.00

Report Ref No. CC3/CTI19015580/Kea3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.