

ASS. REC. BY:

REF: CS/SMO19015581/bqf3m2 Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

From (Person): Agnes Chan Shu Hui of SMD Date/Time: 3.9.19 15.39pm

Estimated Cost: Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SHA 8925 Insured: SBV 707E

at Workshop m/s Chummi Motor Tel: 65425119

of BHC 10 #01-05/06 AMK Autopoint

Policy No: D9MTPV01010238 Claim No: CMTD1904162

Sum Insured: Excess:

Make of Veh: D.O.A. 1.9.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 3.9.19 4.13 p.m. Person Contacted: Lynn H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 8925 - CSI FCI17009726/Gthn2 DOA - 1/10/57 2017
	SBV 707E - x
09/9/19 @ 3.41pm	revised to Agnes Chan via Merimen.

08/11/14

REF:

Surrey Bryan

ASSIGNMENT

COR Aug 2023

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 ~~10~~ days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHIA 892 S Yr Regn: 2015 Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 c.c. 1685

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 431712 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDPU538540

C/No: KMHLB41UMGU077055

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: - 11 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 01/09/2019 D.O.I. 04/09/2019

Survey held at Chunni AMIC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front y Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Sampo SBV 707 E

15/10/19 Jinnu 215 17000/- with 14 days of rev
(Per 15305.18, 47%)

RECEIVED 13 OCT 2019

Date/Time, File Pass to?

☐

: Preli. Report

11/6/10 Jinnu

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: MER-TP

Lump Sum / I.B.V. (\$) 17000

450

11

461

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 09 Sep 2019

Preliminary Advice

Insured Vehicle No	: SBV707E	Accident Date	: 01/09/2019
TP Vehicle No	: SHA892S	Assignment Date	: 03/09/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 10.00
Date of Inspection	: 04/09/2019		
Inspection At	: CHUNNI MOTOR WORK PTE LTD - AMK (HQ) BLK 10 #01-05/06, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,305.18
Revised Amount	:S\$	21,587.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	21,587.30

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Sep 2019		03 Sep 2019 15:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		ONG CHUEN TAI, ID: S1611870B, Tel: +6597438631, Email: NOEMAIL							
Main Claimant:		CITYCAB PTE LTD, Co. Reg. No.: 199502839G							
Vehicle Reg. No.:		SHA892S	Date of Loss:	01/09/2019 19:00 - :59					
Claim Type:		TP / CMTD1904162	Policy/Cover Note No.:	D19MTPV01010238 (Comprehensive)					
Vehicle Reg. No. (Insured):		SBV707E	Policy No. (Claimant):						
		Excess:							
Repairer:		Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016							
Handling Insurer:		Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/09/2019]							
Driver/Custodian (Insured):		ONG CHUEN TAI (56 / Male), NRIC: S1611870B, Tel: +6597438631 Email: NOEMAIL							
Adj Asg. Remarks:		WS: Lynn or Irene 6542 5119 or 7162							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	839G
Vehicle Details	
Vehicle No.:	SHA892S
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Sep 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Primary Colour:	Yellow
Manufacturing Year:	2015
Engine No.:	D4FDFU538540
Chassis No.:	KMHLB41UMGU077055
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$20,370.00
Original Registration Date:	13 Aug 2015
First Registration Date:	13 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$20,518.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Aug 2023
PARF Rebate Amount:	\$15,388.00
Intended COE Rebate Details	
COE Expiry Date:	12 Aug 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,236.00
COE Rebate Amount:	\$24,645.00
Total Rebate Amount:	\$40,033.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 09 Sep 2019

MCD619115973 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 02/09/2019 15:30
 SUBMITTED BY: Huang XiaoYan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 02/09/2019 15:30
 Date Of Accident 01/09/2019 19:30
 Exact Location Of Accident PIE TWDS CHANGI AIRPORT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA892S
 Insured/Policyholder
 Name Of Registered Owner CITYCAB PTE LTD
 Co Reg No 199502839G
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088937MFSH
 Cover Note Number
 Driver
 Name of Driver TAN BEE WEE (CHEN MEIWEI)
 NRIC No S7306658A
 Date Of Birth 20/02/1973
 Occupation OUTDOOR
 Date Of Driving Pass 27/04/1993
 Driving Experience 26 YEARS AND 4 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-92714342
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address 4 SEMBONG ROAD
 Postcode 758329
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 6
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: -
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SBV707E
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver ONG CHUEN LAI
 NRIC/Passport Number
 Contact Number 97438631
 Address
 Postcode
 Insurance Company Name SOMPO INSURANCE SINGAPORE PTE. LTD.
 Nature Of Damage REAR AND FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR AND FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR AND FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAN BEE WEE (CHEN MEIWEI)

Approximate Age

46

Injuries Sustain

NECK PAIN

Injured person in which vehicle?

SHA892S

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD
CO. REG. NO. 199502839G

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)

Date & Time: 02.09.2019@1000HRS

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.: June

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 01.09.2019 @ 1930hrs I was travelling along PIE twds Changi Aiport with one female passenger onboard.

As veh(C) slowed down and I followed suddenly I felt an impact from my rear portion from veh(B) SBV 707E and caused my vehicle to surge forward.

There's 6 vehicles involved in this accident.

As it took place too fast I could not take evasive action to prevent the accident .

I have company and photos and video at scene to support my claims .

After the accident I felt pain on my neck and will consult a doctor later.

Veh(B) SBV 707E MR Ong Chuen Lai HP: 9743 8631

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD

CO. REG. NO. 199502839G

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 02.09.2019@1000HRS

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: June

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 892S

DATE : 2.09.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039


Sump 0

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille broken			\$ 1,110.10	✓
	Radiator Grille H Emblem New			\$ 39.50	✓
	Front Bumper Cover Dented			\$ 1,052.20	✓
	Front Bumper Sponge torn			\$ 99.20	✓
	Front Bumper Reinforcement Dented			\$ 402.10	✓
	Front Bumper Bracket Top (LH/RH) NH	S	22.40	\$ 44.80	X
	Front Bumper Bracket (LH/RH) NH	S	24.60	\$ 49.20	X
	Headlamp Support Top Cover NH			\$ 222.60	X
	Headlamp Support Panel Assy Bt/Cricle			\$ 907.40	✓
	Headlamp (LH/RH) mostly broken	S	1,388.00	\$ 2,776.00	✓ photo
	Radiator Z Bt			\$ 698.30	✓
	Radiator Fan Blade, Cowling, Motor Assy NH Cricle housing			\$ 792.95	X ✓
	Radiator Bracket (RH/LH) NH	S	6.50	\$ 13.00	X
	Radiator Guard broken	S	20.00	\$ 40.00	✓
	Horn Unit (LH/RH) broken	S	73.80	\$ 147.60	✓
	Aircon Condenser Z Bt			\$ 927.50	✓
	Inter Cooler Z Bt			\$ 1,032.50	✓
	Inter Cooler Mounting (2 PCS) NH			\$ 25.90	X
	Wiring-ECM NH photo taken			\$ 3,243.00	X
			10025.35		
			8020.28		
	SUB TOTAL			\$ 13,623.85	
	LESS 20%			\$ 2,724.77	
	DISCOUNTED TOTAL			\$ 10,899.08	
	Front Number Plate Bt			\$ 25.00	Nett ✓
	Front No Plate Trim Cover Bt			\$ 30.00	Nett ✓
			45/-		
			45.00	\$ 55.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	500/-
	Spray Painting Charge			\$ 500.00	200/-
	Wiring Charge			\$ 50.00	30/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Remove/Refix Dashboard			\$ 450.00	44
	Remove/Refix Fuse Box			\$ 180.00	NH
			810.00		
	TOTAL LABOUR			\$ 2,330.00	

SHA 892S

[illegible]

SHA 892S

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,800.00
	Spray Painting Charge			\$ 1,500.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass		2130.00	\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Exhaust Pipe			\$ 300.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 4,620.00
	ESTIMATE TOTAL			\$ 32,123.98
	04/09/2019 @ 1030hrs hba Andrew 2/sam 14 days. Ryan LKK Auto		21380.74 Supp 181.20 21561.94 L/S 17000/-	
				
	<div style="border: 1px solid black; padding: 5px;"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>			
			322705.18	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

FAX : 6542 6039

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19015581/DQF3N2

Date: 17/10/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01010238
Claimant Vehicle No :	SHA892S	Insured Vehicle No :	SBV707E
Date of Loss:	01/09/2019	Nature of Claim:	TP
		Claim No:	CMTD1904162

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA892S	Engine No:	D4FDFU538540
Make & Model:	HYUNDAI I40, 1.7 D (A)	Chassis No:	KMHLB41UMGU077055
Reg. Date:	13/08/2015 (Man. Year: 2015)	Odometer:	431712 km
Colour:	Yellow		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	25,355.18	18,621.94	6,733.24	26.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,950.00	2,940.00	4,010.00	57.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	32,305.18	21,561.94	10,743.24	33.26
Approved Total (Overridden) (\$\$)		17,000.00		
(\$\$)	32,305.18	17,000.00	15,305.18	47.38
+ GST 7.00/7.00% (\$\$)	2,261.36	1,190.00	1,071.36	47.38
Nett Amount (\$\$)	34,566.54	18,190.00	16,376.54	47.38

INSPECTION

Date of Assignment:	03/09/2019	
Date Inspected:	04/09/2019	Inspected At:
		Chunni Motor Work Pte Ltd - Amk (HQ)
		Blk 10 #01-05/06, AMK Autopoint
		Singapore 568047
Estimated Period of Repair:	14.0 days	

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2019)
Parts:	143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA892S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Broken	1,110.10 FL	*1,110.10 FL
2	1		*RADIATOR GRILLE H EMBLEM	Necessary	39.50 FL	*39.50 FL
3	1		*FRONT BUMPER COVER	Dented	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
5	1		*FRONT BUMPER REINFORCEMENT	Dented	402.10 FL	*402.10 FL
6	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
7	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	49.20 FL	*- FL
8	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
9	1		*HEADLAMP SUPPORT PANEL ASSY	Bent/Cracked	907.40 FL	*907.40 FL
10	2		*HEADLAMP (LH/RH)	Mounting Broken	2,776.00 FL	*2,776.00 FL
11	1		*RADIATOR	Bent	698.30 FL	*698.30 FL
12	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Housing Cracked	792.95 FL	*792.95 FL
13	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
14	2		*RADIATOR GUARD	Broken	40.00 FL	*40.00 FL
15	2		*HORN UNIT (LH/RH)	Broken	147.60 FL	*147.60 FL
16	1		*AIRCON CONDENSER	Bent	927.50 FL	*927.50 FL
17	1		*INTER COOLER	Bent	1,032.50 FL	*1,032.50 FL
18	1		*INTER COOLER MOUNTING (2 PCS)	Not Necessary	25.90 FL	*- FL
19	1		*WIRING-ECM	Not Necessary	3,243.00 FL	*- FL
20	1		*BOOT LID	Bent	2,174.90 FL	*2,174.90 FL
21	1		*BOOT LID RUBBER	Deformed	96.50 FL	*96.50 FL
22	2		*BOOT LID HINGE (LH/RH)	Not Necessary	284.60 FL	*- FL
23	1		*BOOT LID LOCK UPPER	Damaged	102.60 FL	*102.60 FL
24	1		*BOOT LID LOCK LOWER	Repair	31.70 FL	*- FL
25	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
26	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
27	2		*BOOT LID LAMP (LH/RH)	Cracked/Mounting Broken	1,131.20 FL	*1,131.20 FL
28	1		*BOOT LID TRIMBOARD	Not Necessary	116.40 FL	*- FL
29	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
30	1		*BOOTLID MOULDING	Cracked	85.00 FL	*85.00 FL
31	1		*BOOTLID I40 EMBLEM	Necessary	27.90 FL	*27.90 FL
32	1		*BOOTLID LOWER GARNISH	Cracked	227.90 FL	*227.90 FL
33	1		*REAR BUMPER	Dented	553.00 FL	*553.00 FL
34	1		*REAR BUMPER REINFORCEMENT	Bent	428.40 FL	*428.40 FL
35	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Dented	160.60 FL	*160.60 FL
36	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
37	1		*REAR BUMPER BRACKET	N/s Broken/O/s Not Necessary	71.20 FL	*35.60 FL
38	1		*REAR BUMPER SPONGE	Not fitted	118.40 FL	*- FL
39	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
40	2		*TAIL LAMP (LH/RH)	Cracked	1,395.60 FL	*1,395.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
42	1		*REAR PANEL GARNISH	Mounting Deformed	57.70 FL	*57.70 FL
43	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
44	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
45	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
46	1		*SPARE TYRE PANEL CUSHION	Not Necessary	209.05 FL	*- FL
47	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
48	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
49	2		*EXHAUST SILENCER	Dented/Bent	1,935.40 FL	*1,935.40 FL
50	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
51	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
52	1		*REAR FENDER WITH HOUSING (LH)	Dented	4,736.80 FL	*2,020.00 FL
53	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
54	1		*TAIL LAMP QUARTER PANEL (LH)	Dented	226.50 FL	*226.50 FL
55	1		*FRONT NO PLATE TRIM COVER }	Bent	30.00 FS	*45.00 FS
56	1		*FRONT NUMBER PLATE }	Bent	25.00 FS	*- FS
57	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
58	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
59	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
60	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **31,614.80** **23,200.75**
 - List Item Discount on L Items 20.00/20.00% (S\$) 6,259.62 4,578.81

Total Parts (S\$) 25,355.18 18,621.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,800.00	1,400.00
2	SPRAY PAINTING CHARGE	New	2,000.00	1,100.00
3	WIRING CHARGE	New	100.00	60.00
4	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
5	REMOVE/REFIX DASHBOARD	New	450.00	0.00
6	REMOVE/REFIX FUSE BOX	New	180.00	0.00
7	TUFF KOTE	New	100.00	40.00
8	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
9	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
10	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
11	REMOVE/REFIX EXHAUST PIPE	New	300.00	60.00
12	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
Gross Labour Cost (\$\$)			6,950.00	2,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >